LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

LKK Auto Consultants Pte Ltd From:

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

23 Dec 2022 Attn: Tan Kah Leong Date:

Preliminary Advice

Vehicle No : SKQ899D Accident Date : 22/10/2022

Make : BMW 520I Policy No.

DMPCSNW00220142200

Excess : S\$750.00 Assignment Date : 19/12/2022

Date of Inspection : 22/12/2022 Est. Duration of Repair : 3

Inspection At : PERFORMANCE MOTORS LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 4,633.15 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 2,252.00 |
| Check Items (Estimated) | :S\$ | 221.65 |
| Total | :S\$ | 2,473.65 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 226,000.00 COE / PARF Rebate :S\$ 100,786.00

Salvage Value :S\$

Margin for Repair :S\$ 125,214.00

Remarks

| (X) | The vehicle is repairable at our | adjusted amount. | We have also | confirmed exc | cess and policy | coverage. Kindly let |
|-------|----------------------------------|------------------|--------------|---------------|-----------------|----------------------|
| | us have your authorisation. | | | | | |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advise amount (Revised & Check items) stated are subject to (X) consistency check, part prices and labour cost.