

CARIS AUTOWORKS PTE LTD
160 SIN MING DRIVE
#05-03 SIN MING AUTOCITY
SINGAPORE 575722
(COMPANY REGISTRATION NO: 201825799E)
TEL: 62589831
FAX: 62585349

Not Withheld
11 Pm @ 2850h
Resurvey After Paint
4 days

ESTIMATE REPAIR COST TO MAZDA (5) REG NO : SLM 6017 C

		S\$
1 PC	BOOT (REAR) 1637	Bz 1763.00 ✓
1 PC	BOOT LOCK 256.20	Du 275.00 ✓
1 PC	BOOT HINGE	n 57.10 X
1 PC	BOOT INNER COVER	cm 516.10 ✓
1 PC	ENG PANEL TOP GARNISH	sn 187.50 X
1 PC	BUMPER 961.20	Bu 989.20 ✓
1 SET	REVERSE SENSOR	sn 368.00 X

TOTAL 4155.90
LESS 20% 831.18
TOTAL 3324.72

LABOUR & MISC CHARGES

PANEL KNOCKING

800.00 4000

SPRAY PAINTING

1000.00 4400

BODY CLIPS

nr 80.00 5000

WIRE CHECKING & DIAGNOSTIC

80.00 200

WHEEL ALIGNMENT

nr 80.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5364.72