

ASS. REC. BY:

REF:

C12/22012709/KW

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNB 4623A Yr Regn: 02, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Fortuner

C.C

2894

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

139362

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MROEX69G 8000 23260

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 0700

R: Falken

285/50R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

8

mm

L/Bal.

6 mm

L/Bal.

8

mm

D.O.A.

13/12/22

D.O.I.

20/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt O/S & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/1 21 Lm @ 9650. @7 days (Red \$3,784.15/28%)

Date/Time, File Pass to?

03/04/2023

1) Typist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair: 7

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format:

OD

Lump Sum / I.B.I: (\$

LS \$9,650.00

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 055010
Date calculated: 19/12/2022 3:21 PM

Full Report
Registration: SNB4623A
Printed: 19/12/2022 3:22 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	13/12/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	FORTUNER
Sub Model:	FORTUNER
Model Sheet Number:	70 64 02
Registration:	SNB4623A
VIN number:	GDH2011022370
Odometer:	

Model Specs

FROM 01.2013	1 PACK GLASS BONDING	HEADLAMP WASHERS	LEATHER SEAT COVER
TOW BAR	2.7 LTR 118KW	4WD	4-SPEED AUTOMATIC
4-WHEEL ALIGNMENT	PRODUCT THAILAND	TWO COAT METALLIC	PREPARE OFF VEHICLE

Not Authorized
1/1/2023
Ex @ 2000h
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle Condition


Vehicle Status

Pre-Accident Damage: [REDACTED]

Date of Inspection: [REDACTED]

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
Spare Tyre Brand	Tread (Spare), mm						

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
M031	REMOVE AND REFIT L/HALF AXLE	23.0		[REDACTED]
M031	REMOVE AND REFIT R/HALF AXLE	23.0		96.60
B150	RENEW FRONT PANEL AND R/WHEELHOUSE	43.0		180.60
B110	RENEW R/F WING	6.0		25.20
NO NUMBER	R + R L/R FRONT FOG LAMP	1.0		4.20
B040	RENEW BOTH HEADLAMPS	5.0		21.00
	INCLUDES: ADJUST HEADLAMPS			
B020	RENEW FRONT BUMPER (REMOVED)	10.0		42.00
	INCLUDES: REQUIRED ATTACHED PARTS			
	REMOVE AND REFIT			
	NOT INCLUDED: RADIATOR GRILLE R + R			
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	2.0		8.40
B030	R + R RADIATOR GRILLE	2.0		8.40
B070	RENEW BONNET	6.0		25.20
	(REMOVED)			
	INCLUDES: RENEW WASHER JET AND BONNET			
	INSULATION			
531041	R + R R/F WHEELHOUSE COVER	4.0		16.80

Code	Description	WU	Price SGD
B085	R + R BLOWER GRILLE	3.0	12.60
M170	R + R STEERING SHAFT	6.0	25.20
M230	R + R INSTRUMENT PANEL	19.0	79.80
	INCLUDES: R + R STEERING WHEEL, COMBINATION SWITCH AND CENTRE CONSOLE		
NO NUMBER	R + R INSTRUMENT PANEL CARRIER	6.0	25.20
M020	R + R RADIATOR	7.0	29.40 25.20
	INCLUDES: BLEED COOLING SYSTEM		
M200	R + R POWER STEERING RACK	14.0	58.80
420091)	R + R RIGHT FRONT WHEEL	1.0	4.20
420091)	R + R FRONT WHEEL	1.0	4.20
420091)	R + R R/F WHEEL/TYRE	3.0	12.60
NO NUMBER	R + R FRONT STABILIZER	4.0	16.80
NO NUMBER	R + R L/STABILIZER ROD	2.0	8.40
NO NUMBER	R + R R/STABILIZER ROD	2.0	8.40
430101)	DIS + ASS R/F SHOCK ABSORBER/COIL SPRING	1.0	4.20
430151)	DETACH + REFIT FRONT SHOCK ABSORBER	2.0	8.40
473101)	R + R R/F BRAKE CALIPER	1.0	4.20
370031) ZAX	DE-/ATTACH FRONT JOINT DISC	3.0	12.60
434211)	RENEW R/F STEERING KNUCKLE	17.0	71.40
	INCLUDES: R + R BRAKE DISC, WHEEL HUB, STEERING LEVER AND SPLASH SHIELD DOES NOT INCLUDE: R + R WHEEL AND BRAKE CALIPER, ALIGN AND ADJUST FRONT AXLE		
M010	RENEW CONDENSER	10.0	42.00
NO NUMBER	REFILL AIR CONDITIONING	4.0	16.80
0471	Bonnet Repair	20.0*	84.00
	Labour Cost	Hrs	WU
	Panel / Mechanical Labour	23.10	231.0
			970.20
	Total of Labour		970.20 1024.80

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	23.0	
	R/F WING NEW PART PAINTING	11.0	
	FRONT PANEL CPL SURFACE PAINT	7.0	
	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
	FRONT BUMPER NEW PART PAINT K1G	22.0	
	R/F W-ARCH MOULDING NEW PART PAINT K1G	5.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	74.82 X
0742	R/F WING NEW PART PAINTING	24.25
1009	FRONT PANEL CPL SURFACE PAINT	16.43
1118	R/F WHEELHOUSE CPL SURFACE PAINT	13.94
0281	FRONT BUMPER NEW PART PAINT K1G	73.71
0802	R/F W-ARCH MOULDING NEW PART PAINT K1G	5.10
0471	Bonnet Repair Painting <50%	46.84

Labour Cost - Paint

Factor

42.00 SGD/h

Hrs

WU

Price SGD

Time Paint

74.0

Preparation Main Work Metal

2.50

25.0

105.00

Preparation Comp. Work Plastic

0.80

8.0

33.60

Total

10 WU/h

10.70

107.0

449.40

Material Cost - Paint

New Part Painting

Price SGD

99.07 24.25

New Part Painting - Plastic K1G

78.81

Surface-/Blend Paint

30.37

Material-constant Metal Preparation

28.60

Material-constant Plastic

12.70

Total

249.55 46.84

Total

21.57

Spare Parts

prices as at 2015-06-01/01

Code	Description	Part Number	Part Source	Price SGD
0281	FRONT BUMPER	52119 0K989	Original	450.00
0338	R/F UPP BUMPER BRKT	52115 0K080	Original	70.00
0339	FRT BUMPER REINF	52021 0K022	Original	180.00
0410	GRILLE	53111 0K700	Original	280.00
0431	MANUFACTURER BADGE	75311 0K060	Original	80.00
0436	R/F WING BADGE	75473 0K011	Original	75.00
0438	R/F WING BADGE	75428 0K011	Original	90.00
0471	BONNET	53301 0K101	Original	480.00
0561	LEFT HEADLAMP ASSY	81150 0K501	Original	480.00
0562	RIGHT HEADLAMP ASSY	81110 0K501	Original	480.00
0638	R/F FOG LAMP CPL	81210 0K080	Original	160.00
0742	R/F WING	53811 0K110	Original	260.00
0802	R/F W-ARCH MOULDING	53847 0K907	Original	220.00
0842	R/W-HOUSE	53805 0K080	Original	130.00
	INSULATION			
1009	FRONT PANEL CPL	53201 0K170	Original	380.00
1118	R/F WHEELHOUSE CPL	53701 0K331	Original	380.00
4465	CONDENSER	88460 0K110	Original	450.00
7050	R/F UPPER AXLE LINK	48610 0K040	Original	280.00
7054	R/F LOWER AXLE ARM	48068 0K040	Original	260.00
7082	R/F STEERING KNUCKLE	43211 0K030	Original	350.00
7088	R/FR SHOCK ABSORBER	48510 0K580	Original	460.00
7092	R/F DAMPER STOP	48609 0K040	Original	120.00
7118	R/INN WHEEL BEARING	90080 37030	Original	110.00
7202	R/FR WHEEL	42611 0K041	Original	480.00
7261	FRONT STABILISER	48811 0K050	Original	450.00
7264	R/F STABILIZER STRUT	48820 0K030	Original	120.00
7269	L/F STABILISER BUSH	48815 0K010	Original	65.00
7270	R/F STABILISER BUSH	48815 0K010	Original	65.00
7300	STEERING GEAR	44200 0K570	Original	2,400.00
7761	RADIATOR	16400 0L190	Original	680.00
1000	R/F FEND RUBBER SEAL	RH FRONT FENDER	Original	40.00
1001	F BUMP CTR MOULDING	FRONT BUMPER	Original	95.00
1002	R/F LOWER AXLE JOINT	R/F LOWER ARM	Original	90.00
1003	R/UPPER BALL JOINT	R/F UPPER ARM	Original	120.00
1004	RH STEER TIE ROD	STEERING	Original	85.00
1011	R/F UPPER ARM BOLT	RH FRONT ARM	Supplementary	120.00

Code	Description	Part Number	Part Source	Price SGD
1005	RH STEER TIE ROD END	STEER	Original	140.00 <i>2</i>
f: OEM Parts				0.00
n: Non-OEM Parts				11,055.00
u: Used parts				100.00
Savings				
Subtotal				11,055.00
Fixed Sundry Parts Price				100.00
Total				11,155.00

Extras

Code	Description	Price SGD
1006	Electrical work Electrical work	25.00* <i>201</i>
1007	Engine coolant Engine coolant	30.00* ✓
1008	Air con coolant Air con	50.00* ✓
1009	Front number plate Number Plate	<i>mit</i> 35.00* ✓
1010	Wheel alignment Wheel alignment	60.00* ✓
Total Extras		200.00
1012	Power Steering oil Steering	<i>Ma</i> 30.00 ✓
1013	RH Front tyre	<i>Pur</i> 260.00 ✓

Final Calculation

	SGD	SGD
Parts	11,055.00	
Fixed Sundry Parts Price	100.00	
Total Parts		11,155.00
Labour Time Base 10 WU/h		
Total 231.0 WU X 42.00 SGD/h	970.20	
Total of Labour		970.20
Total Of Extras		200.00
Paint Work Time Base 10 WU/h		
Labour Cost 107.0 WU X 42.00 SGD/h	449.40	
Material Cost	249.55	
Total Paint Including Material		698.95
Repair Cost Excludes GST		13,024.15
GST (+7.0%)		911.69
Repair Cost Included GST		13,935.84

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/12/2022 16:59 (SGT)
Reported by	Driver
Date of Accident	13/12/2022 20:40 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE Changi near Anak Bukit Flyover towards Changi
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNB4623A
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Hong Guoyao Gabriel
NRIC No	SXXXX009H
Email Address	gabrielhong88@gmail.com
Mobile Phone No	(Phone) +65-91071985
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Fortuner
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2700

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00234082100

DRIVER

Name of Driver	Tan Xiao En Esther
NRIC No	SXXXX867Z
Date Of Birth	23/05/1988
Occupation	Outdoor

Date Of Driving Pass	17/10/2008
Driving experience	14 YEARS AND 2 MONTHS
Gender	Female
Mobile Number	(Phone) +65-92200260
Alt. Phone Number	-
Email Address	gabrielhong88@gmail.com
Address	434 Macpherson Road
Address complement	-
Postcode	368145
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	drizzling
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	son
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	video with workshop.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

Describe Circumstance of the Accident

I was driving back home on PIE, under speed limit
 as floor was wet and I was with my son hence
 I was driving carefully.
 Front right
 Tyre burst and I skidded and hit the
 on my right
 stone/brick wall. No other vehicles was involved
 as I was keeping a very safe distance.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
 (Name as in NRICID card)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	009H
Vehicle Details	
Vehicle No.:	SNB4623A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Dec 2022
Vehicle Make:	TOYOTA
Vehicle Model:	FORTUNER 2.7 2WD AUTO FL
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	2TR6840869
Chassis No.:	MR0ZX69G800023260
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$27,036.00
Original Registration Date:	02 Feb 2010
First Registration Date:	02 Feb 2010
Transfer Count:	3
Actual ARF Paid:	\$27,036.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Feb 2025
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$19,036.00
COE Rebate Amount:	\$8,116.00
Total Rebate Amount:	\$8,116.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 Dec 2022

OK