

GST No. 199800703G

LSK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Center

Estimation

Date :	14-Nov-22
D.O.A :	15-Dec-22
Your ref:	YQ1718X

No.	Description	Qty	Unit Price	Amount	
1	Supply one (1) no. rear Stainless steel frame / BT	1	\$ 6,500.00	\$ 6,500.00	1000
2	Supply two (2) no. rear doors panel / BA	12	\$ 1,800.00	\$ 3,600.00	1200
3	Supply one (10) no. sealant tube / MC	15	\$ 25.00	\$ 375.00	50
4	Supply one (4) no. stainless steel hinges / BT	24	\$ 290.00	\$ 1,160.00	360
5	Supply two (2) no. stainless steel recess locks c/w keys / Im X	2	\$ 320.00	\$ 640.00	X
	Supply two (2) set. Door holder (M/FM, s) / MC BA BT MC	2	\$ 90.00	\$ 180.00	50
6	Supply and install Artwork sticker (rear doors) / MC	1	\$ 1,750.00	\$ 1,750.00	800
7	To remove, refix and to renew affected parts			\$ 2,200.00	21
8	To realignment Ref Box			\$ 800.00	800

need to provide invoice

✕ Camera ?

7% gst \$ 1,204.35

Bal amount due \$ 18,409.35

LTA search \$26.75

5 ~~7~~ Days.

pat by pat.

After my air photos.

Emo Qianf
8288082

23/12/22.