

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 9221A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | DEFORMED | 894.00 | 894.00 |
| 2 | REAR BUMPER SIDE RETAINER RH/LH @\$28.00 | NOT NECESSARY | 56.00 | - |
| 1 | BOOT LID LOGO BADGE | NECESSARY | 62.00 | 62.00 |
| 1 | BOOT LID EMBLEM "MAZDA 2" | NECESSARY | 59.00 | 59.00 |
| 1 | BOOT LID EMBLEM "SKYACTIV TECHNOLOGY" | NECESSARY | 68.00 | 68.00 |
| 1 | BOOT LID (NPA) | TO REPAIR SEE LABOUR | - | - |
| 1 | END PANEL (NPA) | TO REPAIR SEE LABOUR | - | - |
| | LESS 20% DISCOUNT | | -227.80 | -216.60 |
| | | | 911.20 | 866.40 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR REVERSE SENSOR (SN) | NOT WORKING | 200.00 | 200.00 |
| 1 | REAR CAR PLATE WITH HOLDER (SN) | NOT NECESSARY | 35.00 | - |
| 1 | REAR BUMPER CLIPS (SN) | NECESSARY | 35.00 | 30.00 |
| | | | 270.00 | 230.00 |
| | LABOUR | | | |
| | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF BOOT LID AND END PANEL. | | 800.00 | 300.00 |
| | TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED. | | 800.00 | 400.00 |
| | TO REMOVE/REFIX/REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION. | | 90.00 | 30.00 |
| | TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS. | | 60.00 | 30.00 |
| | TO REMOVE AND REPLACE REAR REVERSE SENSOR. | | 100.00 | 30.00 |
| | | | 1,850.00 | 790.00 |
| | GRAND TOTAL | | 3,031.20 | 1,886.40 |

Report Ref No. CS/SMR22012713/Tny3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 1,886.40

Report Ref No. CS/SMR22012713/Tny3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ANG BRYAN TANI

Automotive Assessor / Investigator

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.