



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22012713/Tny3e2	
			Date: 18/05/2023	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SG 5959P	Veh. Inspected	SLJ 9221A
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/12/22/5021	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	20/12/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MAZDA 2	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JM6DJ2HAA01100910	Colour	GREY
	Odometer	81736 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/50 R16	FIRENZA	6 mm
	L/H Front Tyre	205/50 R16	FIRENZA	6 mm
	R/H Rear Tyre	205/50 R16	FIRENZA	6 mm
	L/H Rear Tyre	205/50 R16	FIRENZA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	15/12/2022	Inspection Date	27/01/2023
	Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	