

REC'D BY: T. J. M.

REF: CS/SUM R. 27012713/Tny3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / VS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$48K
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Turn Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLJ9221A Yr Regn: 2016 Dec
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mazda 2 C.C. 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 8736 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SUM 6052 HUAA 04100910
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205 / 50 R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO, or Pirelli

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A.	D.O.I. <u>27/1/23</u>

Survey held at Wah Hong Motors
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

Photos

Others

Report Format:

Loop Card / L.B.R. (T)



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. SLJ9221A MAZDA 2 HATCHBACK 1.5L

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Rear bumper		894.00	de
2	Rear bumper side retainer RH/LH@2*\$28		56.00	x
1	Boot lid logo badge		62.00	new
1	Boot lid emblem "Mazda 2"		59.00	new
1	Boot lid emblem "Skyactiv Technology "		68.00	new
1	Boot lid (Repair refer to labour)		0.00	Rx
1	End panel (Repair refer to labour) - photo		0.00	Rx
		Part Items Total:	1139.00	
		-20%	-227.80	
			911.20	
	<u>SPECIAL NETT ITEMS</u>			
1	Rear reverse sensor		200.00	?
1	Rear car plate with holder		35.00	x
1	Rear bumper clips		35.00	3000
		SN Items Total:	270.00	
		Total Parts	1181.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLJ9221A MAZDA 2 HATCHBACK 1.5L

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	400
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	90.00	30
4	To perform anti-rust treatment on affected areas	60.00	30
5	To remove and replace rear reverse sensor	100.00	30
Labour Total :		1850.00	
TOTAL (PARTS & LABOUR):		3031.20	

Tanpin 97445779
WP 27/1/22 C 215
p/h Reay before paint
3 days
Tanpin C 11/2/22

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	884I
Vehicle Details	
Vehicle No.:	SLJ9221A
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Dec 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	P520363603
Chassis No.:	JM6DJ2HAA01100910
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,177.00
Original Registration Date:	29 Dec 2016
First Registration Date:	29 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$8,177.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2026
PARF Rebate Amount:	\$5,723.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$20,060.00
Total Rebate Amount:	\$25,783.00

The information contained herein is correct as at 16 Dec 2022

OK