



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. **SLJ9221A MAZDA 2 HATCHBACK 1.5L**

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear bumper		894.00	de ✓
2	Rear bumper side retainer RH/LH@2*\$28		56.00	x n ✓
1	Boot lid logo badge		62.00	nr ✓
1	Boot lid emblem "Mazda 2"		59.00	nr ✓
1	Boot lid emblem "Skyactiv Technology "		68.00	nr ✓
1	Boot lid (Repair refer to labour)		0.00	Rp ✓
1	End panel (Repair refer to labour) - plastic		0.00	Rv ✓
Part Items Total:			1083	
			23% - 866.40	
			1139.00	
			-20% -227.80	
			911.20	
<u>SPECIAL NETT ITEMS</u>				
1	Rear reverse sensor		200.00	Rnw ✓
1	Rear car plate with holder		35.00	x n ✓
1	Rear bumper clips		35.00	3aw ✓
SN Items Total:			270.00	230
Total Parts			1181.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLJ9221A MAZDA 2 HATCHBACK 1.5L

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	400
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	90.00	30
4	To perform anti-rust treatment on affected areas	60.00	30
5	To remove and replace rear reverse sensor	100.00	30
			790
	Labour Total :	1850.00	
	TOTAL (PARTS & LABOUR):	3031.20	

Tanflin 97445779

WP' 27/1/22 0715

p/h Resny before paint

3 days

Tanflin @ Pte auto.com

866.40

250

790

\$1886.40

3 days

#