

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EGI22012714/UVY3E2**Date:** 14/03/2023REFERENCE

Insured/Claimant:	ZULRAIMI BIN OSMAN	Policy No:	DMPG22012760	
Date of Loss:	09/12/2022	Nature of Claim:	OD	Claim No: CDMPG22002657

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV7090J		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	2ZR0444424
Reg. Date:	05/02/2010 (Man. Year: 2009)	Chassis No:	ZGE200016221
Colour:	White	Odometer:	181415 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Papiae 6 mm	Rear Left Side:	Kenda 6 mm
Front Right Side:	Papiae 6 mm	Rear Right Side:	Kenda 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
Nett Amount (S\$)	-1,400.00	-1,400.00	0.00	0.00

INSPECTION

Date of Assignment:	03/01/2023		
Date Inspected:	21/12/2022	Inspected At:	Blk 14 Defu Lane 10 #01-412 Singapore 539195 Repairer: SME Motor Pte Ltd
Estimated Period of Repair:	21.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV7090J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >