

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/1141/2022/EQ  
**DATE** : 21-Dec-22  
**WIP** : 55636

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/12/2022**

**YOUR INSURED VEH NO : SJS 3879 T**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MR YONG TECK YEOW DESMOND  
**ADDRESS** : 13 EASTWOOD WALK  
SINGAPORE 486465

**TELEPHONE** : HP +65 90605855  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 5116884920  
**VEHICLE NO** : **SKQ 903 A**  
**MODEL CODE** : AUDI A4 SEDAN 1.4 TFSI S  
**MODEL YEAR** : 31/3/2017  
**ENGINE NO** : CVN 032593  
**CHASSIS NO** : WAUZZZF40HA121142  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 16-Dec-22  
**PLACE OF ACCIDENT** : TAMPINES AVE 5

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKQ 903 A**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	
3	TO RESPRAY REAR BUMPER.	\$	900.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 2,502.00</b>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 903 A**

			<b>DAMAGED PARTS &amp; PRICES</b>	
<b>S/N</b>	<b>PARTS DESCRIPTION</b>	<b>QTY</b>	<b>S/NETT</b>	<b>REMARKS</b>
1	REAR BUMPER	1	\$ 2,609.00	
2	REAR BUMPER FIXING PARTS	1	\$ 480.00	
3	REAR BUMPER SECURING STRIP	1	\$ 249.00	
4	REAR BUMPER SPOILER	1	\$ 276.00	
5	REAR BUMPER REFLECTOR - LH / RH	2	\$ 92.00	
6	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00	
7	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 32.00	
8	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 52.00	
9	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	
10	REAR PARKING AID SEAL RING	4	\$ 10.00	
11	SUNDRIES		\$ 300.00	
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 5,762.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 2,502.00</b>	
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 8,264.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT