3/15/23, 10:34 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI22012719/UQP3Q2
3 Anson Road, #16-00 Springleaf Tower

Singapore 079909 **Date:** 15/03/2023

REFERENCE

Insured/Claimant: CHAN YEE MAN Policy No: DMPCSNW00139542201

Date of Loss: 05/11/2022 Nature of Claim: OD Claim No: SNM22D207984/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJM4045H

Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FC8U568060

Reg. Date: 31/12/2008 (Man. Year: 2008) Chassis No: KMHDU41BR9U650329

Colour: Red Odometer: 178059 km

Engine Capacity: 1591 cc

Market Value/New Car

Price:

ew Car S\$46,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R17 Rear Tyre Size: 205/45 R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,675.00	840.00	835.00	49.85
Miscellaneous Items	200.00	325.00	-125.00	-62.50
Labour	939.66	337.26	602.40	64.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,814.66	1,502.26	1,312.40	46.63
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,814.66	1,300.00	1,514.66	53.81
+ GST 7.00/8.00% (S\$)	197.03	104.00	93.03	47.22
Nett Amount (S\$)	3,011.69	1,404.00	1,607.69	53.38

INSPECTION

Date Inspected:

Date of Assignment: 20/12/2022 Present Location: Car City Auto Centre Pte Ltd (HQ)

Inspected At:

Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

16/02/2023

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2023)

Parts: 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJM4045H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 F=Franchise part.	*PARTS		1,675.00 F	*840.00 F
1 – Franchise part.		Total Parts (S\$)	1,675.00	840.00
	Repor	t was unsubmitted during this print-out.		

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 EXTRA		200.00	325.00
	Sub Total (S\$)	200.00	325.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	478.80	67.20
2	SPRAY PAINTING	New	460.86	270.06
		Gross Labour Cost (S\$)	939.66	337.26
	Rep	ort was unsubmitted during this print-out.		

< END OF ESTIMATES >