

GBC5290G. 2012 Nov

TP ECICS.

Toyota Dyna. 2982cc

Veron.

JTFAT35Y10K202112

Rees Number Plate.	Bent	30(SN) ✓
Rees Number Plate Holder.	Dehd	30(SN) ✓
Rees Number Plate Lamp.	Not ver	68.70 ✓ x
Rees Number Plate Bracket.	Bent	160.40 ✓
Rees Step Panel.	Bent	300(SN) 200(SN)
Reverse Sensor	Damaged	280(SN) 200(SN)
Taillamp x 02.	Crackd	245.4 x 2 = 490.80 ✓
Taillamp Panel x 02	RH Bent	185.5 x 2 = 371 ✓ 185.50
Stopper x 02	wt RH	20 x 2 = 40(SN) ✓ 20(SN)
Stopper Bracket x 02	RH Bent	110.5 x 2 = 221 ✓ 110.50
Tailgate	Dented	1582.60 ✓
Tailgate Side Lock x 02	RH Damaged	220.7 x 2 = 441.40 ✓ 220.70

GBC 5290G.

Tailgate Hinge x 04.	HP new	$64.4 \times 4 = 257.60$	X
Tailgate Lower Member	Repit	495.40.	X
Toyota Sticker	Nec	155.10.	✓
AR Sticker		30(SN)	✓
70km/h Sticker.		10(SN)	✓
Spare Tyre Lock Chain.	HP new	385.90.	X

2905.60

2179.20

S-N: 520

GBC52906.

Panel Beating.

Spray Painting.

Wiring.

To apply tuff coat.

~~800~~ 500.

~~800~~ 600

~~50~~ 30

~~150~~ 60.

1190

total: 3889.20

L/S: 3.11K.

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: