

CC3/AIG00012735/Rvy3 21,750/7 days -ok

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/1132/2022/EQ  
DATE : 17-Dec-22  
WIP : 55221

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/12/2022**

## **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

OWNER'S NAME : MR THIA CHEE CHEW  
ADDRESS : 9 ELIAS GREEN  
#08-01  
SINGAPORE 519963  
TELEPHONE : HP +65 81980001  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7210079662  
VEHICLE NO : SJA 1180 H  
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC  
MODEL YEAR : 28/7/2021  
ENGINE NO : DEM 028557  
CHASSIS NO : WAUZZZF45MN005986  
MILEAGE : 17,387  
DATE IN : 16-Dec-22  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 16-Dec-22  
PLACE OF ACCIDENT : OUTSIDE THE ENTRANCE OF ELIAS GREEN CONDO -  
ELIAS GREEN ROAD

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJA 1180 H

| S/N                         | NATURE OF JOBS                                                                                                                                   |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ | 480.00 / ✓           |                               |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                            | S/N \$ | 350.00 / ✓           |                               |
| 3                           | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.             | S/N \$ | 1,400.00 ? x n1      |                               |
| 4                           | TO CARRY OUT VACUUM AND REGAS FOR R1234.                                                                                                         | S/N \$ | 1,200.00 ? x n1      |                               |
| 5                           | TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.         | S/N \$ | 280.00 / ✓           |                               |
| 6                           | TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY.                                                                                             | S/N \$ | 2,800.00 ? x n1      |                               |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                  | : \$   | <b>6,510.00</b>      |                               |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJA 1180 H**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                                                                               | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 7                           | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER, AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | @500x3<br>\$ 7,000.00 | 1500 ✓                     |
| 8                           | TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR, DOOR HANDLE, RHS REAR DOOR AND RHS FRONT FENDER TOP SUPPORT.                                                                                                                              | @550<br>\$ 5,000.00   | 2750 ✓                     |
| 9                           | TO RENEW RHS FRONT RIM WITH TYRE AND LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.                                                                                                                                                         | S/N \$ 560.00         | ✓                          |
| 10                          | TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.                                                                                                                                                                                                                 | S/N \$ 280.00         | X <sup>an</sup>            |
| 11                          | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.                                                                                                                                                                                                                      | S/N \$ 384.00         | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                                              | <b>: \$ 19,734.00</b> |                            |

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 1180 H

| S/N                   | PARTS DESCRIPTION                                                   | QTY | DAMAGED PARTS & PRICES |          | REMARKS |
|-----------------------|---------------------------------------------------------------------|-----|------------------------|----------|---------|
|                       |                                                                     |     | S/NETT                 |          |         |
| 1                     | FRONT BUMPER <i>de /</i>                                            | 1   | \$                     | 2,377.00 | 1901.60 |
| 2                     | FRONT BUMPER FIXING PARTS <i>X<sup>nn</sup></i>                     | 1   | \$                     | 393.00   |         |
| 3                     | FRONT BUMPER SECURING STRIP - LH / RH <i>? X<sup>nn</sup></i>       | 1   | \$                     | 79.00    |         |
| 4                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>? X<sup>nn</sup></i> | 1   | \$                     | 293.00   |         |
| 5                     | FRONT BUMPER AIR GUIDE - RH <i>? de /</i>                           | 1   | \$                     | 51.00    | 40.08   |
| 6                     | FRONT BUMPER AIR GUIDE GRILLE - RH <i>spa /</i>                     | 1   | \$                     | 151.00   | 120.40  |
| 7                     | FRONT BUMPER OUTER GRILLE HOLE COVER - RH <i>? X<sup>nn</sup></i>   | 1   | \$                     | 54.00    |         |
| 8                     | FRONT BUMPER GUIDE SECTION - RH <i>? nm /</i>                       | 1   | \$                     | 41.00    | 30.24   |
| 9                     | FRONT BUMPER TOP COVER <i>X<sup>nn</sup></i>                        | 1   | \$                     | 143.00   |         |
| 10                    | CAUTION SIGN STICKER <i>X<sup>nn</sup></i>                          | 1   | \$                     | 16.00    |         |
| 11                    | AIR CONDITIONER STICKER <i>X<sup>nn</sup></i>                       | 1   | \$                     | 9.00     |         |
| 12                    | FRONT BUMPER BRACKET <i>X<sup>nn</sup></i>                          | 1   | \$                     | 154.00   |         |
| 13                    | FRONT BUMPER SUPPORT - LH <i>(RH) ? X<sup>nn</sup></i>              | 1   | \$                     | 64.00    |         |
| 14                    | FRONT PARKING AID SENSOR - OUTER <i>X<sup>nn</sup></i>              | 1   | \$                     | 266.00   |         |
| 15                    | FRONT PARKING AID SEAL RING <i>X<sup>nn</sup></i>                   | 4   | \$                     | 10.00    |         |
| 16                    | HORN LOW TONE - RH <i>X<sup>nn</sup></i>                            | 1   | \$                     | 139.00   |         |
| 17                    | HORN BRACKET - RH <i>X<sup>nn</sup></i>                             | 1   | \$                     | 33.00    |         |
| 18                    | FRONT FENDER - RH <i>bu /</i>                                       | 1   | \$                     | 1,227.00 | 981.60  |
| 19                    | FRONT FENDER ATTACHMENT PARTS <i>X<sup>nn</sup></i>                 | 1   | \$                     | 225.00   |         |
| 20                    | FRONT FENDER CLOSING ELEMENT - RH <i>X<sup>nn</sup> nm /</i>        | 1   | \$                     | 81.00    | 64.24   |
| SUB TOTAL SPARE PARTS |                                                                     | :   | \$                     | 5,806.00 |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 1180 H

| S/N                   | PARTS DESCRIPTION                                             | QTY | DAMAGED PARTS & PRICES |         |
|-----------------------|---------------------------------------------------------------|-----|------------------------|---------|
|                       |                                                               |     | S/NETT                 | REMARKS |
| 21                    | FRONT FENDER BRACKET - RH ? ✓ <i>new</i>                      | 1   | \$ 41.00               | 32.72   |
| 22                    | FRONT FENDER DEFORMATION ELEMENT BRACKET - RH ? X <i>nn</i>   | 1   | \$ 55.00               |         |
| 23                    | FRONT FENDER RIVET <i>new</i>                                 | 7   | \$ 27.00               | 21.28   |
| 24                    | FRONT FENDER BRACKET - RH ? X <i>nn</i>                       | 1   | \$ 36.00               |         |
| 25                    | FRONT WHEEL HOUSING LINER - RH <i>de</i>                      | 1   | \$ 262.00              | 209.60  |
| 26                    | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS X <i>nn</i>        | 1   | \$ 149.00              |         |
| 27                    | FRONT WHEEL SPOILER <i>cm</i>                                 | 1   | \$ 82.00               | 65.12   |
| 28                    | FRONT WHEEL SPOILER END PLATE - RH ? X <i>nn</i>              | 1   | \$ 40.00               |         |
| 29                    | FRONT FENDER LEDGE COVER - RH LONG <i>side</i> ? ✓ <i>new</i> | 1   | \$ 35.00               | 27.52   |
| 30                    | HEADLIGHT COVER - RH <i>cut</i>                               | 1   | \$ 49.00               | 38.64   |
| 31                    | BONNET <i>lt</i>                                              | 1   | \$ 3,425.00            | 2740    |
| 32                    | BONNET ATTACHMENT PARTS X <i>nn</i>                           | 1   | \$ 431.00              |         |
| 33                    | BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i>        | 3   | \$ 93.00               | 73.20   |
| 34                    | FRONT FENDER LEDGE COVER - RH UPPER ? X <i>nn</i>             | 1   | \$ 68.00               |         |
| 35                    | BONNET STRIKER - RH X <i>nn</i>                               | 1   | \$ 56.00               |         |
| 36                    | BONNET LOCK X <i>nn</i>                                       | 1   | \$ 228.00              |         |
| 37                    | FRONT PLENUM CHAMBER COVER X <i>nn</i>                        | 1   | \$ 108.00              |         |
| 38                    | HEADLIGHT - RH <i>bro</i>                                     | 1   | \$ 8,172.00            | 6537.60 |
| 39                    | HEADLIGHT HOSE X <i>nn</i>                                    | 1   | \$ 42.00               |         |
| 40                    | HEADLIGHT COMPENSATING PIECE ? X <i>nn</i>                    | 1   | \$ 45.00               |         |
| SUB TOTAL SPARE PARTS |                                                               | :   | \$ 13,444.00           |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 1180 H

|                       |                                         |     | DAMAGED PARTS & PRICES |         |
|-----------------------|-----------------------------------------|-----|------------------------|---------|
| S/N                   | PARTS DESCRIPTION                       | QTY | S/NETT                 | REMARKS |
| 41                    | HEADLIGHT COMPENSATING PIECE ? X n      | 1   | \$ 45.00               |         |
| 42                    | HEADLIGHT COMPENSATING PIECE ? X n      | 1   | \$ 47.00               |         |
| 43                    | LIFT CYLINDER - RH X n                  | 1   | \$ 231.00              |         |
| 44                    | LIFT CYLINDER BRACKET X n ✓             | 1   | \$ 7.00                | 5.44    |
| 45                    | LIFT CYLINDER CORRUGATED PIPE X n       | 1   | \$ 107.00              |         |
| 46                    | LIFT CYLINDER CORRUGATED PIPE X n ✓     | 1   | \$ 53.00               | 42      |
| 47                    | LIFT CYLINDER WASH WATER RESERVOIR X n  | 1   | \$ 160.00              |         |
| 48                    | LOCK CARRIER ? X n                      | 1   | \$ 1,478.00            |         |
| 49                    | READY-MIX COOLANT ? X n                 | 6   | \$ 297.00              |         |
| 50                    | RADIATOR AIR GUIDE - RH INNER ? X n     | 1   | \$ 51.00               |         |
| 51                    | RADIATOR AIR GUIDE - RH OUTER X n       | 1   | \$ 19.00               |         |
| 52                    | RADIATOR AIR GUIDE - LOWER / UPPER X n  | 2   | \$ 44.00               |         |
| 53                    | AIR FILTER X n ✓                        | 1   | \$ 418.00              | 334.40  |
| 54                    | INTAKE AIR DUCT - RH X n                | 1   | \$ 25.00               |         |
| 55                    | ENGINE AIR INTAKE HOSE - CENTER X n     | 1   | \$ 61.00               |         |
| 56                    | FRONT FENDER BRACE - RH ? ✓             | 1   | \$ 132.00              | 105.20  |
| 57                    | FRONT ALUMINIUM RIM - LH / RH sm ✓      | ②   | \$ 2,584.00            | 2067.20 |
| 58                    | FRONT ALUMINIUM RIM RUBBER VALVE ? ✓    | 2   | \$ 8.00                | 5.92    |
| 59                    | FRONT WISHBONE LINK - RH LOWER ? X n    | 1   | \$ 605.00              |         |
| 60                    | FRONT SUSPENSION GUIDE - RH LOWER ? X n | 1   | \$ 1,057.00            |         |
| SUB TOTAL SPARE PARTS |                                         | :   | \$ 7,429.00            |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES

55, UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJA 1180 H

| S/N                         | PARTS DESCRIPTION                          | DAMAGED PARTS & PRICES |        |                  | REMARKS |
|-----------------------------|--------------------------------------------|------------------------|--------|------------------|---------|
|                             |                                            | QTY                    | S/NETT |                  |         |
| 61                          | FRONT SUSPENSION GUIDE - RH UPPER ?        | 1                      | \$     | 575.00           |         |
| 62                          | FRONT SUSPENSION GUIDE - RH UPPER ?        | 1                      | \$     | 575.00           |         |
| 63                          | FRONT WHEEL BEARING HOUSING - RH ?         | 1                      | \$     | 1,070.00         |         |
| 64                          | FRONT WHEEL BEARING HOUSING SWIVEL JOINT ? | 1                      | \$     | 214.00           |         |
| 65                          | FRONT WHEEL HUB ?                          | 1                      | \$     | 499.00           |         |
| 66                          | FRONT DOUBLE ANGLED BALL BEARING FLANGE ?  | 1                      | \$     | 273.00           |         |
| 67                          | SUSPENSION FORKS - RH ?                    | 1                      | \$     | 293.00           |         |
| 68                          | COUPLING ROD ?                             | 1                      | \$     | 129.00           |         |
| 69                          | GAS SHOCK ABSORBER ?                       | 1                      | \$     | 332.00           |         |
| 70                          | TRACK ROD ?                                | 1                      | \$     | 109.00           |         |
| 71                          | TIE ROD END ?                              | 1                      | \$     | 217.00           |         |
| 72                          | LOCK CARRIER CONNECTING PLATE - RH ?       | 1                      | \$     | 241.00           |         |
| 73                          | LOCK CARRIER CONNECTING PLATE - RH ?       | 1                      | \$     | 279.00           |         |
| 74                          | ACRYLIC SEALANT ?                          | S/N                    | \$     | 180.00           |         |
| 75                          | CAVITY WAX ?                               | S/N                    | \$     | 140.00           |         |
| 76                          | STONE CHIP ?                               | S/N                    | \$     | 180.00           |         |
| 77                          | METAL FILLER POWDER ?                      | S/N                    | \$     | 280.00           |         |
| 78                          | LHS FRONT TYRE ?                           | S/N                    |        | TBC              |         |
| 79                          | RHS FRONT TYRE ?                           | S/N                    |        | TBC              |         |
| 80                          | SUNDRIES ?                                 |                        | \$     | 1,000.00         |         |
| <b>TOTAL SPARE PARTS</b>    |                                            | :                      | \$     | <b>33,265.00</b> |         |
| <b>TOTAL LABOUR CHARGES</b> |                                            | :                      | \$     | <b>19,734.00</b> |         |
| <b>GRAND TOTAL</b>          |                                            | :                      | \$     | <b>52,999.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasul - Hp 90010068  
: 15/12/22 @ 1700  
: 7 days  
: EXCESS: THA  
: Repair  
: Resurvey before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT