

ASS. REC. BY:

REF:

Kenneth

C12
1
ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$)

: Prell. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

: F. m. s

: Others

TOTAL

Veh No:

SUB 8824K

Yr Regn:

08, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Wagen

Honda

M. Grey

134863

JHMRC 1890 GC 206956

Good / Fair / Poor / Burnt

Inorder / Jammed / Leaked / Burnt or

Inorder / Jammed / Leaked / Burnt or

Nil / S/Rim / STD / Rim or

215/55R17

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Wagen

Honda

M. Grey

134863

JHMRC 1890 GC 206956

Good / Fair / Poor / Burnt

Inorder / Jammed / Leaked / Burnt or

Inorder / Jammed / Leaked / Burnt or

Nil / S/Rim / STD / Rim or

215/55R17

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

AUTOLUTION
CARTIMES
 CarTimes Autolution Pte Ltd
 160 Sin Ming Drive AutoCity
 #02-04 Singapore 575722
 Tel : 6471 5111
 Email : claims@cartimes.com.sg

Not Authorized
 LI Pong &
 Re Pong After Paint

VEHICLE NO: SNB8824K

MODEL: HONDA ODYSSEY 2.4

CHASSIS NO: JHMRC1890GC206956

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>		
TAILGATE		Bz \$ 1,540.00 ✓
TAILGATE INNER TRIM		Bz \$ 380.00 ✓
TAILGATE LOCK ASSY		\$ Du 395.00 ✓
HONDA EMBLEM		\$ M 65.00 ✓
ODYSSEY EMBLEM		\$ M 395.00 ✓
WIPER MOTOR		\$? 350.00 ✓
TAILGATE CHROME GARNISH		Woy \$ 250.00 ✓
TAILGATE LAMP LHS		\$ Bz 430.00 ✓
TAILGATE LAMP RHS		\$ Bz 430.00 ✓
TAIL LAMP LHS		\$ Sn 840.00 X
TAIL LAMP RHS		\$ Sn 840.00 X
REAR BUMPER		\$ Bz 680.00 ✓
REAR BUMPER RETAINER LHS		\$ Sn 65.00 X
REAR BUMPER RETAINER RHS		\$ Sn 65.00 X
REAR BUMPER REFLECTOR LHS		\$ CM 60.00 ✓
REAR BUMPER REFLECTOR CHROME LHS		\$ Du 320.00 ✓
REAR BUMPER REFLECTOR RHS		\$ Sn 60.00 X
REAR BUMPER REFLECTOR CHROME RHS		\$ Sn 320.00 X
REAR BUMPER CORNER COVER LHS		\$ 100.00 ?
REAR BUMPER CORNER COVER RHS		\$ Sn 100.00 X
REAR BUMPER UNDER COVER		\$ 390.00 ?
END PANEL - INNER		\$ 590.00 ?
END PANEL - OUTER		\$ Bz 460.00 ✓
END PANEL TOP GARNISH		\$ DIT 110.00 ✓
TAILGATE WEATHERSTRIP		Dis/Du 120.00 Solu
SPARE TYRE PANEL		\$ 580.00 ?

SPARE TYRE PANEL TOP COVER
 SMART BUZZER
 KEY ANTENNA
 REAR WINDSCREEN MOULDING
 REAR FENDER INNER TRIM RHS
 REAR FENDER INNER TRIM LHS
 REAR TAILGATE SIDE ABSORBER RHS
 REAR TAILGATE SIDE ABSORBER LHS

\$ 7 295.00
 \$ 7 80.00
 \$ 7 100.00
Mr \$ 220.00 ✓
Mr D17 \$ 620.00 ✓
 \$ 620.00 ✓
 \$ *Sm* 420.00 X
 \$ *Sm* 420.00 X

FRONT BUMPER
 FRONT BUMPER SIDE RETAINER RHS
 FRONT BUMPER SIDE RETAINER LHS
 FRONT GRILLE ASSY
 FRONT GRILLE EMBLEM "H"
 FRONT GRILLE CAMERA
 FRONT REINFORCEMENT
 FRONT BUMPER SPONGE
 FRONT HEADLAMP RHS
 FRONT HEADLAMP LOWER BRACKET RHS
 FRONT HEADLAMP LHS
 FRONT HEADLAMP LOWER BRACKET LHS
 FRONT SUPPORT PANEL
 FRONT SUPPORT PANEL TOP GARNISH
 FRONT AIRCON CONDENSOR
 FRONT RADIATOR ASSY

Bu \$ 750.00 ✓
 \$ 65.00 7
 \$ 65.00 7
 \$ *cm* 895.00 ✓
 \$ *Mr* 45.00 ✓
 \$ 395.00 7
 \$ 420.00 7
 \$ 150.00 7
 7 \$ 3,220.00
Sm \$ 50.00 X
 ? \$ 3,220.00
Sm \$ 50.00 X
Mr \$ 550.00 X
Mr \$ 120.00 X
 \$ 920.00 ?
Sm \$ 720.00 X

20%	\$ 24,345.00
	\$ 4,869.00
	\$ 19,476.00

SPECIAL NETT ITEMS

REAR BUMPER CLIPS
 REAR SENSORS X 2
 WINDSCREEN SEALANT
 REAR FENDER INNER TRIM CLIPS
 REAR TAILGATE INNER TRIM CLIPS
 REAR BUMPER UNDER COVER CLIPS

\$ *Mr* 60.00 ✓
 \$ *Mr* 400.00 ✓
 \$ *Mr* 40.00 ✓
 \$ *Mr* 60.00 ✓
 \$ *Mr* 60.00 ✓
 \$ 60.00 ?

REAR TAIL LAMP CLIPS		\$ <i>nn</i> 60.00	X
FRONT BUMPER CLIPS		\$ <i>nn</i> 60.00	✓
FRONT SUPPORT PANEL TOP GARNISH CLIPS		\$ <i>nn</i> 60.00	X
	Total	\$ 860.00	
	TOTAL PARTS	\$ 20,336.00	

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ ¹¹⁰⁰ 2,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ ¹²⁰⁰ 2,000.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ ⁴⁰⁰ 200.00
4	To provide anti-rust treatment on affected areas	\$ ⁶⁰⁰ 150.00
5	Remove & refit front and rear sensor	\$ ⁸⁰⁰ 200.00
6	Dignostic Check	\$? 100.00
7	Remove & refit rear upholstery	\$ ¹⁰⁰⁰ 200.00
8	To remove and re-fix rear windscreen glass	\$ ¹²⁰⁰ 200.00
9	To remove and re-fix rear upholstery assy and rear inner trim boards	\$ X 200.00
10	To remove and transfer rear tailgate assy and lock mechanism	\$ ⁶⁰⁰ 100.00
11	To remove and re-fix front aircon condenser and re-fill gas	\$? 200.00
12	To remove and re-fix front radiator and re-fill coolant	\$ [~] X 200.00
	Labour Total :	\$ 5,750.00
	TOTAL (PARTS & LABOUR):	\$ 26,086.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/12/2022 11:42 (SGT)
Reported by	Driver
Date of Accident	17/12/2022 07:58 (SGT)
Exact Location of Accident	Buangkok E Dr, Singapore
Additional Location Information	Buangkok East Drive Junction
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNB8824K
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Nurhazidah Binte Mian
NRIC No	S8241931D
Email Address	theharisfamily@gmail.com
Mobile Phone No	(Phone) +65-85885808
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Odyssey
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2356

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5125103867

DRIVER

Name of Driver	Haris Pewiro Bin Gunadi
NRIC No	S7912429Z
Date Of Birth	08/05/1979
Occupation	Indoor

I, the undersigned, hereby consent under the Personal Data Protection Act (PDPA),

to understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIAS") may be considered a collector, data controller and/or processor of my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyer/slaw firms, the Ministry, Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the making of correspondence, statements, invoices, receipts or notices to me which could involve disclosure of certain personal data about me or bring about delivery of the claims as well as on the personal cover of my/our/our vehicles); and/or

(v) complying with applicable laws concerning processing, handling and/or dealing with my claims.

I, as insured, who have insured my vehicle in the relevant insurance policy, hereby consent to the Insurers' lawyer/slaw firms, the Ministry, Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) my Personal Information may be disclosed by any of the Insurers and/or GIAS to my insurer, my workshop, my lawyer/slaw firm, my relevant government agency/authority (such as the police), which may be used outside of Singapore for one or more of the above purposes.

HAZ 17/12/22

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witness by Reporting Centre Personnel
(Name as in NRIC card)

Sketch Plan

Sketch Plan									
Diagram showing vehicle positions and directions. Includes labels A, B, C, D, E, F, G, H, I, J, K, L, M, N, O, P, Q, R, S, T, U, V, W, X, Y, Z.									
Witness by Reporting Centre Personnel									
Name as in NRIC card									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	931D

Vehicle Details

Vehicle No.:	SNB8824K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Dec 2022
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	K24W72013020
Chassis No.:	JHMRC1890GC206956
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$32,373.00
Original Registration Date:	30 Aug 2016
First Registration Date:	30 Aug 2016
Transfer Count:	1
Actual ARF Paid:	\$37,323.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2026
PARF Rebate Amount:	\$24,259.00

Intended COE Rebate Details

COE Expiry Date:	29 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$20,853.00
Total Rebate Amount:	\$45,112.00

The information contained herein is correct as at 20 Dec 2022

OK