

ASS. REC. BY:

REF:

AIS/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

DD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

JTC 7938P

Yr Regn:

02, 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Fluence

C.C.

1961

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

222441

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF126LFO E 53997615

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6 mm

R/Bal.

5 mm

L/Bal.

6 mm

L/Bal.

5 mm

D.O.A.

6/12/22

D.O.A.

21/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1. Recommend TIL

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	854D

Vehicle Details

Vehicle No.:	SJC7938P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Dec 2022
Vehicle Make:	RENAULT
Vehicle Model:	FLUENCE 1.5 DCI 110 A/T SR
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	K9KN837D213511
Chassis No.:	VF1LZLFOE53997615
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$19,750.00
Original Registration Date:	19 Feb 2016
First Registration Date:	19 Feb 2016
Transfer Count:	1
Actual ARF Paid:	\$9,750.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Feb 2026
PARF Rebate Amount:	\$6,337.00

Intended COE Rebate Details

COE Expiry Date:	18 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$14,696.00
Total Rebate Amount:	\$21,033.00

The information contained herein is correct as at 20 Dec 2022

OK

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001935747	Date of Loss:	06/12/2022
Vehicle Reg. No.:	SJC7938P	Driveable?	
Driver Age/Info:	54 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	UNIVERSE LEASING PTE LTD		
Driver:	LEE SIOW HUA		
Make/Model:	RENAULT FLUENCE, 1.5 D DCI 110 (A)	Vehicle Reg. Date:	19/02/2016
Vehicle Colour:	Brown/Grey	Chassis No:	VF1LZLF0E53997615
Engine No:	K9KN837D213511		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14 10 days		
Present Location:	DING AUTO PTE LTD (HQ)		

*Not Authored
L/Rp &
Heavy After Paint
at 82000h*

COST OF CLAIMS	Amount
Parts	53,817.50
Miscellaneous Items	800.00
Labour	4,770.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	59,387.50
+ GST 7.00% (S\$)	4,157.13
Nett Amount (S\$)	63,544.63

This claim is handled by: YAP WEI LIN

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG

Parts: 143

Labour: Repairer's

Print Code:

Validity:

Further Info:

Version: 1.0 (Last Synchronised: 20 Dec 2022)

RENAULT FLUENCE 1.5 D DCI 110 (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List)

Ding Auto Pte Ltd/SJC7938P/20/12/2022 17:50

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	R ₁	0.00	0.00	*1,850.00 F ✓
2	1		*FRONT BUMPER BRACKET RH	R ₁	0.00	0.00	*120.00 F ✓
3	1		*FRONT BUMPER BRACKET LH	R ₁	0.00	0.00	*120.00 F ✓
4	1		*FRONT CTR BUMPER BRACKET	CM ₁	0.00	0.00	*85.00 F ✓
5	1		*FRONT BUMPER TOWING CAP	R ₁	0.00	0.00	*60.00 F X
6	1		*FRONT BUMPER MOULDING RH	CM ₁	0.00	0.00	*300.00 F ✓
7	1		*FRONT BUMPER MOULDING LH	CM ₁	0.00	0.00	*300.00 F ✓
8	1		*FRONT BUMPER CTR MOULDING	CM ₁	0.00	0.00	*180.00 F ✓
9	1		*FRONT BUMPER IMPACT FOAM	CM ₁	0.00	0.00	*160.00 F ✓
10	1		*FRONT BUMPER LOWER SPOILER	DI ₁	0.00	0.00	*250.00 F ✓
11	1		*FRONT BUMPER GRILLE	CM ₁	0.00	0.00	*450.00 F ✓
12	1		*FRONT CTR GRILLE	CM ₁	0.00	0.00	*600.00 F ✓
13	1		*FRONT SUPPORT PANEL COMPLETE	R ₁	0.00	0.00	*1,200.00 F ✓
14	1		*GRILLE BADGE	CM ₁	0.00	0.00	*120.00 F ✓
15	1		*BONNET	BU ₁	0.00	0.00	*1,050.00 F ✓
16	1		*BONNET HINGE RH	DI ₁	0.00	0.00	*380.00 F ✓
17	1		*BONNET HINGE LH	DI ₁	0.00	0.00	*380.00 F ✓
18	1		*BONNET LOCK	R ₁	0.00	0.00	*320.00 F ✓
19	1		*BONNET INSULATOR		0.00	0.00	*280.00 F ?
20	1		*FRONT FENDER RH	R ₁	0.00	0.00	*580.00 F ✓
21	1		*FRONT FENDER LH	R ₁	0.00	0.00	*580.00 F ✓
22	1		*FRONT FENDER INNER COVER RH		0.00	0.00	*285.00 F ?
23	1		*FRONT FENDER INNER COVER LH	R ₁	0.00	0.00	*285.00 F X
24	1		*HEADLAMP ASSY RH	BU ₁	0.00	0.00	*2,250.00 F ✓
25	1		*HEADLAMP ASSY LH	BU ₁	0.00	0.00	*2,250.00 F ✓
26	1		*FOG LAMP ASSY RH		0.00	0.00	*720.00 F ?
27	1		*FOG LAMP ASSY LH		0.00	0.00	*720.00 F ?
28	1		*FOG LAMP COVER RH	CM ₁	0.00	0.00	*300.00 F ✓
29	1		*FOG LAMP COVER LH	CM ₁	0.00	0.00	*300.00 F ✓
30	1		*DAY LAMP ASSY RH	MI ₁	0.00	0.00	*340.00 F ✓
31	1		*DAY LAMP ASSY LH	CM ₁	0.00	0.00	*340.00 F ✓
32	1		*RADIATOR ASSY	R ₁	0.00	0.00	*800.00 F ✓
33	1		*RADIATOR AIR GUIDE RH	CM ₁	0.00	0.00	*120.00 F ✓
34	1		*RADIATOR AIR GUIDE LH	CM ₁	0.00	0.00	*120.00 F ✓
35	1		*CONDENSOR ASSY	R ₁	0.00	0.00	*1,100.00 F ✓
36	1		*INTERCOOLER ASSY		0.00	0.00	*1,450.00 F ?
37	1		*FAN SHROUD ASSY COMPLETE		0.00	0.00	*1,950.00 F ?
38	1		*FRONT BUMPER REINFORCEMENT	R ₁	0.00	0.00	*850.00 F ✓
39	1		*AIR FILTER HOUSING		0.00	0.00	*550.00 F ?
40	1		*AIR RESONATOR		0.00	0.00	*250.00 F ?
41	1		*AIR HOSE		0.00	0.00	*180.00 F ?
42	1		*AIR DUCT		0.00	0.00	*140.00 F ?
43	1		*FUSE BOX HOUSING		0.00	0.00	*350.00 F ?
44	1		*AIR-COND SUCTION HOSE		0.00	0.00	*450.00 F ?
45	1		*AIR-COND DISCHARGE HOSE		0.00	0.00	*320.00 F ?
46	1		*REAR DOOR MOULDING LH		0.00	0.00	*350.00 F ?
47	1		*DASHBOARD	T ₁	0.00	0.00	*4,200.00 F ✓

48	1	*DRIVER AIRBAG	<i>Burn</i>	0.00	0.00	*2,800.00 F	<i>✓</i>
49	1	*PASSENGER AIRBAG	<i>u</i>	0.00	0.00	*3,200.00 F	<i>✓</i>
50	1	*AIRBAG ECU	<i>na</i>	0.00	0.00	*1,550.00 F	<i>✓</i>
51	1	*STEERING COLUMN SPRING COMPLETE	<i>na</i>	0.00	0.00	*2,000.00 F	<i>✓</i>
52	1	*SEAT BELT ASSY RH	<i>na</i>	0.00	0.00	*1,220.00 F	<i>✓</i>
53	1	*SEAT BELT ASSY LH	<i>na</i>	0.00	0.00	*1,220.00 F	<i>✓</i>
54	1	*FRONT WINDSCREEN - GLASS	<i>cm</i>	0.00	0.00	*1,700.00 F	<i>✓</i>
55	1	*FRONT WINDSCREEN - MOULDING	<i>na</i>	0.00	0.00	*300.00 F	<i>X</i>
56	1	*WASHER TANK	<i>na</i>	0.00	0.00	*240.00 F	<i>✓</i>
57	1	*FRONT INDICATOR LAMP ASSY RH	<i>na</i>	0.00	0.00	*380.00 F	<i>X</i>
58	1	*FRONT INDICATOR LAMP ASSY LH	<i>u</i>	0.00	0.00	*380.00 F	<i>X</i>
59	1	*PARKING SENSOR X 4PCS (EACH \$400/PC)	<i>3</i>	0.00	0.00	*1,600.00 F	<i>✓</i>
60	1	*HEADLAMP MODULE RH		0.00	0.00	*900.00 F	<i>?</i>
61	1	*HEADLAMP MODULE LH		0.00	0.00	*900.00 F	<i>?</i>
62	1	*HORN - HIGH PITCH		0.00	0.00	*100.00 F	<i>?</i>
63	1	*HORN - LOW PITCH		0.00	0.00	*100.00 F	<i>?</i>

F=Franchise part.

Sub Total (\$\$) 48,925.00
+ Margin on L,N Items 10.00% (\$\$) 4,892.50

Total Parts (\$\$) 53,817.50

Ding Auto Pte Ltd/SJC7938P/20/12/2022 17:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT GRILLE, INNER COVER & GARNISH PANEL CLIPS	250.00 ✓
2	1	HEADLAMP MODULE & ECU - REPROGRAMMING & CALIBRATION	550.00 300
Sub Total (S\$)			800.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,800.00 800 ✓
2	SPRAY PAINT - FRT BUMPER, BONNET, FRT FENDER X2, FRT DOOR X2, REAR DOOR LH & SUPPORT PANEL	New	1,800.00 1200
3	REMOVE & REFIT - DASHBOARD COMPONENTS	New	250.00 ✓
4	REMOVE & REFIT - SEAT BELT COMPONENTS (X2)	New	250.00 120
5	REMOVE & REFIT - FRT WINDSCREEN GLASS	New	180.00 120
6	ALIGN HEADLAMP/FOG LAMP/ DAY LAMP & TEST WIRING	New	180.00 30
7	ALIGN PARKING SENSOR & TEST WIRING	New	150.00 60
8	REFILL - RADIATOR COOLANT	New	80.00 50
9	REFILL - AIRCOND GAS	New	80.00 ✓
Gross Labour Cost (S\$)			4,770.00

Ding Auto Pte Ltd/SJC7938P/20/12/2022 17:50. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >