

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	HL ASSURANCE F	PTE LTD	F	Ref:	CS3/HLA22012742/y3	
	11 KEPPEL ROAD #11-01 ABI PLAZA	SINGAPORE 089057	Г	Date:	21/12/2022	
			C	Code:	HLA	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMN 3677A	Veh. Inspected		SJP 7841R	
	Policy No.	MP313749	Coverage (\$)		0.00	
	Claim No.	MPC03914/GN	Excess (\$)		0.00	
	Assign From	GRACE NG TIAN AI	Assign Date		21/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	dometer - Steering				
	Brakes Modification					
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	12/12/2022	Inspection Date			
	Survey held at	MASTER CAR SPRAY SERVICE 36 TOH GUAN ROAD EAST #01-48 ENTERPRISE HUB SINGAPORE 608580				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					