

Our Job Ref No : 305539960

Date 23.12.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SHC8466B

Date of Accident : 15.12.22


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A **INCOME** --- **FBP3967H**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$420.78
 - (b) Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost \$1,050.78**
 - (c.) Lumpsum Repair (If applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : NAZ

Date : 9/1/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305539960
REGN NO : SHC8466B
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 24.03.2022
DATE/TIME IN : 19.12.2022 11:05
ACCIDENT DATE : 15.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2712-G COVER REAR BUMPER#	1	503.04	25.00	377.28	/CRA
0002 04-01-0302-2267-G BUMPER PIECE	10	22.00	25.00	16.50	/NEC
0003 28-01-0302-2017-A FUEL TANK LID (PETROL ONL	1 N	30.00	10.00	27.00	/NEC

SUB-TOTAL : 420.78

JOB NATURE

0000 PB	PANEL BEAT (SHC8466B)TP	350.00	/
0001 SP	SPRAYPAINT CHARGE	250.00	/
0002 L	REMOVE/REFRIG REVERSE SENSOR	30.00	/

SUB-TOTAL : 630.00

TOTAL : 1,050.78


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Income CP/P)
JH

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305539960
REGN NO : SHC8466B
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 24.03.2022
DATE/TIME IN : 19.12.2022 11:05
ACCIDENT DATE : 15.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G	COVER REAR BUMPER	1	503.04	25.00	377.28	✓ CRA
0002 04-01-0302-2288-G	REINFORCEMENT SUB-ASSY RE	1	394.80	25.00	296.10	? X SVC
0003 04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50	✓ NE
0004 04-01-0302-2287-G	GUARD-REAR BUMPER CENTER	1	654.96	25.00	491.22	? X SVC
0005 04-01-0302-3837-G	RETAINER RR BUMPER SIDE L	1	94.80	25.00	71.10	? X SVC
0006 28-01-0302-2017-A	FUEL TANK LID (PETROL ONL	1 N	30.00	10.00	27.00	✓ NE

SUB-TOTAL : 1,279.20

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFRIG REVERSE SENSOR	50.00	30

SUB-TOTAL : 750.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305539960
REGN NO : SHC8466B
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 24.03.2022
DATE/TIME IN : 19.12.2022 11:0
ACCIDENT DATE : 15.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,029.20

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

NAZ LKK

19/12/2022 1744

P/P

2 Day

(CHECK ITEM PHOTO)

BEFORE PAINT PHOTO)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: