

COMFORT TRANSPORTATION PTE LTD**REPAIR ESTIMATE****Vehicle No. :** SHD3340H**Date:** 19/12/2022**Make :** HYUNDAI**Insurance:** INCOME**Model :** I-40**MVA:** MS. LOKE Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 553.00
1	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER LOWER COVER			\$ 228.00
	SUB TOTAL			\$ 803.00
	LESS 20%			\$ 160.60
	DISCOUNTED TOTAL			\$ 642.40
	REAR BUMPER RUBBER MAT			\$ 50.00
				\$ 50.00
	Labour Charge			
	PANEL BEATING			\$ 300.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR			\$ 660.00
	ESTIMATE TOTAL			\$ 1,352.40

✓ CEA
✓ NEC
✓ DEF

Nett ✓ NEC
Nett

280
250
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA 2 LKK

19/12/2022 1620

L/S

2 DAYS

AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: