			COMFORTDELGRO				
Our Job Ref No : 305539989				MINEERING			
Date : 22/12/22			ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156				
FINALIZATION FORM			Fax:	0346 8138			
To :	To :LKK		Fax :				
Attn : MrNaz							
Vehicle Reg No. : SH	Vehicle Reg No. : SHD3340H			19.12.2022			
The survey and estimates	of the repairs of the above-m	entioned vehic	le are as follow	vs:-			
4 -		NCOME		SLD5654S			
The finalized amount				3233313			
	after List discount						
(b) Labour Charg							
	t-By-Part Repair Cost						
TOTAL TOT PAR	-by-rart Repair Cost			\$0.00			
(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost		20%		\$1,000.00 \$1,000.00			
4. We shall treat the a 7 working days  5. Thank you for your a	2	w		estimates and			
Signature : Name : Ms. Lok	a YY		gnature :	NG2 LKK			
Tel : 62148355		_	Date : 9/1/2023				
Fax : 654681		_		11.1-02)			
		_					
For Official Use Only							
Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks			
Rental Rate P/Day		YES					
2. Loss of Income Paid		NO					
3. Survey Fees							
4. LTA Search Fee	\$7.49 / \$2.00			24			
<ol><li>Medical Fees (on behalf of driver, if applicable)</li></ol>							
O CHYBL HADDRADIE :							
6 Overrun							

## **COMFORT TRANSPORTATION PTE LTD**

REPAIR ESTIMATE

Vehicle No.: SHD3340H Make : HYUNDAI

Model

: I-40

Date: 19/12/2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	A	mount
4	1 REAR BUMPER COVER			\$	553.00
1	1 REAR BUMPER CLIPS			\$	22.00
1	1 REAR BUMPER LOWER COVER			\$	228.00
	SUB TOTAL			\$	803.00
	LESS 20%			\$	160.60
	DISCOUNTED TOTAL			\$	642.40
REAR BUMPER RUBBER MAT				\$	50.00
				\$	50.00
	Labour Charge				
PANEL BEATING				\$	<del>300.0</del> 0
SPRAY PAINTING CHARGE				\$	300.00
REMOVE/REFIX REVERSE SENSOR				\$	60.00
	TOTAL LABOUR			\$	660.00
	ESTIMATE TOTAL			\$	1,352.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK 19/12/2022 1620 L15 20Ays AFTER RELATE PHOTOS

Date: Signature: Acknowledged by Repairer

is subject to final approval from Insurance Company • Supplementary item(s) must be resurveyed and

- No illegal modification(s) is allowed
- Third party survey is on a "Without Prejudice" basis
  - Parts prices are subject to confirmation
  - To display damaged part(s) during resurvey
    - . To resurvey before/after spray painting
      - the Repairer of the following:

LKK Auto Consultants hence notity