

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012753/TVY3M4**Date:** 20/01/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00102632201

Claimant Vehicle No : SMS2348E **Insured Vehicle No :** YM9211J

Date of Loss: 19/12/2022 Nature of Claim: TP Claim No: SNM22D209163/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS2348E**

Make & Model: NISSAN NOTE, 1.2 (A) Engine No: HR12128556K

Reg. Date: 17/02/2020 (Man. Year: 2019) Chassis No: JN1TAAE12Z0983379

Colour: Silver Odometer: 36194 km

Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,027.76	1,014.32	2,013.44	66.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,763.00	1,405.00	1,358.00	49.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,790.76	2,419.32	3,371.44	58.22
+ GST 8.00/8.00% (S\$)	463.26	193.55	269.71	58.22
Nett Amount (S\$)	6,254.02	2,612.87	3,641.15	58.22

INSPECTION

Date of Assignment: 21/12/2022

Date Inspected: 23/12/2022 Inspected At: Tan Chong Motor Sales Pte Ltd (Bukit Timah)
911, Bukit Timah Road
Singapore 589622

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jan 2023)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS2348E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*CLIP (\$1.4X10)	Necessary	14.00 FN	*14.00 FN
2	10		*CLIP (\$1.4X10)	Necessary	14.00 FN	*14.00 FN
3	1		*HOOD	Bent	915.70 FN	*915.70 FN
4	1		*BRACE ASSY-R/CO	Not Necessary	317.30 FN	*- FN
5	1		*GRILLE TOP,RAD	Cut	299.20 FN	*299.20 FN
6	1		*LAMP ASSY-RH	Not Necessary	577.80 FN	*- FN
7	1		*LAMP ASSY-LH	Not Necessary	577.80 FN	*- FN
8	1		*EMBLEM RAD GRIL	Not Necessary	70.00 FN	*- FN
9	1		*GRILLE-RADIATOR	Not Necessary	299.20 FN	*- FN
10	1		*ENERGY ABSORBER	Not Necessary	236.30 FN	*- FN
11	1		*FACE-FR BUMPER	Repair	425.90 FN	*- FN
12	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	3,777.20	1,262.90
- Nett Item Discount on N Items 20.00/20.00% (S\$)	749.44	248.58
Total Parts (S\$)	3,027.76	1,014.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R/INSTALL OR RENEW FR HEADLAMP ASSIST TO REPAIR	New	48.00	0.00
2	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	120.00	120.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	100.00	100.00
4	REPAIR FR UPP PANEL,RH/LH FR FENDER & FR BUMPER RENEW FR HOOD	New	1,120.00	560.00
5	S/PAINT RH/LH FR FENDER, HOOD,FR TOP/BUMPER & FR PANEL	New	1,375.00	625.00
Gross Labour Cost (\$\$)			2,763.00	1,405.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >