

CS/CT/220/2753/Tvg3.

Veh No: SMS 2348F Yr Regn: 2020, Feb

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Note. C.C. 1198

Colour Sl / 1st A/C: Insured / Std / NI / NA

Sp. Reading 3/6/94. T/Radio: Insured / Std / NI / NA.

Eng/No:

C/No: 2017A1A11C10783377

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: in order / Jammed / Leaked / Burnt or

Modi: Nil / 6 / STD ARim or

	
N/S	O/S

Tyre Size: F:

R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO

Front

R/Bal.	6 mm	R/Bal.	6 mm
--------	------	--------	------

L/Bal.	6	mm	L/Bal.	6	mm
--------	---	----	--------	---	----

D.O.A. 19/12/2022 D.O.I. 23/12/22

Survey held at Tan Chong Bht 1, mah

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The W/C / Chassis frame / Body Structure affected due to collision.

19/1/23	Final fig \$2419.32 (Red 3371.44,58%)
---------	---------------------------------------

☐: Prelim. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 1

2) 19/1/23-typist

Add Fee: ☐ Site Insp (\$

~~Elmer Ferner~~ : Merimen

Large Green Table **\$2419.32**

e: ☐ Site Insp (\$

□; Interview (\$

TECHNICS 18

400

Survey Fee:

Transportation:

$$S + RS \rightarrow S!$$

3) Photos

1) Others

23/12/22 @ 9.50am

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0354/2022
DATE : 20-DEC-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR KUAN THAI SOH
ADDRESS : BLK 109 TECK WHYE LANE
#06-578
S(680109)
TELEPHONE NO : 98577527

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-YM9211J
VEHICLE NO : SMS2348E
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12128556K
CHASSIS NO : JN1TAAE12Z0983379
MILEAGE : 1 KM
DATE IN : 20/12/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 19/12/2022

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMS2348E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	R/INSTALL OR RENEW FR HEADLAMP ASSIST TO REPAIR	48.00	? X
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	✓
4	ZZ/001	REPAIR FR UPP PANEL,RH/LH FR FENDER & FR BUMPER RENEW FR HOOD	1120.00	280 560
5	ZZ/002	S/PAINT RH/LH FR FENDER,HOOD,FR TOP/BUMPER & FR PANEL	1375.00	625
TOTAL LABOUR CHARGES			2763.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMS2348E

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 CLIP(\$1.4X10)	01553-05933	14.00	7ec ✓	
2 CLIP(\$1.4X10)	01553-10501	14.00	7ec ✓	
3 SUNDRIES	NPN			20. 30.00 nec
4 HOOD	F510M-3VAMA	915.70	bt ✓	
5 BRACE ASSY-R/CO	62511-3VA3H	317.30	? X nn	
6 GRILLE TOP,RAD	62320-5WJ1A	299.20	7ent ✓	
7 LAMP ASSY-RH	26010-5WK0B	577.80	? X nn	
8 LAMP ASSY-LH	26060-5WK0B	577.80	? X nn	
9 EMBLEM RAD GRIL	62890-3VA2A	70.00	? X nn	
10 GRILLE-RADIATOR	62310-5WJ0B	299.20	? X nn	
11 ENERGY ABSORBER	62090-5WJ0A	236.30	? X nn	
12 FACE-FR BUMPER	62022-5WJ0H	425.90	Rp	
SUB TOTAL		3747.20	0.00	30.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		749.44	0.00	0.00
GRAND TOTAL		2997.76	0.00	30.00
OVERALL TOTAL		3027.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMS2348E

TOTAL LABOUR CHARGES	2763.00
TOTAL SPARE PARTS CHARGES	3027.76
GRAND TOTAL	5790.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Tanpin 9749549/62563561
- WP 23/12/22 @ 930
P/P Resurvey before paint.
4-5 days
tanpin @ khantowm.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: