

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TP Chirren.

Veron

Page No. 1

Vehicle No. SMC8588Z

TOYOTA CHR

ZYX102113798

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	REAR BUMPER <i>Dehid</i>		855.10	✓
2	REAR BUMPER SIDE HOLDER @112.20 <i>new</i>		224.40	✓
3	REAR BUMPER SIDE GRILLE @187.00 <i>2 new</i>		374.00	x
4	REAR BUMPER SIDE GRILLE REFLECTOR @59.00 <i>new</i>		118.00	x.
5	REAR BUMPER TOW COVER <i>Dehid</i>		27.70	✓
6	REAR BUMPER LOWER GARNISH <i>Dehid</i>		465.10	✓
7	REAR BUMPER RINFORCEMENT <i>Dehid</i>		352.70	✓
8	REAR BUMPER UNDERCOVER @189.20 <i>new</i>		378.40	x
9	REAR BUMPER LOWER GARNISH REFLECTOR <i>Cracked</i>		145.40	✓
10	REVERSE SENSOR @250.00 <i>Damaged</i>		500.00	200(SN).
11	REAR END PANEL <i>new</i>		731.40	x
12	REAR END PANEL TOP GARNISH <i>new</i>		347.40	x
13	REAR END PANEL ANTENNA SENSOR <i>new</i>		106.90	x.
14	TAILGATE <i>new</i>		1112.50	x
15	TAILGATE LOCK		389.40	x
16	TAILGATE LOCK COVER		29.40	x
17	TAILGATE LOCK STRIKER		105.50	x
18	TAILGATE WEATHERSTRIPE		371.40	x
19	TAILGATE INNER PULL POCKET		38.40	x
20	TAILGATE GLASS MOULDING		158.40	x
21	TOYOTA LOGO		72.20	x
22	CHR WORDING		55.60	x
23	HYBRID EMBLEM		121.40	x
24	REAR EXHAUST PIPE		987.90	x
25	REAR EXHAUST PIPE MOUNTING		45.00	x
26	REAR EXHAUST PIPE GASKET		45.40	x
27	REAR EXHAUST PIPE HEAT SHIELD		110.90	x.
			8269.90	
		less 25%	2067.48	25%
			6202.43	
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS <i>new</i>		50.00	30
2	REAR BUMPER LOWER SPOILER <i>Damaged</i>		1000.00	600.
3	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		20.00	x
4	REAR END PANEL SEALANT <i>new</i>		60.00	x
5	TAILGATE GLASS SEALANT		60.00	x.
	Total Parts		1190.00	

2070.40

1552.80

S.N: 200

630

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Page No. 2

Vehicle No. SMC8588Z

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1200.00	500
2	SPRAY PAINTING	1200.00	500
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	150.00	X
5	TO REMOVE UPHOLSTERY	150.00	30
6	TO TRANSFER TAILGATE FITTINGS	150.00	X
7	TO REMOVE TAILGATE GLASS	180.00	X
8	TO REMOVE REVERSE SENSOR	100.00	50
9	TO REMOVE REAR CAMERA	100.00	X
10	TO REMOVE REAR VIDEO RECORDER	100.00	X
	Labour Total :	3380.00	
TOTAL (PARTS & LABOUR):		10772.43	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3492.80

H/s: 2.8K

0 3 Days.

2.8K.