

ASS. REC. BY:

REF:

LIP / 22012757/Knys

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$68k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 4 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKV 9312UYr Regn: 10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Odysseyc.c. 2356Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 148467

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RC11107208Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 23/11/22D.O.I. 27/12/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/12/21 Rpt @ 3050h Central (Red. \$ 2116.16, 41%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	758Z
Vehicle Details	
Vehicle No.:	SKV9312U
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Dec 2022
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY ABSOLUTE 2.4 CVT ABS AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K24W1407335
Chassis No.:	RC11107208
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$29,622.00
Original Registration Date:	08 Oct 2015
First Registration Date:	08 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$33,471.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Oct 2025
PARF Rebate Amount:	\$20,082.00
Intended COE Rebate Details	
COE Expiry Date:	07 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,001.00
COE Rebate Amount:	\$16,879.00
Total Rebate Amount:	\$36,961.00

The information contained herein is correct as at 14 Dec 2022

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

Not Authorized

M/S: LIBERTY INSURANCE PTE LTD
 51 CLUB STREET
 #03-00 LIBERTY HOUSE
 SINGAPORE 069428
 TEL: 62218611
 ATTN: Motor Claim Department

61/Py 83050/r
Recovery After Pain
4 days

Estimate No: ES2291340/AMK
 Date: 27 Dec 2022
 Policy No: 5074510496-07
 Veh Reg No: SKV9312U
 Make/Model: HONDA ODYSSEY 2.4 CVT
 Chassis No: RC11107208
 Engine No: K24W1407335
 Reg. Date: 08/10/2015

WS Ref: TP/LIBERTY/AMK
 Claim Type: Third Party
 Accident Date: 23/11/2022
 TP Veh Reg No: SLX7459X

Estimate Repair Cost to Vehicle No :SKV9312U

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	626.60	1 PC	<i>Bu</i> 626.60	<i>—</i>
2 REAR BUMPER CLIP	3.90	5 PC	<i>na</i> 19.50	<i>—</i>
3 REAR BUMPER CHROME	121.90	2 PC	<i>na</i> 243.80	<i>—</i>
4 REAR TAILGATE	1,193.00	1 PC	<i>Bu</i> 1,193.00	<i>—</i>
5 TAILGATE LOGO	280.30	1 PC	<i>na</i> 280.30	<i>—</i>
6 TAILGATE INNER LOCK	203.50	1 PC	<i>na</i> 203.50	<i>x</i>
7 TAILGATE INNER RUBBER	125.30	1 PC	<i>na</i> 125.30	<i>502.12 61.755m</i>
8 TAILGATE LOWER CHROME MOULDING	215.90	1 PC	<i>na</i> 215.90	<i>—</i>
9 TAILGATE WINDSCREEN GLASS MOULDING	203.10	1 SET	<i>na</i> 203.10	<i>—</i>
10 REAR END PANEL	591.20	1 PC	<i>na</i> 591.20	<i>x</i>
11 REAR END PANEL TOP GARNISH	130.50	1 PC	<i>Bu</i> 130.50	<i>x</i>
			3,832.70	
		Less 20%	766.54	3,066.16
Special Net				
12 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>na</i> 40.00	<i>—</i>
13 REAR END PANEL SEALANT	40.00	1 PC	<i>na</i> 40.00	<i>x</i>
14 REVERSE SENSOR	200.00	1 SET	<i>Shay</i> 200.00	<i>—</i>
			280.00	280.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	<i>✓</i>
16 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILLAMPS, TAILGATE & ATTACHMENTS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	800.00	1 LA	800.00	<i>500</i>
17 PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS, TAILGATE, REAR END PANEL, REAR LUGGAGE PANEL & ALL AFFECTED AREAS	800.00	1 LA	800.00	<i>600</i>
18 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	40.00	1 PC	40.00	<i>✓</i>
19 RUSTPROOFING	60.00	1 LA	60.00	<i>300</i>
			1,820.00	1,820.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : LIBERTY INSURANCE PTE LTD

51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428

TEL: 62218611

FAX: 62241047

ATTN: Motor Claim Department

WS Ref: TP/LIBERTY/AMK

Claim Type: Third Party

Accident Date: 23/11/2022

TP Veh Reg No: SLX7459X

Estimate No: ES2291340/AMK

Date: 27 Dec 2022

Policy No: 5074510496-07

Veh Reg No: SKV9312U

Make/Model: HONDA ODYSSEY 2.4
CVT

Chassis No: RC11107208

Engine No: K24W1407335

Reg. Date: 08/10/2015

Estimate Repair Cost to Vehicle No :SKV9312U

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 5,166.16
			Add GST @ 7%	361.63
			Total Amount Payable	<u>S\$ 5,527.79</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE