

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012759/KVY3Q2**Date:** 19/06/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00000132201		
Claimant Vehicle No :	SLR4088J	Insured Vehicle No :	PC4233M		
Date of Loss:	13/12/2022	Nature of Claim:	TP	Claim No:	SNM22D209060/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR4088J	Engine No:	G4FGHH678032
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFJ411MJ5739461
Reg. Date:	15/08/2017 (Man. Year: 2017)	Odometer:	42103 km
Colour:	Metallic Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,408.00	1,054.00	354.00	25.14
Miscellaneous Items	35.00	35.00	0.00	0.00
Labour	1,150.00	820.00	330.00	28.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,593.00	1,909.00	684.00	26.38
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	2,593.00	1,700.00	893.00	34.44
+ GST 8.00/8.00% (S\$)	207.44	136.00	71.44	34.44
Nett Amount (S\$)	2,800.44	1,836.00	964.44	34.44

INSPECTION

Date of Assignment:	26/01/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	26/01/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2023)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR4088J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER	Buckled / Dented	550.00 F	*550.00 F
2	1		*1 PC FRT BUMPER RH SIDE RETAINER	Serviceable	6.00 F	*- F
3	1		*1 PC FRT BUMPER REINFORCEMENT	Repair	190.00 F	*- F
4	1		*6 PCS FRT BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
5	1		*1 PC FRT BUMPER LOGO	Necessary	42.00 F	*42.00 F
6	1		*1 PC FRT BUMPER RH AIR DUCT	Serviceable	30.00 F	*- F
7	1		*1 PC RH HEADLAMP	Cut	450.00 F	*450.00 F
						F=Franchise part.
Sub Total (\$\$)					1,280.00	1,054.00
+ Margin on L,N Items 10.00/0.00% (\$\$)					128.00	0.00
Total Parts (\$\$)					1,408.00	1,054.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT NO.PLATE (NECESSARY)	35.00	35.00
Sub Total (\$\$)			35.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT FRT BUMPER ASSY, FOGLAMPS, GRILLE, HEADLAMP. TO KNOCK, REPAIR FRT RH FENDER AND REALIGN THE SAME.	New	400.00	300.00
2	PUTTY AND RESPRAY FRT RH FENDER, FRT BUMPER , FRT RH DOOR.	New	600.00	400.00
3	TO APPLY FOR REMOVE AND REFIT OPC NO PLATE, SEND FOR INSPECTION INCLUDING COUPON.	New	150.00	120.00
Gross Labour Cost (\$\$)			1,150.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >