



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 1742P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	MTG CRACKED	1,349.90	981.00
1	FRONT BUMPER LH SIDE RETAINER	DISTORTED	72.00	72.00
1	SET FRONT BUMPER CLIPS	NECESSARY	40.00	40.00
1	FRONT BUMPER INNER FOAM	SERVICEABLE	85.90	-
1	LH HEADLAMP	CUT	876.20	876.20
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	652.40	-
1	FRONT LH FENDER UNDER SPLASH SHIELD	SERVICEABLE	248.00	-
1	SET FRONT FENDER UNDER SPLASH SHIELD CLIPS	NOT NECESSARY	40.00	-
1	FRONT LH SHOCK ABSORBER	SERVICEABLE	386.00	-
1	FRONT LH LOWER ARM	SERVICEABLE	435.20	-
1	FRONT LH KNUCKLE ARM	BENT	620.00	590.00
1	FRONT LH WHEEL HUB & BEARING	NECESSARY	286.40	286.40
1	FRONT STABILIZER BAR LH LINK ROD	SERVICEABLE	171.00	-
	LESS 25% DISCOUNT		-1,315.75	-711.40
			3,947.25	2,134.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT LH TYRE (SN)	SERVICEABLE	280.00	-
1	FRONT LH SPORT RIM (SN)	DENTED	600.00	400.00
			880.00	400.00
<b><u>LABOUR</u></b>				
	LABOUR CHARGES FOR REMOVE / REFIT, PANEL BEATING, CUTTING, WELDING AND REPLACEMENT OF DAMAGES. INCLUSIVE OF THE REPAIR OF FRONT LH FENDER.		600.00	300.00
	TO PUTTY AND SPRAY PAINTINGS CHARGES.		600.00	400.00
	TO REMOVE, REFIT FRONT LH UNDER CARRIAGE DAMAGES.		250.00	80.00
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.		100.00	60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TP APPLY ANTI RUST TREATMENT.	NOT NECESSARY	60.00	-
			1,610.00	840.00
GRAND TOTAL			6,437.25	3,374.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/AGI22012760/Kny3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.