

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22012760/Kny3e2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date:	05/01/2023	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLG 4008Z	Veh. Inspected	SJJ 1742P	
	Policy No.	P10619999R01	Coverage (\$)	0.00	
	Claim No.	C10019384 /JT	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	21/12/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ESTIMA (A)	c.c	2362	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	ACR507061157	Colour	METALLIC BLACK	
	Odometer	350851 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/50 R18	YOKOHAMA	9 mm	
	L/H Front Tyre	225/50 R18	YOKOHAMA	9 mm	
	R/H Rear Tyre	225/50 R18	YOKOHAMA	9 mm	
	L/H Rear Tyre	225/50 R18	YOKOHAMA	9 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	. General Information				
	Accident Date	18/12/2022	Inspection Date	21/12/2022	
	Survey held at	GUAN MOTOR WORKS			
		176 SIN MING DRIVE #02-03			
		SIN MING AUTOCARE SINGAPORE 575721			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: