

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 20.12.2022

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLB1039E**
MODEL : **NISSAN X-TRAIL**
DATE OF ACCIDENT : 20.12.2022
TIME OF ACCIDENT : 12:00 HRS

Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT NETT PRICE	TOTAL NETT PRICE
1	TAILGATE WEATHER STRIP <i>3 m</i>	1	\$ 164.90	\$ 164.90
2	TAILGATE DETECTOR <i>1 m</i>	1	\$ 469.30	\$ 469.30
3	REAR BUMPER <i>Dehd.</i>	1	\$ 673.80	\$ 673.80
4	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 65.40	\$ 130.80
5	REAR BUMPER CENTER AIR VENT <i>Dehd</i>	1	\$ 105.30	\$ 105.30
6	REAR BUMPER SIDE RETAINER <i>m</i>	2	\$ 39.80	\$ 79.60
7	REAR BUMPER REINFORCEMENT <i>Dehd</i>	1	\$ 587.10	\$ 587.10
8	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 196.20	\$ 392.40
9	REAR FENDER ARCED GARNISH <i>2</i>	2	\$ 164.70	\$ 329.40
10	REAR FENDER INNER COWLING <i>3 m</i>	2	\$ 97.30	\$ 194.60
11	REAR FENDER INNER TRIM <i>3 m</i>	2	\$ 479.40	\$ 958.80
12	REAR END PANEL <i>Repair</i>	1	\$ 496.30	\$ 496.30
13	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 127.10	\$ 127.10
14	REAR STORAGE COVER BOARD <i>3 m</i>	1	\$ 915.80	\$ 915.80
15	REAR STORAGE COVER BOARD (SIDE) <i>3 m</i>	2	\$ 71.40	\$ 142.80

1572.90
1415.61

TOTAL PRICE \$ 5,768.00
LESS 10% \$ 576.80
SUB TOTAL PRICE \$ 5,191.20

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER TOP CHROME (SPECAIL TYPE) <i>new</i>	1	\$ 450.00	\$ 450.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER LOWER SPOILER (SPECAIL TYPE) <i>Dehd</i>	1	\$ 1,800.00	\$ 1,800.00
4	REAR FENDER ARCED GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
5	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
6	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLB1039E**
 MODEL : **NISSAN X-TRAIL**
 DATE OF ACCIDENT : 20.12.2022
 TIME OF ACCIDENT : 12:00 HRS

7	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
8	REAR END PANEL TOP GARNISH CLIP (SET) <i>an</i>	1	\$ 40.00	\$ 40.00	<i>10</i>
9	REAR END PANEL TOP CHROME (SPECAIL TYPE) <i>del</i>	1	\$ 380.00	\$ 380.00	<i>280</i>
10	REVERSE SENSOR (4PCS) <i>and</i>	1	\$ 480.00	\$ 480.00	<i>250</i>

1850

TOTAL \$ 3,560.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	<i>300</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	<i>400</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING AND BULB CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIAE REPAIR	\$ 350.00	<i>30</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>x</i>
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

840

TOTAL \$ 3,960.00

Admin

F/S 21/12/22

04 Days

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,751.20
 TOTAL LABOUR COST : \$ 3,960.00
 TOTAL REPAIR COST : \$ 12,711.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

total: 4105.61

F/S: 3250 ✓