

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/III22012765/ANY3M4**Date:** 15/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

**Claimant Vehicle No :** SLV6082R**Insured Vehicle No :** SLM1523R

Date of Loss: 19/12/2022

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLV6082R**

Make &amp; Model: HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)

Engine No: G4FGHU861278

Reg. Date: 06/01/2018 (Man. Year: 2017)

Chassis No: KMHD841CMJU610400

Colour: Grey

Odometer: 0 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,741.28	2,007.04	1,734.24	46.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,240.00	1,060.00	46.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,041.28</b>	<b>3,247.04</b>	<b>2,794.24</b>	<b>46.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,041.28</b>	<b>2,600.00</b>	<b>3,441.28</b>	<b>56.96</b>

INSPECTION

Date of Assignment: 21/12/2022

Date Inspected: 10/01/2023 Inspected At:

AUTOMOBILE HUB ENTERPRISE  
1 KAKI BUKIT AVENUE 6  
#02-11 AUTOBAY  
SINGAPORE 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV6082R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	485.40 FL	*- FL
2	1		*FRONT BUMPER SIDE HOLDER	Not Necessary	34.90 FL	*- FL
3	1		*FRONT FENDER	Repair	1,227.00 FL	*- FL
4	1		*FRONT DOOR	Dented	1,832.40 FL	*1,832.40 FL
5	1		*FRONT DOOR LOCK	Not Necessary	247.20 FL	*- FL
6	1		*FRONT DOOR WEATHERSTRIPE	Not Necessary	135.80 FL	*- FL
7	1		*FRONT DOOR MIRROR	Damaged	638.90 FL	*638.90 FL
8	1		*FRONT BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
9	1		*FRONT DOOR PROTECTOR	Necessary	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,661.60	2,501.30
- List Item Discount on L Items 20.00/20.00% (\$\$)					920.32	494.26
Total Parts (\$\$)					3,741.28	2,007.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	1,000.00	700.00
3	WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	30.00
5	TO REMOVE UPHOLSTERY	New	150.00	0.00
6	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>2,300.00</b>	<b>1,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >