

Vehicle Damage Assessment Report for [SLV6082R]

Estimate Created: 09/05/2023 07:16 by LKK_assignments
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 09/05/2023 16:35 by LKK_assignments (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Elantra
Engine Type			
License Plate Number	SLV6082R	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	MICHELIN 195/65R15 6.0 mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$2,600.00 WITH 3 WORKING
DAYS

Insurlogic 4 (09/05/2023 16:34)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Front door		1	1832.40	-20.00 %	1,465.92
Front door mirror		1	638.90	-20.00 %	511.12

Parts Subtotal 1,977.04

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Front door protector		1.0	30.00	0.00 %	30.00

Materials Subtotal 30.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	400.00	0.00 %	400.00
Wiring	RnR	30.00	0.00 %	30.00
To apply tuff coat	RnR	30.00	0.00 %	30.00
To transfer front door fittings	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	700.00	0.00 %	700.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 540.00

Paint Labor Subtotal 700.00

Labor Subtotal 1,240.00

Summary

Repair Cost 3,247.04

Discount(20 %) (649.41)

2,597.63

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 2,597.63