

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01055/2022/EQ
DATE : 24-Nov-22
WIP : 48226

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WU JIANWEI
ADDRESS : 37 GOODMAN ROAD
SINGAPORE 439003

TELEPHONE : HP +65 81332270
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210114406
VEHICLE NO : **SLF 8283 Z**
MODEL CODE : AUDI RS E-TRON GT F83RH7
MODEL YEAR : 24/9/2021
ENGINE NO : EBG 047285
CHASSIS NO : WAUZZZFW7N7902024
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Jun-22
PLACE OF ACCIDENT : GUILLEMARD ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 8283 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$	280.00	
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$	800.00	
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
4	TO REMOVE AND RENEW AIRCON CONDENSER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,800.00	
5	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND KNEE AIRBAG.	S/N \$	3,600.00	
6	TO REMOVE AND REINSTALL FRONT COMPARTMENT COMPONENTS AND FRONT AXLE DIFFERETIAL TO FACILLITATE CAR O-LINER REPAIRS.	S/N \$	3,200.00	
TOTAL LABOUR CHARGES		:	\$ 10,160.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 8283 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILLITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$	3,600.00	
8	TO PLACE VEHICLE ON CAR O-LINER.	S/N \$	2,400.00	
9	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	450.00	
10	TO RENEW FRONT WINDSCREEN.	S/N \$	480.00	
11	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$	400.00	
12	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$	200.00	
TOTAL LABOUR CHARGES		:	\$ 7,530.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 8283 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO CARRY OUT DE-ENERGISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$	480.00	
14	TO REMOVE AND REINSTALL HIGH VOLTAGE BATTERY ASSY.	S/N \$	1,800.00	
15	TO CARRY OUT BATTERY MODULE CHECK.	S/N \$	1,800.00	
16	TO REMOVE AND REINSTALL REAR SUSPENSION ASSY WITH SUBFRAME. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$	3,600.00	
17	TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, RHS FRONT DOOR AND BOTH SILL PANEL TRIMS. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT, RHS FRONT UPPER WHEEL MOUNT WITH WHEEL HOUSING, FIREWALL, RHS A-PILLAR AND RHS SILL PANEL. ALIGN BOTH RHS CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	23,400.00	
18	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, RHS FRONT DOOR, DOOR HINGES, RHS WING MIRROR COVER, BOTH SILL PANEL TRIM, RHS FENDER TOP SUPPORT, RHS FRONT UPPER WHEEL HOUSING, FIREWALL, RHS A-PILLAR, RHS SILL PANEL AND DOOR ENTRANCE. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	\$	12,000.00	
TOTAL LABOUR CHARGES		:	\$ 43,080.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLF 8283 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
19	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	900.00	
20	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00	
21	TO APPLY LTA APPROVAL FOR CUTTING CHASSIS NUMBER FRAME.	S/N \$	480.00	
22	TO CARRY OUT CALIBRATION AND BASIC SETTING FOR FRONT BUMPER CAMERA.	S/N \$	480.00	
23	TO RENEW ALL FRONT RIM. TO CARRY OUT PRE-REPAIR WHEEL ALIGNMENT CHECK AND POST-REPAIR WHEEL ALIGNMENT CHECK.	S/N \$	640.00	
24	TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST-REPAIR DIAGNOSTIC CHECK.	S/N \$	384.00	
TOTAL LABOUR CHARGES		:	\$ 65,454.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,420.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 608.00	
3	FRONT BUMPER TRIM	1	\$ 1,159.00	
4	FRONT BUMPER GRILLE - LH / RH	2	\$ 426.00	
5	FRONT BUMPER TRIM - CENTER	1	\$ 83.00	
6	FRONT BUMPER TRIM - LH	1	\$ 28.00	
7	FRONT BUMPER TRIM - CENTER	1	\$ 34.00	
8	FRONT BUMPER TRIM - RH	1	\$ 28.00	
9	FRONT BUMPER SPOILER	1	\$ 822.00	
10	FRONT BUMPER COVER	1	\$ 61.00	
11	AUDI EMBLEM	1	\$ 181.00	
12	FRONT BUMPER COVER - CENTER	1	\$ 22.00	
13	FRONT BUMPER BRACKET - CENTER	1	\$ 168.00	
14	FRONT BUMPER SECURING PLATE - CENTER	1	\$ 37.00	
15	FRONT BUMPER ADAPTER	1	\$ 101.00	
16	FRONT BUMPER GRILLE	1	\$ 518.00	
17	FRONT BUMPER FOAM STRIPS	1	\$ 13.00	
18	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 235.00	
19	FRONT BUMPER ADJUSTMENT PART	1	\$ 28.00	
20	FRONT BUMPER PLASTIC FOAM STRIP	1	\$ 257.00	
SUB TOTAL SPARE PARTS		:	\$ 8,229.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER BRACKET	1	\$ 24.00	
22	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	1	\$ 248.00	
23	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 398.00	
24	ADHESIVE TAPES	1	\$ 30.00	
25	FRONT BUMPER AIR GUIDE - LH / RH OUTER	2	\$ 202.00	
26	FRONT BUMPER AIR GUIDE PLATE BLOCK LH / RH	2	\$ 1,390.00	
27	FRONT "360" CAMERA	1	\$ 1,006.00	
28	FRONT BUMPER WIRING SET	1	\$ 1,038.00	
29	FRONT BUMPER FOAM FILLER PIECE	1	\$ 134.00	
30	FRONT BUMPER BRACKET - LH / RH	2	\$ 122.00	
31	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 72.00	
32	FRONT BUMPER BRAKE COOLING AIR DUCT - LH / RH	2	\$ 228.00	
33	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 84.00	
34	FRONT BUMPER SUPPORT - LOWER	1	\$ 232.00	
35	FRONT BUMPER CROSS MEMBER	1	\$ 2,169.00	
36	FRONT DRIVER ASSISTANCE SYSTEM BRACKET	1	\$ 237.00	
37	FRONT BUMPER PULL STRAP	1	\$ 387.00	
38	LOCK CARRIER	1	\$ 1,341.00	
39	TWIN HORN	1	\$ 238.00	
40	FRONT PARKING AID SENSOR	1	\$ 292.00	
SUB TOTAL SPARE PARTS		:	\$ 9,872.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT PARKING AID SENSOR - CENTER INNER / OUTER	2	\$ 584.00	
42	FRONT PARKING AID SENSOR - OUTER	2	\$ 584.00	
43	FRONT PARKING AID SEAL RING	4	\$ 10.00	
44	FRONT FENDER - LH / RH	2	\$ 11,910.00	
45	FRONT FENDER SUPPORT - LH / RH	2	\$ 176.00	
46	FROTN FENDER SUPPORT - LH / RH	2	\$ 346.00	
47	FRONT FENDER CONSOLE BRACKET - LH / RH	2	\$ 920.00	
48	FRONT FENDER BRACKET - LH / RH	2	\$ 70.00	
49	FRONT FENDER BRACKET - LH / RH	2	\$ 70.00	
50	FRONT FENDER BRACKET - LH / RH	2	\$ 82.00	
51	RADIATOR AIR GUIDE - LH/ RH INNER	2	\$ 126.00	
52	FRONT FENDER TRIM - LH / RH INNER	2	\$ 184.00	
53	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 706.00	
54	FRONT WHEEL HOUSING LINER - LH / RH LOWER	2	\$ 376.00	
55	FRONT FENDER FUEL FILLER FLAP - RH	1	\$ 346.00	
56	FRONT FENDER INSERT - RH	1	\$ 819.00	
57	FRONT THROTTLE CONTROL ELEMENT	1	\$ 191.00	
58	FRONT FIBRE OPTIC CONDUCTOR	1	\$ 163.00	
59	FRONT SWITCH MODULE MECHANICAL - RH	1	\$ 199.00	
60	BONNET	1	\$ 7,749.00	
SUB TOTAL SPARE PARTS		:	\$ 25,611.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	BONNET IMPACT PROTECTION - CENTER	1	\$ 66.00	
62	BONNET HINGE - LH / RH	2	\$ 606.00	
63	BONNET GAS FILLED STRUT - LH / RH	2	\$ 256.00	
64	BONNET STRIKER	1	\$ 123.00	
65	BONNET HOOD HINGE COVER - RH	1	\$ 34.00	
66	BONNET SEAL	1	\$ 180.00	
67	FRONT RETAINER COVER	1	\$ 22.00	
68	BONNET LOCK	1	\$ 246.00	
69	BONNET ATTACHMENT PARTS	1	\$ 249.00	
70	LOCK CARRIER COVER	1	\$ 329.00	
71	LOCK CARRIER COVER - LH / RH	2	\$ 392.00	
72	LOCK CARRIER COVER - UPPER	1	\$ 225.00	
73	FRONT WATER BOX COVER	1	\$ 222.00	
74	HEADLIGHT - LH / RH	2	\$ 48,640.00	
75	HEADLIGHT HOSE - LH / RH	2	\$ 100.00	
76	HEADLIGHT COMPENSATING PIECE	4	\$ 185.00	
77	LIFT CYLINDER WASH WATER RESERVOIR	1	\$ 240.00	
78	LIFT CYLINDER WINDSCREEN WASHER SYSTEM PUMP	1	\$ 138.00	
79	LIFT CYLINDER FUEL FILLER NECK	1	\$ 202.00	
80	LIFT CYLINDER WASHER WATER HOSE LINE	1	\$ 18.00	
SUB TOTAL SPARE PARTS		:	\$ 52,473.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	LIFT CYLINDER PIPE	1	\$ 77.00	
82	LIFT CYLINDER PIPE	1	\$ 519.00	
83	LIFT CYLINDER WASHER WATER HOSE LINE	1	\$ 18.00	
84	A/C CONDENSER	1	\$ 687.00	
85	FRONT FRAME - RH	1	\$ 218.00	
86	A/C CONDENSER REFRIGERANT LINE	1	\$ 50.00	
87	A/C CONDENSER REFRIGERANT LINE	1	\$ 130.00	
88	A/C CONDENSER REFRIGERANT LINE	1	\$ 114.00	
89	A/C CONDENSER REFRIGERANT LINE	1	\$ 358.00	
90	A/C CONDENSER REFRIGERANT LINE	1	\$ 141.00	
91	A/C CONDENSER REFRIGERANT LINE	1	\$ 463.00	
92	A/C CONDENSER REFRIGERANT LINE	1	\$ 808.00	
93	A/C CONDENSER HEAT CONDENSER	1	\$ 573.00	
94	A/C CONDENSER REFRIGERANT LINE	1	\$ 203.00	
95	A/C CONDENSER BRACKET SHUT-OFF VALVES	1	\$ 66.00	
96	A/C CONDENSER BRACKET SHUT-OFF VALVES BRACKET	1	\$ 183.00	
97	FRONT AIR CONDITIONING DRIER	1	\$ 161.00	
98	RADIATOR DISTRIBUTOR	1	\$ 337.00	
99	RADIATOR	1	\$ 1,384.00	
100	RADIATOR AIR GUIDE - LH / RH	2	\$ 218.00	
SUB TOTAL SPARE PARTS		:	\$ 6,708.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	FRONT FRAME	1	\$ 218.00	
102	RADIATOR EXPANSION TANK	1	\$ 233.00	
103	READY-MIX COOLANT	18	\$ 890.00	
104	RADIATOR FAN - RH	1	\$ 2,899.00	
105	RADIATOR FAN PROTECTIVE CAP	1	\$ 46.00	
106	RADIATOR AIR GUIDE	1	\$ 48.00	
107	RADIATOR FAN - LH	1	\$ 3,173.00	
108	PROTECTIVE CAP	1	\$ 46.00	
109	RADIATOR AIR GUIDE - LH	1	\$ 48.00	
110	SIDE MEMBER - RH	1	\$ 1,451.00	
111	FRONT END SECTION	1	\$ 43,043.00	
112	FRONT SUSPENSION STRUT MOUNTING - RH	1	\$ 18,943.00	
113	FRONT SIDE PART - RH	1	\$ 6,894.00	
114	FRONT WINDSCREEN	1	\$ 3,932.00	
115	FRONT WINDSCREEN GEL FOIL RAIN SENSOR	1	\$ 131.00	
116	FRONT RETAINING SPRING	1	\$ 24.00	
117	WINDSCREEN PRIMER	1	\$ 22.00	
118	SIDE MEMBER TRIM - LH / RH	2	\$ 2,068.00	
119	FRONT ROCKER PANEL MOLDING BRACKET - LH / RH	2	\$ 184.00	
120	FRONT WHEEL COVER - RH	1	\$ 259.00	
SUB TOTAL SPARE PARTS		:	\$ 84,552.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
121	FRONT WHEEL COVER STONE CHIP PROTECTION FILM - LH / RH	2	\$ 658.00	
122	FRONT DOOR - RH	1	\$ 7,611.00	
123	FRONT OUTER DOOR SEAL	1	\$ 191.00	
124	FRONT DOOR ATTACHMENT PARTS	1	\$ 380.00	
125	FRONT DOOR HINGE HALF - RH UPPER	1	\$ 105.00	
126	FRONT DOOR HINGE HALF - RH UPPER	1	\$ 151.00	
127	FRONT DOOR HINGE HALF - RH LOWER	1	\$ 105.00	
128	FRONT DOOR HINGE HALF - RH LOWER	1	\$ 151.00	
129	FRONT DOOR SEAL - RH	1	\$ 261.00	
130	FRONT DOOR SEAL - RH INNER	1	\$ 808.00	
131	FRONT DOOR CATCH	1	\$ 105.00	
132	FRONT WINDOW GUIDE SLOT SEAL - RH INNER	1	\$ 759.00	
133	FRONT WINDOW SLOT SEAL TRIM STRIP - RH OUTER	1	\$ 422.00	
134	FRONT EXTERIOR WING MIRROR MOUNTING - RH	1	\$ 2,311.00	
135	FRONT WING MIRROR CAP - RH	1	\$ 348.00	
136	AIR CONDITIONER STICKER	1	\$ 34.00	
137	FRONT LITHIUM BATTERY	1	\$ 4,054.00	
138	FRONT LITHIUM BATTERY RETAINING PLATE	1	\$ 369.00	
139	FRONT LITHIUM BATTERY RETAINER - RH	1	\$ 53.00	
140	FRONT LITHIUM BATTERY RETAINER - RH	1	\$ 194.00	
SUB TOTAL SPARE PARTS		:	\$ 19,070.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
141	FRONT HIGH-VOLTAGE BATTERY	1	\$ 173,121.00	
142	WARNING SIGN	1	\$ 47.00	
143	WARNING SIGN DATA TAG	1	\$ 16.00	
144	WARNING SIGN NOTICE	2	\$ 39.00	
145	WARNING SIGN "NO ENTRY" PROHIBITION SIGN	1	\$ 47.00	
146	WARNING SIGN NOTICE	1	\$ 48.00	
147	WARNING SIGN	1	\$ 47.00	
148	WARNING SIGN	1	\$ 47.00	
149	FRONT PROTECTION PLATE	1	\$ 270.00	
150	FRONT COVER - LH / RH	2	\$ 134.00	
151	FRONT COOLANT CONNECTION - LH / RH	2	\$ 133.00	
152	FRONT COOLANT HOSE - LH / RH	2	\$ 92.00	
153	FRONT HIGH-VOLTAGE BATTERY CHARGER	1	\$ 12,684.00	
154	FRONT BRACKET	1	\$ 92.00	
155	FRONT CHARGER RETAINER - LH / RH	2	\$ 34.00	
156	FRONT VOLTAGE CONVERTER	1	\$ 12,609.00	
157	FRONT VOLTAGE CONVERTER	1	\$ 23,663.00	
158	FRONT BRACKET	1	\$ 17.00	
159	FRONT CHARGING SOCKET HIGH-VOLTAGE WIRING SET	1	\$ 1,956.00	
160	FRONT HIGH-VOLTAGE WIRING SET	1	\$ 1,780.00	
SUB TOTAL SPARE PARTS		:	\$ 226,876.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
161	FRONT AND REAR ALUMINIUM RIM	4	\$ 9,648.00	
162	FRONT TYRE PRESSURE SENSOR	1	\$ 403.00	
163	FRONT TYRE PRESSURE CONTROL SYSTEM METAL VALVE	3	\$ 134.00	
164	FRONT ANTI-THEFT WHEEL STUDS	1	\$ 124.00	
165	FRONT SUPPORT FRAME	1	\$ 2,987.00	
166	FRONT STABILIZER LINK - LH / RH	2	\$ 720.00	
167	FRONT ENGINE MOUNTING - LH / RH	2	\$ 368.00	
168	FRONT REINFORCEMENT - LH / RH	2	\$ 94.00	
169	FRONT REINFORCEMENT PLATE - REAR CENTER	1	\$ 472.00	
170	FRONT REINFORCEMENT PLATE - LH / RH	2	\$ 114.00	
171	FRONT AXLE DIFFERENTIAL	1	\$ 6,848.00	
172	FRONT TRANSMISSION FLUID	3	\$ 447.00	
173	FRONT SWIVEL MOUNTING - LH / RH	2	\$ 1,338.00	
174	FRONT WHEEL HUB PLATE - LH / RH	2	\$ 42.00	
175	FRONT WHEEL HUB - LH / RH	2	\$ 997.00	
176	FRONT CABLE HOLDER - RH	1	\$ 26.00	
177	FRONT TRACK CONTROL ARM - LH / RH	2	\$ 3,200.00	
178	FRONT SUSPENSION CONTROL ARM WISHBONE - UPPER	2	\$ 793.00	
179	FRONT DRIVE SHAFT - LH / RH	2	\$ 5,516.00	
180	FRONT UNIVERSAL JOINT GREASE - OUTER	1	\$ 62.00	
SUB TOTAL SPARE PARTS		:	\$ 34,333.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
181	FRONT SHOCK ABSORBERS - LH / RH	2	\$ 2,454.00	
182	FRONT SHOCK ABSORBERS CAP	1	\$ 16.00	
183	FRONT SPRING SUPPORT - LOWER	1	\$ 12.00	
184	FRONT PROTECTIVE SLEEVE	1	\$ 20.00	
185	FRONT COIL SPRING	1	\$ 308.00	
186	FRONT SPRING SUPPORT - LOWER	1	\$ 27.00	
187	FRONT LOWER SEAT INSERT	1	\$ 21.00	
188	FRONT SHOCK ABSORBER RUBBER STOP	1	\$ 21.00	
189	FRONT BEARING PLATE - RH	1	\$ 186.00	
190	FRONT GAS STRUT - LH / RH	2	\$ 5,296.00	
191	FRONT BRAKE COOLING AIR DUCT - LH / RH	2	\$ 88.00	
192	FRONT ANTI-ROLL BAR	1	\$ 341.00	
193	FRONT COUPLING ROD - LH / RH	2	\$ 616.00	
194	FRONT LEVEL SENSOR WITH POLES - LH / RH	2	\$ 1,132.00	
195	FRONT STEERING GEAR TRACK RODS	1	\$ 8,312.00	
196	FRONT BRAKE PADS RED CALIPER	1	\$ 879.00	
197	FRONT DISK BRAKE PADS	1	\$ 1,287.00	
198	FRONT DISC BRAKE - RH	1	\$ 5,515.00	
199	FRONT COVER PLATE - RH	1	\$ 42.00	
200	FRONT SENDER WIRE	1	\$ 83.00	
SUB TOTAL SPARE PARTS		:	\$ 26,656.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
201	FRONT BRAKE HOSE - RH	1	\$ 191.00	
202	FRONT BRAKE HOSE RETAINER - RH	1	\$ 26.00	
203	FRONT SUSPENSION SUB-FRAME	1	\$ 4,756.00	
204	FRONT DRIVE SHAFT GREASED - LH / RH	2	\$ 3,618.00	
205	FRONT WHEEL BEARING HOUSING - LH / RH	2	\$ 2,056.00	
206	FRONT ANGULAR BALL BEARING - LH / RH	2	\$ 448.00	
207	FRONT WHEEL HUB - LH / RH	2	\$ 997.00	
208	FRONT CABLE HOLDER - LH / RH	2	\$ 84.00	
209	FRONT TRACK CONTROL ARM - LH / RH LOWER	2	\$ 1,722.00	
210	FRONT TRACK CONTROL ARM - LH / RH UPPER	2	\$ 508.00	
211	FRONT TRACK CONTROL ARM - LH / RH UPPER	2	\$ 439.00	
212	FRONT TRACK ROD - LH / RH	2	\$ 375.00	
213	FRONT ANTI-ROLL BAR	1	\$ 257.00	
214	FRONT GAS SHOCK ABSORBER - LH / RH	2	\$ 2,454.00	
215	FRONT SPRING CYLINDER - LH / RH	2	\$ 6,112.00	
216	FRONT UNDERBODY TRIM	1	\$ 662.00	
217	FRONT UNDERBODY TRIM SILL - RH	1	\$ 213.00	
218	FRONT UNDERBODY TRIM REAR END	1	\$ 784.00	
219	FRONT STEERING WHEEL AIRBAG UNIT	1	\$ 5,046.00	
220	FRONT PASSENGER AIRBAG UNIT	1	\$ 3,629.00	
SUB TOTAL SPARE PARTS		:	\$ 34,377.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
221	FRONT HEAD AIRBAG UNIT - LH / RH	2	\$ 3,872.00	
222	FRONT KNEE AIRBAG UNIT - LH / RH	2	\$ 3,630.00	
223	FRONT AIRBAG CONTROL UNIT	1	\$ 1,845.00	
224	FRONT AIRBAG CRASH SENSOR - LH / RH	2	\$ 898.00	
225	FRONT SPORTS STEERING WHEEL	1	\$ 3,387.00	
226	FRONT AIR DUCT DASHBOARD	1	\$ 13,594.00	
227	FRONT MOULDED HEADLINER	1	\$ 7,693.00	
228	FRONT GRAB HANDLE - LH / RH	2	\$ 254.00	
229	REAR GRAB HANDLE - LH / RH	2	\$ 254.00	
230	A-PILLAR TRIM - LH / RH	2	\$ 1,478.00	
231	B-PILLAR TRIM - LH / RH UPPER	2	\$ 1,474.00	
232	C-PILLAR TRIM - LH / RH	2	\$ 200.00	
233	C-PILLAR TRIM - LH / RH REAR	2	\$ 580.00	
234	C-PILLAR TRIM - LH / RH	2	\$ 778.00	
235	FRONT THREE POINT AUTOMATIC SEAT BELT - LH / RH	2	\$ 3,818.00	
236	FRONTSEAT BELT HEIGHT ADJUSTER - LH / RH	2	\$ 115.00	
237	DATA TAG	1	\$ 494.00	
238	STATIC MIXER	1	\$ 12.00	
239	2-PACK EPOXY ADHESIVE	1	\$ 122.00	
240	FRONT ALUMINIUM POWDER	1	\$ 637.00	
SUB TOTAL SPARE PARTS		:	\$ 45,135.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 8283 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
241	HARDENER	1	\$	232.00
242	FRONT ALUMINIUM PRIMER	1	\$	233.00
243	CLEANING BLOCK	1	\$	96.00
244	FRONT NO PLATE	S/N	\$	60.00
245	ACRYLIC SEALANT	S/N	\$	180.00
246	CAVITY WAX	S/N	\$	140.00
247	STONE CHIP	S/N	\$	180.00
248	METAL FILLER POWDER	S/N	\$	280.00
249	FRONT WINDSCREEN SEALANT	S/N	\$	200.00
250	RHS FRONT TYRE	S/N	TBC	
251	SUNDRIES		\$	2,000.00
TOTAL SPARE PARTS		:	\$ 577,493.00	
TOTAL LABOUR CHARGES		:	\$ 65,454.00	
GRAND TOTAL		:	\$ 642,947.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT