

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 09 Jan 2023

Preliminary Advice

Vehicle No	: SLF8283Z	Accident Date	: 29/06/2022
Make	: AUDI RS	Policy No.	: 7210114406
Assignment Date	: 22/12/2022	Excess	: S\$2,000.00
Date of Inspection	: 29/11/2022	Est. Duration of Repair	: 0
Inspection At	: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	642,947.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	710,940.00
Pre-Accident Value	:S\$	517,000.00
COE / PARF Rebate	:S\$	172,428.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	538,512.00
Margin for Repair (Pre-Accident Value)	:S\$	344,572.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle recommends Total Loss.