

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22012768/KQY3M4**Date:** 18/04/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002005022
Claimant Vehicle No :	SKT9655R	Insured Vehicle No :	FBT6099Y
Date of Loss:	09/12/2022	Nature of Claim:	TP
		Claim No:	295720

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT9655R	Engine No:	01465985N52B30AF
Make & Model:	BMW 630CI, 3.0 (A)	Chassis No:	WBAEH32050B720893
Reg. Date:	06/09/2005 (Man. Year: 2005)	Odometer:	114124 km
Colour:	Metallic Pearl Grey		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R19	Rear Tyre Size:	275/35R19
Front Left Side:	Michelin 4 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,196.80	0.00	3,196.80	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	565.00	915.00	61.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,676.80	565.00	4,111.80	87.92

INSPECTION

Date of Assignment:	22/12/2022	
Date Inspected:	09/01/2023	Inspected At: TROPICAL TECH AUTOMOBILE SERVICES BLK 5032, ANG MO KIO AVENUE 3 #01-303 IND. PARK 2 SINGAPORE 569535
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts: M1-COUPE	BMW 630CI 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKT9655R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Repair	1,998.00 FL	*- FL	
2	1		*REAR EXHAUST SILENCER BOX (RH)	Repair	1,554.00 FL	*- FL	
					Sub Total (\$\$)	3,552.00	0.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	355.20	0.00
					Total Parts (\$\$)	3,196.80	0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPARE PARTS ITEM }	New	500.00	250.00
2	REMOVE AND REFIT REAR BUMPER, REAR EXHAUST SILENCER BOX (RH) }	New	-	-
3	PANEL BEATING REAR END PANEL, HEAT / WELD / PANEL BEATING / PULL / STRAIGHTEN / ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	-	-
4	TO CHECK AND REFIT REAR TAIL LAMP WIRE HARNESS	New	80.00	15.00
5	UNDER COATING ON VEHICLE	New	200.00	0.00
6	PUTTY / PRIMER APPLICATION, SPRAY PAINTING REAR END PANEL, REAR BUMPER	New	700.00	300.00
Gross Labour Cost (S\$)			1,480.00	565.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >