

SKQ5631B.

TP SMRT.
Hui Rong.

Toyota Altis. 1598 cc.

MROS3REH10452096 9.

- Rear Number Plate } 30(SN) +
Not Nec
- Rear Number Plate Holder } 30(SN) +
- Rear Bumper Distorted. 556.40 ✓
- Rear Bumper Clips Nec 30(SN) ✓
- Rear Bumper Side Holder x 02 Dented 60.4 x L = 120.80 ✓
- Rear Bumper Reflector x 02 RH Smashed 59.8 x 2 = 119.60 ✓ 59.80
- Rear Bumper Reinforcement Dented 399.50 ✓
- Rear Bumper Reinforcement Bracket x 02 Bent 68.2 x L = 136.40 ✓
- Reverse Sensor x 02 Damaged 265.3 x L = 530.60 ✓
- Rear End Panel Distorted 670.10 ✓
- Rear End Panel Top Garnish Debond 185.50 ✓
- Rear End Panel Top Garnish Clips 20(SN) ✓
- Rear End Panel Sealant Nec 60(SN) ✓
- Taillamp x 02 Crushed 394.5 x 2 = 789 ✓
- Taillamp Panel x 02 RH Dented 374.9 x 2 = 749.80 ✓ 374.9
- Taillamp Lower Bracket x 02 RH Crushed 58 x 2 = 116. ✓ 58

SKQ 5631B.

| | | | |
|-----------------|------------------------|---------------|-----------------------------|
| Boothlid | Dented | 781.10 | ✓ |
| Boothlid | Lock | Damaged | 399.50 ✓ |
| Boothlid | Lock | Antenna Guard | 192.20 ✓ |
| Boothlid | Weatherstripe | at | 175.80 ✓ |
| Boothlid | Hinge x 02 | HP NW | $79.6 \times 2 = 159.20$ X |
| Boothlid | Reflector x 02 | HP NW | $379.8 \times 2 = 759.60$ X |
| Toyota Logo | } new | 58.90 | ✓ |
| Corolla Wording | | 39.30 | ✓ |
| Altis Wording | | 43.60 | ✓ |
| Rear Fender RH. | Bubbled | 986.80 | ✓ |
| Rear Fender | Inner Trim Cover RH | HP NW | 338 X |
| Rear Fender | Inner Trim Cover Clips | HP NW | 30(SN) X |
| Rear Fender | Inner Shield RH. | torn | 145.10 ✓ |
| Rear Fender | Inner Shield clips. | new | 20(SN) ✓ |
| Rear Windscreen | Moulding | } new | 89.70 ✓ |
| Rear Windscreen | Sealant | | 60(SN) ✓ |

SKQ5631B.

| | | | |
|------------------|----------------|---------------------|----------|
| Spare Tyre Panel | Buckled | 974.50 | ✓ |
| Spare Tyre Panel | Insulation Pad | 280 (SN) | 200(SN) |
| Spare Tyre Panel | Top Cover | Deland | 292.10 ✓ |
| Spare Tyre | lock screw | Bent | 33.40 ✓ |
| Rees | Exhaust Pipe | Bent | 781.10 ✓ |
| Rees | Exhaust Pipe | Mounting | NE ree |
| | | | 38.90 ✓ |
| Rees | Exhaust Pipe | Gasket | ree |
| | | | 34.50 ✓ |
| Rees | Exhaust Pipe | Heat shield | crumpled |
| | | | 145.80 ✓ |

9054.80

len 25%: 6791.10

S.N: 390

U8T8E OMS

SKW 5631B

| | | | |
|----------------------------------|----------|------------------|---|
| Front Number Plate | Dented | 30(SN) | ✓ |
| Front Number Plate Holder | Deformed | 30(SN) | ✓ |
| Front Bumper | Deformed | 531.10 | ✓ |
| Front Bumper Clips | new | 30(SN) | ✓ |
| Front Bumper Side Holder x 02 | new | 48.1 x 2 = 96.20 | X |
| Front Bumper Reinforcement | Dented | 399.50 | ✓ |
| Front Bumper Sponge | Deformed | 90.10 | ✓ |
| Front Bumper Lower Grille | Deformed | 191.40 | ✓ |
| Front Bumper Under Cover | Deformed | 258.20 | ✓ |
| Front Bumper Under Cover Clips | new | 30(SN) | ✓ |
| Front Bumper Fog Lamp x 02 | } new | 325 x 2 = 650 | X |
| Front Bumper Fog Lamp Cover x 02 | | 38.1 x 2 = 76.20 | X |
| Front Grille | cracked | 381.40 | ✓ |
| Front Grille Clips | new | 20(SN) | ✓ |
| Front Grille Logo | new | 47.90 | ✓ |
| Front Grille Top Cover | new | 80.70 | X |

SKQ5631B.

| | | |
|-----------------------------|------------|------------------------|
| Front Grille Top Cover Caps | 14 New | 20(SN) X |
| Front Brace Panel | Bent | 182.10 ✓ |
| Front Support Panel | Buckled | 989.50 ✓ |
| Horn x 02 | 1 New | 120.7 x 2 = 241.40. X |
| Headlamps x 02 | Cracked | 2999.8 x 2 = 5999.60 ✓ |
| Air Con Condenser | Dented | 1289.30. ✓ |
| Radiator | Dented | 1780.90 ✓ |
| Radiator Fan Cowling | 16P New | 244.50 + |
| Radiator Fan Blade | | 191.10. + |
| Radiator Fan Motor | | 394.40 + |
| Bonnet | Dented | 1058.20. ✓ |
| Bonnet Lock. | New | 135.40. X |
| Coolant | New | 40(SN) ✓ |

13199.20

S-N: 180

Len 25%: 9899.40

SKQ5631B.

Panel Beating
Spray Painting.

~~3400~~ 2400
~~2200~~ 1600
~~150~~ 60

Wiring,

~~220~~ 120.

To apply tuft coat

To remove condensers and }
to top up air con gas }

~~120~~ 60

To remove radiator and }
to top up coolant }

~~120~~ 60

To remove reverse sensor

~~100~~ 50

To remove upholstery.

~~180~~ 80

To transfer bootlid fittings.

~~150~~ 60

To remove rear windscreen.

~~180~~ 120

To remove exhaust pipe.

~~150~~ 80.

4690

total: 21950.50

2/s: 17k

(Repair Limit)

18 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: