

(08/11/13) wef

ASS. REC. BY: *John*

REF:

CC4/LPC22012773/RP93

318F

(08-2024/mv)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKQ 43116

at Workshop m/s

nova

of

Fm yvona

Insured:

LPC

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

63K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No.

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 21K

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Veh No:

SKQ 43116

Yr Regn: 2014 / NOV

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B-M-W 520I

c.c 1997

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

131367

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA5A32000D769516

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/12/22

D.O.I.

03/01/23

Survey held at

nova

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

21/12/2022

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Page : - 1
Veh No : - SKQ4311G
Model : - BMW 520I
Acc Date : - 11/12/2022
Incharge : - ONG
Code : - FY0173

No	Description	Qty	U.Price	Amounts S\$
LIST ITEMS:				
1	FRONT BONNET	1	PC 1650.00	1650.00 ✓
2	FRONT BONNET RUBBER	1	PC 120.00	120.00 ✓
3	FRONT BONNET LOCK ASSY LH	1	PC 280.00	280.00
4	FRONT BONNET LOCK ASSY RH	1	PC 280.00	280.00
5	FRONT SUPPORT PANEL	1	PC 490.00	490.00
6	FRONT SUPPORT PANEL UPPER COVER	1	PC 320.00	320.00 ✓
7	FRONT SUPPORT PANEL V STRUT	2	PC 70.00	140.00
8	FRONT BUMPER	1	PC 1200.00	1200.00 ✓
9	FRONT BUMPER EMBLEM LOGO	1	PC 130.00	130.00 ✓
LIST TOTAL S\$				3420
5% DISCOUNT S\$				5%
				3249

- SPECIAL NET ITEMS :**
- FRONT BONNET INSULATOR CLIPS **NEC**
 - FRONT BUMPER CLIPS **NEC**

1	SET	30.00	30.00 ✓
1	SET	40.00	40.00 ✓
			70.00

SPECIAL NET TOTAL S\$

LABOUR:

TO REMOVE, REPLACE, REPAIR & READJUST FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER & ETC. BACK TO ORIGINAL CONDITIONS

TO SUPPLY PAINT & FURNISHING MATERIAL AT FRONT BONNET, FRONT SUPPORT PANEL & FRONT BUMPER

TO REMOVE, REFIT FRONT RADIATOR, AIR COND CONDENSOR & ETC. TO EFFECT REPLACE OF FRONT SUPPORT PANEL

TO REFILL AIR COND GAS & VACUUM

TO CHECK WIRING & ELECTRICAL SYSTEM

LABOUR TOTAL S\$

Part
Hp 90010288
4 days
4/5
03/01/23 @ 1300
Reg after repair

600.00 ~~280~~ 500
600.00 ~~400~~ 500
80.00 ~~7x~~ 1000
100.00 ~~?~~
80.00 ~~X~~

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Customer's Signature/Co. Stamp

Acknowledged by Repairer

Signature:

Date:

MOVA AUTOMOTIVE PTE LTD

E. & O.E

NON-TAX AMOUNT S
AMOUNT S\$ 5909.50
GST @ 7 % 413.67
AMOUNT DUE S\$ 6323.17

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: **(65) 6476 3333**
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: **(65) 6272 3892**
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

SUPPLEMENTARY

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555


Page : - 1
Veh No : - SKQ4311G
Model : - BMW 520I
Acc Date : - 11/12/2022
Incharge : - ONG

No	Description	Qty	U.Price	Amounts S\$
LIST ITEMS:				
1	FRONT SUPPORT PANEL UPPER COVERING LH <i>cm</i>	1	PC 320.00	320.00
2	FRONT SUPPORT PANEL UPPER COVERING RH <i>cm</i>	1	PC 320.00	320.00
3	FRONT RADIATOR AIR BAFFLE ASSY <i>cm</i>	1	PC 593.00	593.00
LIST TOTAL S\$				1233.00
5% DISCOUNT S\$				-61.65
				1171.35

E. & O.E

NON-TAX AMOUNT S
AMOUNT S\$ 1171.35
GST @ 8 % 93.71
AMOUNT DUE S\$ 1265.06

Customer's Signature/Co. Stamp


MOVA AUTOMOTIVE PTE LTD

3249.00

70.00

1000.00

1171.35

5490.35

20%

4392.28

4/5 - \$4,400 / 4 days