

萬 汽 車 服 務

MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782
 Website: <http://www.millionauto.com> Email: wendy@millionauto.com
 Tel: 6567 0817, 6264 9091 Fax: 6791 4716
 Reg No: 317413/00-K GST Reg No: M90363176A

Vehicle No : GBE3887M

Model : NISSAN NV350

Chassis No : JN1MC2E26Z0005145

Year : 2015

REPAIR ESTIMATE

S/N.	PARTS REPLACEMENT - LIST ITEM	Qty	Unit Price (S) \$	Price (S) \$
1	FRONT BUMPER ASSY	1	\$ 701.30	\$ 701.30
2	FRONT BUMPER BRACKET RH	1	\$ 147.00	\$ 147.00
3	FRONT RADIATOR GRILLE	1	\$ 455.00	\$ 455.00
4	FRONT CORNER PANEL RH	1	\$ 477.80	\$ 477.80
5	FRONT PANEL	1	\$ 1,206.90	\$ 1,206.90
6	HEADLAMP RH	1	\$ 390.80	\$ 390.80
7	SIDE MIRROR RH	1	\$ 321.50	\$ 321.50
8	FRONT DOOR ASSY RH	1	\$ 1,015.60	\$ 1,015.60
9	FRONT DOOR HINGE RH	1	\$ 70.60	\$ 70.60
10	FRONT DOOR CHECKER RH	1	\$ 87.80	\$ 87.80
11	FRONT DOOR WEATHERSTRIP RH	1	\$ 187.40	\$ 187.40
12	FRONT DOOR STEP PANEL GARNISH RH	1	\$ 78.50	\$ 78.50

	\$ 5,140.20
Less 10%	\$ (514.02)
Sub Total :	\$ 4,626.18

PARTS REPLACEMENT -SPECIAL NETT ITEMS

1	FRONT DOOR ROV STICKER	\$ 30.00
2	FRONT BUMPER CLIPS	\$ 30.00
Sub Total:		\$ 60.00

LABOUR AND MISCELLANEOUS CHARGES

1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN AFFECTED AREA AND REPLACE DAMAGE PARTS	\$ 1,100.00
2	TO PUTTY AND SPRAY PAINTING TO AFFECTED AREA	\$ 900.00
3	TO CONDUCT WHEEL ALIGNMENT	\$ 100.00
4	TO APPLY ANTI RUST PROOFING ON AFFECTED AREA	\$ 100.00
5	TO REMOVE AND TRANSFER FRONT DOOR MECHANISM	\$ 100.00
6	TO CHECK LIGHTING SYSTEM	\$ 60.00
7	TO CHECK AND RESET ALL WIRING FUNCTION	\$ 80.00
8	TO REMOVE AND INSTALL FRONT WINDSCREEN	\$ 120.00
Sub Total :		\$ 2,560.00