

AUTO UNITED SG Pte.Ltd

13, Kaki Bukit Road 4 #03-29, Bartley Biz Centre @ Kaki Bukit. S(417807)

Business Reg No: 202209402D

Tel: 9657 2134 / Fax:

E-Mail:

To: Motor Claims Department

TP Liberty
Xiao Chu

Date: 21/12/2022

Vehicle No: SJF6415Y

Model: Honda Fit

Estimated Repair Cost For SJF6415Y (Honda Fit)

QTY	Parts	Amount
1	Rear bumper <i>Distorted</i>	\$ 856.40 485
2	Rear bumper bracket @ SGD 68.20 <i>new</i>	\$ 136.40 +
2	Rear bumper side retainer @ SGD 120.20 <i>new</i>	\$ 240.40 70
1	Rear bumper tow garnish <i>Distorted</i>	\$ 48.00 ✓
1set	Rear bumper clips (set) <i>new</i>	\$ 60.00 30
1	Tailgate panel <i>Distorted</i>	\$ 1,408.40 89.5
1	Tailgate outer garnish <i>new</i>	\$ 256.80 +
1set	Tailgate glass seal / sponge tape <i>new</i>	\$ 120.00 60
1	Tailgate Logo <i>new</i>	\$ 107.40 +
1	Tailgate inner trimboard <i>new</i>	\$ 586.70 285
1set	Tailgate inner trimboard clips (set) <i>new</i>	\$ 60.00 30
1	Tailgate inner lock <i>Distorted</i>	\$ 298.70 ✓
1	Tailgate glass inner seal <i>new</i>	\$ 67.10 40
1	Tailgate weather strip <i>lit</i>	\$ 198.70 ✓
2	Tailgate hinge @ SGD 71.80 <i>new</i>	\$ 143.60 +
2	Tailgate damper @ SGD 295.80 <i>new</i>	\$ 591.60 +
1	Tailgate wiper motor <i>new</i>	\$ 296.40 +
2	Taillamp assy @ SGD 592.80 <i>LH Distorted</i>	\$ 1,185.60 295
1	Rear end panel <i>Distorted</i>	\$ 765.20 495
1	Rear end panel top garnish <i>Distorted</i>	\$ 428.30 185
1set	Rear end panel top garnish clips (set) <i>new</i>	\$ 50.00 20
2	Rear fender inner trim garnish @ SGD 495.30 <i>LH Distorted</i>	\$ 990.60 288
2set	Rear fender inner trim garnish clips (set) <i>new</i>	\$ 80.00 30
1	Rear spare tyre panel <i>new</i>	\$ 937.80 +
1	Rear spare tyre top cover <i>Distorted</i>	\$ 210.30 ✓
1	Rear spare tyre top foam <i>Distorted</i>	\$ 240.70 ✓
1	Exhaust pipe <i>new</i>	\$ 975.80 +
1	Exhaust pipe end muffler <i>new</i>	\$ 198.70 +
2	Exhaust mounting @ SGD 98.50 <i>new</i>	\$ 60.00 +
Parts Sum:		\$ 11,599.60
Parts Less 20% :		\$ 2,319.92
Parts Total:		\$ 9,279.68
Special Nett Items		
1	Tailgate panel sealant <i>new</i>	\$ 80.00 +
1	Tailgate glass sealant <i>new</i>	\$ 80.00 60
1	Rear end panel sealant <i>new</i>	\$ 80.00 60
1	Rear floor panel sealant <i>new</i>	\$ 80.00 +
1set	Reverse sensor w/module <i>new</i>	\$ 280.00 20
1	Rear exhaust pipe gum <i>new</i>	\$ 95.00 +
1set	Rear number plate w/garnish <i>new</i>	\$ 55.00 +
Special Nett Items Total:		\$ 750.00

4214.40

3371.52

300

Labour & Misc Charges

Description	Amount
To Remove, Replace, Re-align & Install affected Rear Damaged Areas (\$350.00 per day)	\$ 1,750.00 120
To Putty, Prep & Re-spray on affected Rear Damaged Areas (\$350.00 per panel)	\$ 2,100.00 80
To Disconnect Front Wire Harness, Electrical Components to Facilitate Repairs	\$ 60.00 30
To Remove & Renew Rear Distance Sensor, To Align & Calibrate Distance Programming	\$ 120.00 50
To Remove & Install Rear Tailgate glass to Facilitate Repairs	\$ 150.00 120
To Remove & Transfer Rear Tailgate Components to Facilitate Repairs	\$ 150.00 60
To Remove & Transfer Spare Tyre Components to Facilitate Repairs	\$ 150.00 60
To Re-programme & Re-set ECU Diagnostic	\$ 280.00 +
To Apply Undercoating on the Affected Damaged Areas	\$ 250.00 80
Labour Charges Total:	\$ 5,010.00

Parts Total: \$ 9,279.68
Special Nett Items Total: \$ 750.00
Labour Charges Total: \$ 5,010.00
Total Cost Of Repair: \$ **15,039.68**
 (Non-Inclusive of GST)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/S 22/12/22

07 Days

total: 5871.52

L/S: 4.2K.

(Nett Value).