

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MICHAEL LEE THIAM CHYE
 BLK 707 JURONG WEST ST 71 #09-48
 SINGAPORE 640707

Contact : 97927007

TP Chin
Xiao Chen.

TAX INVOICE

Repair Code : CLM17533
 Date in : 21/12/2022
 Vehicle Num. : SLW5126A
 Model : MAZDA3 SEDAN 1.5 AT EU6
 Chassis/Eng# : JM6BN22A8H0161866/P520454173

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR CLEANER BOX ASSY <i>checked</i>	1	226.00	✓ 226.00
AIRBAG ECU <i>{ Activated</i>	1	1147.00	✓ 1,147.00
AIRBAG IMPACT SENSOR	1	132.00	✓ 132.00
AIRCON CONDENSER <i>Distorted.</i>	1	1116.00	✓ 1,116.00
AIRCON CONDENSER ALUMINIUM PIPE <i>{ Bent.</i>	1	463.00	✓ 463.00
AIRCON CONDENSER DISCHARGE PIPE	1	248.00	✓ 248.00
AIRCON CONDENSER SUCTION PIPE <i>Bent.</i>	1	345.00	✓ 345.00
BATTERY BRACKET <i>checked.</i>	1	49.00	✓ 49.00
BATTERY COVER <i>new</i>	1	63.00	x 63.00
CENTER PILLAR GARNISH L/R <i>new</i>	2	158.00	x. 316.00
ENGINE MOUNTING (REAR) <i>Damaged</i>	1	330.00	✓ 330.00
FRONT ABS PUMP <i>Damaged</i>	1	1731.00	✓ 1,731.00
FRONT ABS SENSOR L/R <i>new</i>	2	148.00	x. 296.00
FRONT AIR DUCT <i>Deformed</i>	1	97.70	✓ 97.70
FRONT BONNET <i>Distorted</i>	1	1120.00	✓ 1,120.00
FRONT BONNET HINGES L/R <i>Bent.</i>	2	45.00	✓ 90.00
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	25.00	x 50.00
FRONT BONNET INNER TOP RUBBER SEAL <i>ut</i>	1	66.00	✓ 66.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MICHAEL LEE THIAM CHYE
 BLK 707 JURONG WEST ST 71 #09-48
 SINGAPORE 640707

Contact : 97927007

TAX INVOICE

Repair Code : CLM17533
 Date in : 21/12/2022
 Vehicle Num. : SLW5126A
 Model : MAZDA3 SEDAN 1.5 AT EU6
 Chassis/Eng# : JM6BN22A8H0161866/P520454173

FRONT BONNET MECHANISM LOCK	<i>Damaged</i>	1	207.00	✓	207.00
FRONT BONNET MECHANISM LOCK COVER	<i>Damaged</i>	1	42.00	✓	42.00
FRONT BRACE PANEL	<i>Bent</i>	1	45.00	✓	45.00
FRONT BUMPER	<i>Distorted</i>	1	866.00	✓	866.00
FRONT BUMPER INNER FOGLAMP BRACKET L/R	<i>crckd.</i>	2	43.00	✓	86.00
FRONT BUMPER LOWER GRILLE SIDE COVER L/R	<i>Missing</i>	2	36.00	✓	72.00
FRONT BUMPER NUMBER PLATE GARNISH	<i>crckd</i>	1	85.00	✓	85.00
FRONT BUMPER REINFORCEMENT	<i>Distorted</i>	1	502.00	✓	502.00
FRONT BUMPER REINFORCEMENT OUTER COVER	<i>smashed.</i>	1	265.00	✓	265.00
FRONT BUMPER SIDE RETAINER L/R	<i>Damaged</i>	2	19.70	✓	39.40
FRONT BUMPER SIGNAL LAMP GARNISH L/R	<i>ut</i>	2	53.00	✓	106.00
FRONT BUMPER SIGNAL LAMP L/R	<i>crcked</i>	2	147.00	✓	294.00
FRONT BUMPER TOP BRACKET	<i>Distorted</i>	1	95.60	✓	95.60
FRONT BUMPER TOP COVER	<i>Distorted</i>	1	355.00	✓	355.00
FRONT BUMPER TOP COVER RIVET	<i>new</i>	4	5.90	✓	23.60
FRONT BUMPER TOW HOOK COVER	<i>Distorted</i>	1	18.00	✓	18.00
FRONT BUMPER UNDER COVER	<i>tom</i>	1	95.00	✓	95.00
FRONT DASHBOARD	<i>tom</i>	1	1429.00	✓	1,429.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MICHAEL LEE THIAM CHYE
 BLK 707 JURONG WEST ST 71 #09-48
 SINGAPORE 640707

Contact : 97927007

TAX INVOICE

Repair Code : CLM17533

Date in : 21/12/2022

Vehicle Num. : SLW5126A

Model : MAZDA3 SEDAN 1.5 AT EU6

Chassis/Eng# : JM6BN22A8H0161866/P520454173

FRONT ECU CONTROL UNIT	<i>cracked</i>	1	505.00	✓	505.00
FRONT ENGINE CROSS MEMBER	<i>Best.</i>	1	1880.00	✓	1,880.00
FRONT ENGINE CROSS MEMBER LOWER GARNISH	<i>Delud</i>	1	87.90	✓	87.90
FRONT ENGINE CROSS MEMBER SIDE BRACKET L/R	<i>Damaged</i>	2	105.00	✓	210.00
FRONT ENGINE INTAKE MANIFOLD	<i>cracked</i>	1	849.00	✓	849.00
FRONT ENGINE UNDER COVER	<i>tom</i>	1	286.00	✓	286.00
FRONT FENDER INNER BRACKET L/R	<i>Best.</i>	2	58.00	✓	116.00
FRONT FENDER INNER SHIELD L/R	<i>tom</i>	2	101.00	✓	202.00
FRONT FENDER L/R	<i>Distorted</i>	2	350.00	✓	700.00
FRONT GRILLE	<i>Distorted</i>	1	145.00	✓	145.00
FRONT GRILLE 'LOGO' EMBLEM	<i>Distorted</i>	1	61.00	✓	61.00
FRONT GRILLE CHROME MOULDING L/R	<i>Distorted</i>	2	191.00	✓	382.00
FRONT GRILLE INNER BRACKET L/R		2	70.00	✓	140.00
FRONT GRILLE SIDE COVER L/R	<i>Missing</i>	2	80.00	✓	160.00
FRONT HEADLAMP CLIPS L/R	<i>new</i>	2	10.50	✓	21.00
FRONT HEADLAMP L/R	<i>cracked</i>	2	1070.00	✓	2,140.00
FRONT HORN L/R	<i>HEM</i>	2	145.00	✗	290.00
FRONT KNUCKLE ARM BEARING L/R	<i>RH Damped</i>	2	568.00		1,136.00

568.

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@m51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MICHAEL LEE THIAM CHYE
 BLK 707 JURONG WEST ST 71 #09-48
 SINGAPORE 640707

Contact : 97927007

TAX INVOICE

Repair Code : CLM17533

Date in : 21/12/2022

Vehicle Num. : SLW5126A

Model : MAZDA3 SEDAN 1.5 AT EU6

Chassis/Eng# : JM6BN22A8H0161866/P520454173

FRONT KNUCKLE ARM L/R	RH Damaged	2	402.00	402	804.00
FRONT LH BODY MEMBER	Repair	1	1700.00	X	1,700.00
FRONT LH ENGINE MOUNTING	Damaged	1	351.00	✓	351.00
FRONT LOWER ARM L/R	RH Bent	2	508.00	508	1,016.00
FRONT PASSENGER AIRBAG	Activated	1	1169.00	✓	1,169.00
FRONT RH ENGINE MOUNTING	Damaged	1	421.00	✓	421.00
FRONT SEAT BELT L/R	Activated	2	1023.00	✓	2,046.00
FRONT SHOCK ABSORBER L/R	Bent RH	2	360.00	360	720.00
FRONT SHOCK ABSORBER TOP MOUNTING L/R	XRC new	2	95.00	X	190.00
FRONT SPORT RIM L/R	Wf	2	1162.00	1500/500	2,324.00
FRONT STABILIZER LINK L/R	RH Damaged	2	64.70	64.70	129.40
FRONT STEERING AIRBAG	} Activated	1	1082.00	✓	1,082.00
FRONT STEERING CLOCK SPRING SENSOR		1	192.00	✓	192.00
FRONT SUPPORT PANEL	Bent	1	493.00	✓	493.00
FRONT SUPPORT TOP PANEL	Damaged	1	147.00	✓	147.00
FRONT TIE ROD END L/R	XRC new	2	155.00	X	310.00
FRONT WASHER TANK	Distorted	1	113.00	✓	113.00
FRONT WASHER TANK MOTOR	XRC new	1	72.00	X	72.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MICHAEL LEE THIAM CHYE
 BLK 707 JURONG WEST ST 71 #09-48
 SINGAPORE 640707

Contact : 97927007

TAX INVOICE

Repair Code : CLM17533
 Date in : 21/12/2022
 Vehicle Num. : SLW5126A
 Model : MAZDA3 SEDAN 1.5 AT EU6
 Chassis/Eng# : JM6BN22A8H0161866/P520454173

FRONT WASHER TANK NECK	<i>Demgd</i>	1	69.00	✓	69.00
FRONT WHEEL HOUSING L/R	<i>Repair</i>	2	1690.00	✗	3,380.00
FRONT WIPER GARNISH L/R	<i>At</i>	2	186.00	✓	372.00
RADIATOR	<i>Distorted</i>	1	1117.00	✓	1,117.00
RADIATOR DEFLECTOR	<i>Distorted</i>	1	165.00	✓	165.00
RADIATOR FAN COWLING ASSY	<i>Painted</i>	1	1423.00	✓	1,423.00
RADIATOR LOWER HOSE	<i>new</i>	1	73.00	+	73.00
RADIATOR SIDE GUIDE LOWER L/R	<i>Distorted</i>	2	73.00	✓	146.00
RADIATOR SIDE GUIDE TOP L/R	<i>Distorted</i>	2	68.00	✓	136.00
RADIATOR SPARE TANK	<i>Cracked</i>	1	68.00	✓	68.00
RADIATOR TOP HOSE	<i>new</i>	1	65.00	+	65.00
RESONATOR	<i>Cracked</i>	1	192.70	✓	192.70
Subtotal before discount					42,308.30
Percentage discount 20%					8,461.66
Sub-total 1					33,846.64
BATTERY	<i>new</i>	1	380.00	✗	380.00
FRONT 205/60R16 TYRE L/R	<i>new</i>	2	450.00	✗	900.00
FRONT BUMPER CLIPS - SET	<i>new</i>	1	60.00	30	60.00

31125.90
 24900.72
 S.N: 1500

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MICHAEL LEE THIAM CHYE
 BLK 707 JURONG WEST ST 71 #09-48
 SINGAPORE 640707

Contact : 97927007

TAX INVOICE

Repair Code : CLM17533
 Date in : 21/12/2022
 Vehicle Num. : SLW5126A
 Model : MAZDA3 SEDAN 1.5 AT EU6
 Chassis/Eng# : JM6BN22A8H0161866/P520454173

FRONT BUMPER NUMBER PLATE	<i>Distohd</i>	1	25.00	<i>✓</i>	25.00
FRONT BUMPER NUMBER PLATE HOLDER	<i>Dang d.</i>	1	50.00	<i>30</i>	50.00
FRONT FENDER INNER SHIELD CLIPS L/R - SET	<i>new</i>	2	50.00	<i>60</i>	100.00
FRONT WIPER GARNISH CLIPS L/R - SET	<i>new</i>	2	30.00	<i>✓</i>	60.00
RADIATOR COOLANT	<i>new</i>	1	80.00	<i>40</i>	80.00
Subtotal before discount					1,655.00
Percentage discount 0%					0.00
Sub-total 2					1,655.00
Parts-total					35,501.64

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	<i>120</i>	140.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	<i>30</i>	80.00
To remove, change air bag, air-bag sensor, air-bag wire and resetting system.	<i>250</i>	350.00
To reset system after repair works	<i>180</i>	400.00
To remove, install engine with transmission. (to FR)	<i>350</i>	400.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	<i>350</i>	450.00
To road test driving, check and resetting wheel alignments system.	<i>80</i>	100.00
To remove, change dashboard fascia and transfer where necessary.	<i>220</i>	400.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R), front bumper and front doors (L/R).	<i>1400</i>	1,600.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MICHAEL LEE THIAM CHYE
BLK 707 JURONG WEST ST 71 #09-48
SINGAPORE 640707

Contact : 97927007

TAX INVOICE

Repair Code : CLM17533
Date in : 21/12/2022
Vehicle Num. : SLW5126A
Model : MAZDA3 SEDAN 1.5 AT EU6
Chassis/Eng# : JM6BN22A8H0161866/P520454173

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
To apply anti-rust chemical on repaired and replaced panel.

	180	2,400.00
	120.	150.00
Labour Total	4800	6,470.00
Parts & Labour Total		41,971.64

*** This is a computer-generated document which requires no signature.***

page 7

Admin Lj
h/s 22/12/22
18 Days.

total: 31545.72

h/s: 25.2K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: