

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 10 Jan 2023

Preliminary Advice

Vehicle No	: SML7704P	Accident Date	: 20/12/2022
Make	: OPEL INSIGNIA GRANDSPORT B16DTH	Policy No.	: SP2002451400
Assignment Date	: 22/12/2022	Excess	: S\$2,000.00
Date of Inspection	: 27/12/2022 (Desktop Survey)	Est. Duration of Repair	: 05 days
Inspection At	: MUNICH AUTOCARE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,376.40	(Est \$12,238.90 + Supp \$137.50)
Revised Amount	:S\$	5,452.80	
Check Items (Estimated)	:S\$	3,942.80	
Total	:S\$	9,395.60	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	48,677.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,323.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on Supplementary.
Part by Part repair. According to the repairer, there are no second-hand parts available.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.