

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)
 60 Jalan Lam Huat, #07-43
 Singapore 737869
 Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	20/12/2022
Vehicle Reg. No.:	SML7704P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 Turbo (A)	Vehicle Reg. Date:	03/06/2019
Vehicle Colour:	Black		
Engine No:	A2183328JSUX0428	Chassis No:	W0VZM6EF0K103500
Odometer:	170588 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 7

Present Location: **MUNICH AUTOCARE PTE LTD (HQ)**

COST OF CLAIMS		Amount
Parts		9,634.90
Miscellaneous Items		164.00
Labour		2,440.00
Paintwork Labour		0.00
Towing		0.00
Calculated Gross Total (S\$)		12,238.90
- Excess (S\$)		2,000.00
(S\$)		10,238.90
+ GST 7.00% (S\$)		716.72
Nett Amount (S\$)		10,955.62

This claim is handled by: LIM JIA HAW

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Dec 2022)
 Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Munich Autocare Pte Ltd/SML7704P/22/12/2022 11:39
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39214206	*FRONT BONNET	0.00	0.00	*1,705.00 F
2	1	39118540	*FRONT BONNET LOCK	0.00	0.00	*43.00 F
3	1	39143307	*FRONT BONNET LOCK BRACKET	0.00	0.00	*127.00 F
4	1	39126608	*FRONT BONNET HINGE LH	0.00	0.00	*133.00 F
5	1	39126609	*FRONT BONNET HINGE RH	0.00	0.00	*133.00 F
6	1	39150008	*FRONT BONNET DAMPER LH	0.00	0.00	*125.00 F
7	1	39150008	*FRONT BONNET DAMPER RH	0.00	0.00	*125.00 F
8	1	39107929	*FRONT RADIATOR GRILLE	0.00	0.00	*299.00 F
9	1	13491196	*FRONT RADIATOR GRILLE MOULDING (CHROME)	0.00	0.00	*274.00 F
10	1	13491190	*FRONT RADIATOR GRILLE MOULDING LH (CHROME)	0.00	0.00	*131.00 F
11	1	13491191	*FRONT RADIATOR GRILLE MOULDING RH (CHROME)	0.00	0.00	*131.00 F
12	1	39197502	*FRONT BUMPER UPPER INNER GARNISH	0.00	0.00	*141.00 F
13	1	39114984	*FRONT RADIATOR TOP GARNISH	0.00	0.00	*40.00 F
14	1	13491204	*FRONT LOGO EMBLEM	0.00	0.00	*75.00 F
15	1	39159651	*FRONT BUMPER	0.00	0.00	*1,158.00 F
16	1	39098178	*FRONT BUMPER SPONGE	0.00	0.00	*107.00 F
17	1	39117745	*FRONT BUMPER REINFORCEMENT	0.00	0.00	*459.00 F
18	1	39108221	*FRONT BUMPER LOWER GRILLE	0.00	0.00	*120.00 F
19	1	39108219	*FRONT BUMPER LOWER LIP GARNISH LH	0.00	0.00	*62.00 F
20	1	39108220	*FRONT BUMPER LOWER LIP GARNISH RH	0.00	0.00	*62.00 F
21	1	13491269	*INSERT, CHROME, FRONT FOGLAMP LH	0.00	0.00	*537.00 F
22	1	13491272	*INSERT, CHROME, FRONT FOGLAMP RH	0.00	0.00	*537.00 F
23	1	39210100	*FRONT HEADLAMP RH	0.00	0.00	*822.00 F
24	1	13491383	*HEADLAMP BRACKET RH	0.00	0.00	*47.00 F
25	1	39077621	*FRONT UPPER SUPPORT PANEL	0.00	0.00	*170.00 F
26	1	39143306	*FRONT SUPPORT PANEL	0.00	0.00	*258.00 F
27	3	95515167	*FRONT PARKING SENSOR	0.00	0.00	*615.00 F
28	1		*FRONT BUMPER WIRING HARDNESS	0.00	0.00	*323.00 F

F=Franchise part.

Sub Total (S\$) 8,759.00
 + Margin on L,N Items 10.00% (S\$) 875.90
 Total Parts (S\$) 9,634.90

Munich Autocare Pte Ltd/SML7704P/22/12/2022 11:39. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	7	FRONT BUMPER CLIP	49.00 Some
2	1	LICENSE PLATE WITH CASING	45.00 ht
3	10	RADIATOR TOP COVER CLIP SET	70.00 740x14
Sub Total (S\$)			164.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISMANTLE & REFIX FRONT ACCIDENT POTION, FRONT BONNET, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, FRONT SUPPORT PANEL AND ETC	New	1,200.00 500
2	TO DISMANTLE & RENEW FRONT PARKING SENSOR	New	120.00 40
3	TO CHECK ELECTRIC WIRING FOR PROPER FUNCTION INCLUDING ADJUST OF HEADLAMP	New	120.00 50
4	TO RESPRAY FRONT ACCIDENT POTION, FRONT BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, AND ETC	New	1,000.00 500
Gross Labour Cost (S\$)			2,440.00

Munich Autocare Pte Ltd/SML7704P/22/12/2022 11:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97495749/62563561
Not Authorise, E\$2000
27/12/22 Present
Resurvey before paint
4-5 days.
taufik@khanato.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

(SUPPLEMENTARY)INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	20/12/2022
Vehicle Reg. No.:	SML7704P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 TURBO (A)	Vehicle Reg. Date:	03/06/2019
Vehicle Colour:	BLACK		
Engine No:	A2183328JSUX0428	Chassis No:	W0VZM6EF0K1035006
Odometer:	170588 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	137.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	137.50
+ GST 7.00% (S\$)	9.63
Nett Amount (S\$)	147.13
+ Previous Estimates (S\$)	10,955.62
Claim Total (S\$)	11,102.75

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jan 2023)

Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SML7704P/06/01/2023 09:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39114984	*TOP RADIATOR GRILLE COVER	0.00	0.00	*30.00 F
2	1	84262659	*AIR DUCT	0.00	0.00	*95.00 F
F=Franchise part.						
Sub Total (S\$)						125.00
+ Margin on L,N Items 10.00% (S\$)						12.50
Total Parts (S\$)						137.50

Munich Autocare Pte Ltd/SML7704P/06/01/2023 09:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Munich Autocare Pte Ltd/SML7704P/06/01/2023 09:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >