LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 27 Dec 2022

Preliminary Advice

Vehicle No: SML7704PAccident Date: 20/12/2022Make: OPEL INSIGNIA GRANDSPORT B16DTHPolicy No.: SP2002451400Assignment Date: 22/12/2022Excess: S\$2,000.00Date of Inspection: 27/12/2022 (Desktop Survey)Est. Duration of Repair: 05 days

Inspection At : MUNICH AUTOCARE PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,238.90
Revised Amount	:S\$	5,315.30
Check Items (Estimated)	:S\$	3,942.80
Total	:S\$	9,258.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

 Pre-Accident Value
 :S\$ 96,000.00

 COE / PARF Rebate
 :S\$ 48,677.00

Salvage Value :S\$

Margin for Repair :S\$ 47,323.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Part by Part repair. According to the repairer, there are no second-hand parts available.

 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency

check, part prices and labour cost.