

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI22012791/KNY3E2**Date:** 13/03/2023REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG22009143
<b>Claimant Vehicle No :</b>	SJT8441J	<b>Insured Vehicle No :</b>	GBF1883G
Date of Loss:	20/12/2022	Nature of Claim:	TP
		Claim No:	CDMCG22002754

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJT8441J</b>	Engine No:	LEB5947330
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU31247313
Reg. Date:	25/08/2017 (Man. Year: 2017)	Odometer:	137837 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 9 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,886.40	5,368.84	2,517.56	31.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	2,010.00	510.00	20.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>10,406.40</b>	<b>7,378.84</b>	<b>3,027.56</b>	<b>29.09</b>

INSPECTION

Date of Assignment:	22/12/2022		
Date Inspected:	23/12/2022	Inspected At:	RC Auto 160 Sin Ming Ddrive #06-20 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	6.0 days		

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Feb 2023)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJT8441J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,040.00 F	*953.00 FL
2	1		*REAR BOOTLID RUBBER	Distorted/Dented	110.00 F	*110.00 FL
3	1		*REAR BOOTLID OUTER GANISH	Cracked	280.00 F	*280.00 FL
4	4		*REAR WINDSCREEN GLASS RUBBER SEAL	Necessary	128.00 F	*128.00 FL
5	1		*REAR WINDSCREEN	Shattered	900.80 F	*900.80 FL
6	1		*REAR BOOTLID INNER GANISH	Mtg Cracked	460.00 F	*270.00 FL
7	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*REAR PANEL	Bent	460.60 F	*460.60 FL
9	2		*REAR LAMP	Cracked	980.00 F	*980.00 FL
10	2		*REAR BOOTLID REFLECTOR	Cracked	840.00 F	*826.40 FL
11	1		*REAR PANEL GANISH	Dented	116.00 F	*116.00 FL
12	1		*VEZEL LOGO EMBLEM	Necessary	80.00 F	*80.00 FL
13	1		*HONDA LOGO EMBLEM	Necessary	55.00 F	*55.00 FL
14	1		*REAR BOOTLID LOCK	Dented	210.00 F	*210.00 FL
15	2		*REAR BUMPER SIDE	Serviceable	596.00 F	*- FL
16	2		*REAR BUMPER REFLECTOR	Serviceable	120.00 F	*- FL
17	2		*REAR FENDER INNER GANISH	Dented/Deformed	760.00 F	*760.00 FL
18	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
19	1		*SET CAR RECORDER (2 CHANNEL)(50%)	Missing	450.00 FS	*225.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,886.40</b>	<b>6,604.80</b>
<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	0.00	1,235.96
<b>Total Parts (S\$)</b>	<b>7,886.40</b>	<b>5,368.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO INSTALL WINDSCREEN	New	150.00	120.00
2	TO REMOVE HYBRID BATTERY TO FACILITATE REPAIR	New	250.00	150.00
3	SPRAY PAINTING	New	800.00	800.00
4	ANTI RUST	New	100.00	60.00
5	TO TRANSFER TAILGATE ACCESSORIES	New	80.00	60.00
6	TO REPLACE ALL THE ABOVE PARTS	New	1,000.00	700.00
7	TO RESET AND CHECK ALL WIRING WORKS	New	40.00	20.00
8	TO REMOVE REAR SEATS AND UPHOLSTERY	New	100.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>2,520.00</b>	<b>2,010.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >