

Vehicle Damage Assessment Report for [SJT8441J]

Estimate Created: 10/03/2023 12:48 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 10/03/2023 13:18 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Vezel
Engine Type			
License Plate Number	SJT8441J	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$7,378.84 WITH 6 WORKING
DAYS.

Insurlogic 4 (10/03/2023 13:17)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
rear bootlid		1	953.00	-20.00 %	762.40
rear bootlid rubber		1	110.00	-20.00 %	88.00
rear bootlid outer garnish		1	280.00	-20.00 %	224.00
rear windscreen glass rubber seal		4	32.00	-20.00 %	102.40
rear windscreen glass		1	900.80	-20.00 %	720.64
rear bootlid inner garnish		1	270.00	-20.00 %	216.00
rear bumper clips		10	5.00	-20.00 %	40.00
rear panel		1	460.60	-20.00 %	368.48
rear lamp		2	490.00	-20.00 %	784.00
rear bootlid reflector		2	413.20	-20.00 %	661.12
rear panel garnish		1	116.00	-20.00 %	92.80
vezel logo emblem		1	80.00	-20.00 %	64.00
honda logo emblem		1	55.00	-20.00 %	44.00
rear bootlid lock		1	210.00	-20.00 %	168.00
rear fender inner garnish		2	380.00	-20.00 %	608.00

Parts Subtotal 4,943.84

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
reverse sensor		1.0	200.00	0.00 %	200.00
car recorder		1.0	450.00	-50.00 %	225.00

Materials Subtotal 425.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To install rear windscreen glass	RnR	120.00	0.00 %	120.00
To remove hybrid battery to facilitate repair	RnR	150.00	0.00 %	150.00
Anti rush	RnR	60.00	0.00 %	60.00
To transfer tailgate lid	RnR	60.00	0.00 %	60.00
Labour to replace all the above parts	RnR	700.00	0.00 %	700.00
To reset and check all wiring works	RnR	20.00	0.00 %	20.00
To remove rear seat and upholstery	RnR	100.00	0.00 %	100.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	800.00	0.00 %	800.00
Labor Rate	S\$ 50 / Hour		General Labor Subtotal	1,210.00
			Paint Labor Subtotal	800.00
			Labor Subtotal	2,010.00

Summary

Repair Cost	7,378.84
Discount(0 %)	(0.00)
	7,378.84
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	7,378.84