

ASS. REC. BY:

REF:

C72/220127931kg

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 92k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 06 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNA 3717AYr Regn: 07.17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mini Cooperc.c. 1998Colour: M.P. Pink

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 66268

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: WMWXS720602E 46740Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 205/40R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 13/12/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/12/21 Sun @ 8500 Lined to 5967.81, 41%

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation

S - RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format:

Lump Sum / I.B.F. (\$)

MER-TP
8500

TOTAL

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 055887
Date calculated: 21/12/2022 5:00 PM

Full Report
Registration: SNA3717A
Printed: 21/12/2022 5:01 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	13/12/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MINI
Model:	MINI F55
Sub Model:	COOPER S
Model Sheet Number:	19 32 03
Registration:	SNA3717A
VIN number:	WMWXS720602E46740
Odometer:	

Model Specs

FROM 01.2017	CHROMLINE INTERIOR	AUTO AIR CON	WINDSCREEN RAIN SENS
REARVIEW CAMERA	REFRIGERANT R-1234YF	COMFORT ACCESS SYST	TELESERVICE
ELEC/HEATED D/MIRROR	RADIO VISUAL BOOST	DAB TUNER	LED HEADLAMP
INDICATORS WHITE	LED FOG LAMPS	HEIGHT ADJ PASS SEAT	SEAT CVR LEATH CROSS
HEATED FRONT SEATS	SPORT SEATS	JCW EXTERIOR	FRT FOLDING ARMREST
PEDESTRIAN PROTECT	MINI EXCITEMENT PACK	ANTI-THEFT ALARM	INTERIOR LAMP PACK
ON-BOARD COMPUTER	MINI DRIVING MODES	STORAGE PACKAGE	HEAD-UP DISPLAY
RR PARK DIST CONTROL	1998CCM 141KW	LEATHER STRG WHEEL	MULTI FUNC S-WHEEL
SPEED CRUISE ONTROL	O2 VOLUME	TYRES 205/40 WR 18	6-SPEED AUTO GEARBOX
TYRE W/FLAT RUNNING	WHEELS 7J X 18 ALLOY	JCW AERODYNAMIC KIT	WHEEL BOLT LOCK
EDC DAMPER CONTROL	TYRE PRESSURE SENSOR	ROOF/MIRROR BLACK	CTR BONNET STRIP BLK
REAR SPOILER	TWO COAT METALLIC	PREPARE OFF VEHICLE	

NOT AUTHORIZED
1/12/22
Repairing After Paint
6 days

Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
32 00 590	ELECTRONIC TRACK AND WHEEL ALIGNMENT (WITHOUT: ADJUSTMENT)		16.0	56.00
51 11 656	R + R FRONT BUMPER		6.0	21.00
NO NUMBER	R + R LEFT FRONT SPOILER		3.0	10.50
51 71 947	R + R LEFT SILL RAIL		6.0	21.00
41 35 550)	RENEW L/F SIDE PANEL		6.0	21.00
41 51 580	R + R LEFT FRONT DOOR		5.0	17.50
41 52 580	R + R LEFT REAR DOOR		3.0	10.50

Code	Description	WU	Price SGD
41 51 501	RENEW L/F DOOR (REMOVED)	26.0	91.00
41 52 501	RENEW L/R DOOR (REMOVED)	22.0	77.00
NO NUMBER	RENEW L/R LOWER DOOR HINGE	14.0	49.00
NO NUMBER	RENEW L/R UPPER DOOR HINGE	14.0	49.00
51 13 605	R + R L/R WHEELARCH TRIM	2.0	7.00
36 10 800)	R + R LEFT FRONT WHEEL	1.0	3.50
34 11 519)	R + R L/F BRAKE CALIPER (WHEEL REMOVED)	1.0	3.50
31 21 580)	R + R L/F WHEEL HUB (FRONT WHEEL REMOVED)	4.0	14.00
31 21 504)	R + R L/F STEERING KNUCKLE	4.0	14.00
36 10 800)	R + R LEFT REAR WHEEL	1.0	3.50
33 53 565)	R + R LEFT REAR COIL SPRING	3.0	10.50
34 21 750)	R + R L/R BRAKE CALIPER	1.0	3.50
33 32 501)	R + R L/REAR TRAILING LINK	5.0	17.50
33 32 621	RENEW L/R TRAILING ARM (REMOVED) INCLUDES: BEARING BRKT AND WHEEL BEARING REMOVE AND REFIT	6.0	21.00
36 11 512	R + R L/F WHEEL/TYRE	6.0	21.00
36 11 512	R + R L/R WHEEL/TYRE	6.0	21.00
41 51 504	ADJUST L/F DOOR	2.0	7.00
41 52 504	ADJUST L/R DOOR	2.0	7.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		12.60	151.0
Alignment			
Measuring Work		1.30	16.0
Total of Labour			584.50

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	L/F WING NEW PART PAINTING	9.0
	LEFT FRONT DOOR NEW PART PAINTING	15.0
	L/R DOOR NEW PART PAINTING	13.0
	L/DOOR MIRROR COVER NEW PART PAINT K1R	4.0
	LEFT SILL MOULDING NEW PART PAINT K1G	9.0

Paint Material Per Part

Code	Description	Price SGD
0741	L/F WING NEW PART PAINTING	13.42
1481	LEFT FRONT DOOR NEW PART PAINTING	40.76
1781	L/R DOOR NEW PART PAINTING	30.44
1745	L/DOOR MIRROR COVER NEW PART PAINT K1R	5.90
2171	LEFT SILL MOULDING NEW PART PAINT K1G	18.14

Labour Cost - Paint

Factor

42.00 SGD/h

Time Paint

Hrs

WU

Price SGD

Preparation Main Work Metal

2.50

50.0

105.00

Preparation Comp. Work Plastic

0.80

8.0

33.60

Total

10 WU/h

8.30

83.0

348.60

Total

12 WU/h

8.30

99.6

348.60

Material Cost - Paint

Price SGD

New Part Painting

84.62

New Part Painting - Plastic K1R

5.90

New Part Painting - Plastic K1G

18.14

Material-constant Metal Preparation

28.60

Material-constant Plastic

12.70

Total

149.96

Spare Parts

				prices as at 2022-12-15	
Code	Description	Part Number	Part Source		Price SGD
0391	L/F SPOILER	51 11 7 360 743	Original	CM	110.00 ✓
0741	L/F WING	41 00 7 374 521	Original	R	550.00 X
0787	L/F WHEELARCH TRIM	51 77 7 376 011	Original	nd/Gt	220.00 ✓
1481	LEFT FRONT DOOR	41 00 7 327 445	Original	Ry	1,250.00 ✓
1487	L/F UPPER DOOR HINGE	41 51 7 284 533	Original	R	90.00 X
1495	L/F LOWER DOOR HINGE	41 51 7 284 535	Original	R	90.00 X
1505	L/F DOOR CHECK	51 21 7 328 595	Original	Rn	110.00 X
1513	L/LWR DOOR SEAL	51 76 7 322 508	Original	Rn	80.00 ✓
1547	L/WINDOW REGULATOR	51 33 7 409 357	Original	Ry	380.00 ✓
1551	L/F WINDOW MOTOR	67 62 7 405 701	Original	Tn	360.00 ✓
1565	L/OUTER HANDLE	51 21 9 450 311	Original	R	190.00 X
1577	L/F DOOR LOCK	51 21 7 281 937	Original	nd	350.00 ✓
1599	L/A-PILLAR SEAL	51 76 7 322 455	Original	DIS	190.00 ✓
1711	L/F DOOR TRIM	51 41 7 429 341	Original	Rn	750.00 X
1745	L/DOOR MIRROR COVER	51 14 2 354 925	Original	DIS	130.00 ✓
1781	L/R DOOR	41 00 7 327 449	Original	Ry	1,250.00 ✓
1787	L/R UPPER DOOR HINGE	41 52 7 284 545	Original	DIS	90.00 X ✓
1795	L/R LOWER DOOR HINGE	41 52 7 284 543	Original	R	90.00 X
1799	L/B-PILLAR SEAL	51 76 4 827 413	Original	Gt	280.00 ✓
1805	L/R DOOR CHECK	51 22 7 322 423	Original	Rn	110.00 X
1817	L/R LWR DOOR SEAL	51 76 7 327 313	Original	Rn	60.00 X
1847	L/R WINDOW REGULATOR	51 35 7 490 207	Original	Rn	350.00 X
1851	L/R WINDOW MOTOR	67 62 7 354 889	Original	Rn	180.00 X
1865	L/R OUTER HANDLE	51 21 7 327 339	Original	R	180.00 X
2011	L/R DOOR TRIM	51 42 7 429 347	Original	Rn	750.00 X
2171	LEFT SILL MOULDING	51 77 7 398 781	Original	CM	380.00 ✓
2193	L/F SILL COVER	51 77 7 374 897	Original	CM	90.90 ✓
2195	L/SILL PANEL COVER	51 77 7 381 033	Original	CM	360.00 ✓
2197	L/R SILL COVER	51 77 7 374 900	Original	Rn	57.25 X
2199	LEFT HOOD TAPE	51 77 7 403 246	Original	NEC	17.80 ✓
2201	LEFT HOOD TAPE	51 77 7 403 247	Original	Rn	13.80 X
3669	L/R W-ARCH COVER FRT	51 77 7 329 031	Original	Gt	140.00 ✓
3671	L/R W-ARCH TRIM REAR	51 77 7 318 829	Original	Gt	190.00 ✓
7081	L/F STEERING KNUCKLE	31 21 6 876 643	Original	Ry	550.00 ✓

Code	Description	Part Number	Part Source	Price SGD
7131	L/F WHEEL HUB	31 20 6 874 443	Original	380.00 <i>380.00 X</i>
7201	L/FR WHEEL	36 11 6 858 900	Original	<i>580.00</i> <i>✓</i>
9181	L/R WHEEL HUB/BRG	33 41 6 867 927	Original	<i>380.00</i> <i>✓</i>
9321	L/R CONTROL ARM	33 30 8 842 877	Original	<i>650.00</i> <i>✓</i>
9551	L/RR WHEEL	36 11 6 858 900	Original	<i>580.00</i> <i>✓</i>

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	12,559.75
Fixed Sundry Parts Price	100.00
Total	12,659.75

Extras

Code	Description	Price SGD
1000	ECU diagnostic ECU diagnostic	<i>150.00*</i> <i>X</i>
1001	Electrical work Electrical work	<i>25.00*</i> <i>201</i>
1002	Wheel alignment Wheel alignment	<i>60.00*</i> <i>✓</i>
1003	LH REAR TYRE TYRE	<i>250.00*</i> <i>X</i>
Total Extras		485.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	12,559.75	
Total Parts	100.00	12,659.75
Labour Time Base 12 WU/h		
Total 151.0 WU X 42.00 SGD/h	528.50	
Alignment		
Measuring Work	56.00	
Total of Labour		584.50
Total Of Extras		485.00
Paint Work Time Base 10 WU/h		
Labour Cost 83.0 WU X 42.00 SGD/h	348.60	
Material Cost	149.96	
Total Paint Including Material		498.56
Repair Cost Excludes GST		14,227.81
GST (+7.0%)		995.95
Repair Cost Included GST		15,223.76

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The Motor Claims Department
M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

File No : SH/2022/334/12/018/OD
Date : 04-January-2023

Estimated cost of repair for vehicle no : SNA3717A Mini Cooper S
Policy no: DMPCSNW00265742100 Accident Date: 13.12.2022

Description	Quantity	Cost Price
-------------	----------	------------

Rear left wheel lower arm bolt

\$ *Rs* 30.00 ✓

Labour charge for repair left side panel - ⁶⁰~~80~~ WU

55.80/-

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 055887
Date calculated: 18/01/2023 2:16 PM

Full Report
Registration: SNA3717A
Printed: 18/01/2023 2:16 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	13/12/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: MINI
Model: MINI F55
Sub Model: COOPER S
Model Sheet Number: 19 32 03
Registration: SNA3717A
VIN number: WMWXS720602E46740
Odometer:

Model Specs

FROM 01.2017	CHROMLINE INTERIOR	AUTO AIR CON	WINDSCREEN RAIN SENS
REARVIEW CAMERA	REFRIGERANT R-1234YF	COMFORT ACCESS SYST	TELESERVICE
ELEC/HEATED D/MIRROR	RADIO VISUAL BOOST	DAB TUNER	LED HEADLAMP
INDICATORS WHITE	LED FOG LAMPS	HEIGHT ADJ PASS SEAT	SEAT CVR LEATH CROSS
HEATED FRONT SEATS	SPORT SEATS	JCW EXTERIOR	FRT FOLDING ARMREST
PEDESTRIAN PROTECT	MINI EXCITEMENT PACK	ANTI-THEFT ALARM	INTERIOR LAMP PACK
ON-BOARD COMPUTER	MINI DRIVING MODES	STORAGE PACKAGE	HEAD-UP DISPLAY
RR PARK DIST CONTROL	1998CCM 141KW	LEATHER STRG WHEEL	MULTI FUNC S-WHEEL
SPEED CRUISE ONTROL	O2 VOLUME	TYRES 205/40 WR 18	6-SPEED AUTO GEARBOX
TYRE W/FLAT RUNNING	WHEELS 7J X 18 ALLOY	JCW AERODYNAMIC KIT	WHEEL BOLT LOCK
EDC DAMPER CONTROL	TYRE PRESSURE SENSOR	ROOF/MIRROR BLACK	CTR BONNET STRIP BLK
REAR SPOILER	TWO COAT METALLIC	PREPARE OFF VEHICLE	

Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		2.0	7.00
32 00 590	ELECTRONIC TRACK AND WHEEL ALIGNMENT (WITHOUT: ADJUSTMENT)		16.0	56.00
51 11 656	R + R FRONT BUMPER		6.0	21.00
NO NUMBER	R + R LEFT FRONT SPOILER		3.0	10.50
51 71 947	R + R LEFT SILL RAIL		6.0	21.00
51 13 602	R + R L/F WHEELARCH TRIM		2.0	7.00
41 51 580	R + R LEFT FRONT DOOR		5.0	17.50
41 52 580	R + R LEFT REAR DOOR		3.0	10.50

Code	Description	WU	Price SGD
41 51 501	RENEW L/F DOOR (REMOVED)	26.0	91.00
41 52 501	RENEW L/R DOOR (REMOVED)	22.0	77.00
NO NUMBER	RENEW L/R LOWER DOOR HINGE	14.0	49.00
51 13 605	R + R L/R WHEELARCH TRIM	2.0	7.00
36 10 800)	R + R LEFT FRONT WHEEL	1.0	3.50
34 11 519)	R + R L/F BRAKE CALIPER (WHEEL REMOVED)	1.0	3.50
31 21 580)	R + R L/F WHEEL HUB (FRONT WHEEL REMOVED)	4.0	14.00
31 21 504)	R + R L/F STEERING KNUCKLE	4.0	14.00
36 10 800)	R + R LEFT REAR WHEEL	1.0	3.50
33 53 565)	R + R LEFT REAR COIL SPRING	3.0	10.50
34 21 750)	R + R L/R BRAKE CALIPER	1.0	3.50
33 32 501)	R + R L/REAR TRAILING LINK	5.0	17.50
33 32 621	RENEW L/R TRAILING ARM (REMOVED) INCLUDES: BEARING BRKT AND WHEEL BEARING REMOVE AND REFIT	6.0	21.00
36 11 512	R + R L/F WHEEL/TYRE	6.0	21.00
36 11 512	R + R L/R WHEEL/TYRE	6.0	21.00
41 51 504	ADJUST L/F DOOR	2.0	7.00
41 52 504	ADJUST L/R DOOR	2.0	7.00
0741	L/F WING REPAIR	20.0*	70.00
2173	L/SIDE MEMBER REINF REPAIR	60.0*	210.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	17.80	213.0	745.50
Alignment			
Measuring Work	1.30	16.0	56.00
Total of Labour			801.50

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	LEFT FRONT DOOR NEW PART PAINTING	15.0	
	L/R DOOR NEW PART PAINTING	13.0	
	L/DOOR MIRROR COVER NEW PART PAINT K1R	4.0	
	LEFT SILL MOULDING NEW PART PAINT K1G	9.0	
	L/F WING REPAIR PAINTING <50%	9.0	

Paint Material Per Part

Code	Description	Price SGD
1481	LEFT FRONT DOOR NEW PART PAINTING	40.76
1781	L/R DOOR NEW PART PAINTING	30.44
1745	L/DOOR MIRROR COVER NEW PART PAINT K1R	5.90
2171	LEFT SILL MOULDING NEW PART PAINT K1G	18.14
0741	L/F WING REPAIR PAINTING <50%	8.40

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			50.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.80	8.0	33.60
Total	10 WU/h	8.30	83.0	348.60
Total	12 WU/h	8.30	99.6	348.60

Material Cost - Paint

	Price SGD
New Part Painting	71.20
New Part Painting - Plastic K1R	5.90
New Part Painting - Plastic K1G	18.14
Repair Painting	8.40
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	144.94

Spare Parts

				prices as at 2022-12-15
Code	Description	Part Number	Part Source	Price SGD
0391	L/F SPOILER	51 11 7 360 743	Original	110.00
0787	L/F WHEELARCH TRIM	51 77 7 376 011	Original	220.00
1481	LEFT FRONT DOOR	41 00 7 327 445	Original	1,250.00
1513	L/LWR DOOR SEAL	51 76 7 322 508	Original	80.00
1547	L/WINDOW REGULATOR	51 33 7 409 357	Original	380.00
1551	L/F WINDOW MOTOR	67 62 7 405 701	Original	360.00
1577	L/F DOOR LOCK	51 21 7 281 937	Original	350.00
1599	L/A-PILLAR SEAL	51 76 7 322 455	Original	190.00
1745	L/DOOR MIRROR COVER	51 14 2 354 925	Original	130.00
1781	L/R DOOR	41 00 7 327 449	Original	1,250.00
1795	L/R LOWER DOOR HINGE	41 52 7 284 543	Original	90.00
1799	L/B-PILLAR SEAL	51 76 4 827 413	Original	280.00
2171	LEFT SILL MOULDING	51 77 7 398 781	Original	380.00
2193	L/F SILL COVER	51 77 7 374 897		90.90
2195	L/SILL PANEL COVER	51 77 7 381 033	Original	360.00
2197	L/R SILL COVER	51 77 7 374 900	Original	0.00
2199	LEFT HOOD TAPE	51 77 7 403 246		17.80
2201	LEFT HOOD TAPE	51 77 7 403 247	Original	0.00
3669	L/R W-ARCH COVER FRT	51 77 7 329 031	Original	140.00
3671	L/R W-ARCH TRIM REAR	51 77 7 318 829	Original	190.00
7081	L/F STEERING KNUCKLE	31 21 6 876 643	Original	550.00
7131	L/F WHEEL HUB	31 20 6 874 443	Original	380.00
7201	L/FR WHEEL	36 11 6 858 900	Original	580.00
9181	L/R WHEEL HUB/BRG	33 41 6 867 927	Original	380.00
9321	L/R CONTROL ARM	33 30 8 842 877	Original	650.00
9551	L/RR WHEEL	36 11 6 858 900	Original	580.00
1003	L/R WHEEL ARM BOLT	LH REAR WHEEL	Supplementary	30.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			9,018.70
u: Used parts	Fixed Sundry Parts Price			100.00
	Total			9,118.70

Extras

Code	Description	Price SGD
1000	ECU diagnostic ECU diagnostic	150.00*
1001	Electrical work Electrical work	20.00*
1002	Wheel alignment Wheel alignment	60.00*
Total Extras		230.00

Final Calculation

	SGD	SGD
Parts	9,018.70	
Fixed Sundry Parts Price	100.00	
Total Parts		9,118.70
Labour Time Base 12 WU/h		
Total 213.0 WU X 42.00 SGD/h	745.50	
Alignment		
Measuring Work	56.00	
Total of Labour		801.50
Total Of Extras		230.00
Paint Work Time Base 10 WU/h		
Labour Cost 83.0 WU X 42.00 SGD/h	348.60	
Material Cost	144.94	
Total Paint Including Material		493.54
Repair Cost Excludes GST		10,643.74
GST (+8.0%)		851.50
Repair Cost Included GST		11,495.24

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

1/2 Lmp @ 8500/h B4 excess

Assessment Note

No assessment notes entered.

R026400
3.1.23 13:26
SNA3717A
160-0702



SNA3717A

MINI : R58 Coupe
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-2°48'	-2°48'	-1°00' 0°00'
3°26'	3°26'	
-0°11'	-0°11'	0°04' 0°08'
13°33'	13°33'	
10°45'	10°45'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°08'	-0°08'	-1°00' 0°00'
3°45'	3°45'	
-0°10'	-0°10'	0°04' 0°08'
10°26'	10°26'	
10°18'	10°18'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-2°39'	-2°40'	-0°20' 0°20'
-0°19'	-0°19'	-0°30' 0°30'
3°07'	3°07'	
-0°20'	-0°20'	0°00' 0°24'

Rear : Left

Actual	Before	Specified Range
-4°02'	-4°02'	-2°10' -1°20'
-0°43'	-0°43'	0°10' 0°14'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°12'	-1°12'	-2°10' -1°20'
0°09'	0°09'	0°10' 0°14'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-2°49'	-2°49'	-0°30' 0°30'
-0°34'	-0°34'	0°12' 0°36'
-0°26'	-0°26'	-0°12' 0°12'

6399

1.23 13:14

3717A

0-0702



SNA3717A

MINI : R58 Coupe (2011 - 2015) : Series/Sport Suspension/JCW Series : with 18" Wheel
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°31'	-0°39'	-1°00' 0°00'
3°33'	3°33'	
0°02'	0°00'	0°04' 0°08'
11°19'	11°27'	
10°48'	10°48'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°07'	-0°02'	-1°00' 0°00'
3°52'	3°52'	
0°02'	-0°03'	0°04' 0°08'
10°24'	10°19'	
10°17'	10°17'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°24'	-0°38'	-0°20' 0°20'
-0°20'	-0°20'	-0°30' 0°30'
0°54'	1°08'	
0°04'	-0°03'	0°00' 0°24'

Rear : Left

Actual	Before	Specified Range
-1°17'	-3°02'	-2°10' -1°20'
0°09'	0°01'	0°10' 0°14'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°15'	-1°05'	-2°10' -1°20'
0°11'	0°03'	0°10' 0°14'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°02'	-1°56'	-0°30' 0°30'
0°20'	0°04'	0°12' 0°36'
-0°01'	-0°01'	-0°12' 0°12'

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	193F
Vehicle Details	
Vehicle No.:	SNA3717A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Dec 2022
Vehicle Make:	MINI
Vehicle Model:	COOPER S 2.0 MT FWD 3DR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	G227H465B48A20A
Chassis No.:	WMWXS720602E46740
Maximum Power Output:	141.0 kW (189 bhp)
Open Market Value:	\$37,005.00
Original Registration Date:	21 Jul 2017
First Registration Date:	21 Jul 2017
Transfer Count:	1
Actual ARF Paid:	\$38,807.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2027
PARF Rebate Amount:	\$27,164.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$24,851.00
Total Rebate Amount:	\$52,015.00

The information contained herein is correct as at 13 Dec 2022

OK