

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 28 Feb 2023

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SLK9140U | Accident Date | : 19/12/2022 |
| TP Vehicle No | : SMC4187Z | Assignment Date | : 22/12/2022 |
| Make | : NISSAN TEANA | Est. Duration of Repair | : 4 |
| Date of Inspection | : 23/12/2022 | | |
| Inspection At | : DICKSON AUTO CARE CENTRE PTE LTD (HQ) 29 UBI ROAD 4, DICKSON AUTO CENTRE SINGAPORE 408619 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 7,007.41 |
| Revised Amount | :S\$ | 2,384.45 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 2,384.45 |
| Lump Sum Repair | :S\$ | 1,900.00 |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.