

ASS. REC. BY:

REF:

A15/ 22012795/Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2-3 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PME 23435

Yr Regn:

09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Golf 1984

Colour:

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

59044

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WUW 777 AU 23W 286465

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / R/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

27/11/22

Rear

R/Bal.

7

mm

L/Bal.

7

mm

D.O.I.

23/12/2022

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Fnt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/12/21 @ 2750L Contd

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

Allianz Insurance Co of S'pore Pte Ltd
3 Temasek Ave
#09-01 Centennial Tower
Singapore 039190
ATTN: MOTOR CLAIM DEPARTMENT

Not Authorised
Penalty B4 per
11 Rmp @ 2750h
2 days

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SME2343S

MODEL : GTI GOLD 2.0

POLICY NO :

CHASSIS NO : WVVZZZAUZJW286465

YEAR OF MANUFACTURE : 2018

DATE / TIME OF ACCIDENT: 27/11/2022 Time: 1520Hrs AT Nex Mall 1A Carpark

THIRD PARTY VEHICLE NO: SNC9832A

Date: 21/12/2022

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Heaadlamp LH 2087.95	1	\$ 2,625.00	CM	\$ 2,625.00 ✓
2 Front Grille	1	\$ 512.50	Bu	\$ 512.50 X
3 Head Light Retainers LH	1	\$ 35.00	Bu	\$ 35.00 X
4 Front Bumper 1145.30	1	\$ 1,300.00	Bu	\$ 1,300.00 ✓
5 Front Bumper Retainers	1	\$ 18.00	Bu	\$ 18.00 X
6 Front Fender LH	1	\$ 675.00	R	\$ 675.00 X
7 VW EMBLEM	1	\$ 140.00	R	\$ 140.00 X
8 Fog Light LH	1	\$ 1,250.00	Bu	\$ 1,250.00 X
9 Front Bumper Bottom Lid RH	1	\$ 262.50	Bu	\$ 262.50 X
10 Front Lower Grille	1	\$ 200.00	Bu	\$ 200.00 X
11 Bonnet	1	\$ 1,625.00	R	\$ 1,625.00 X
12 Bonnet Lock	1	\$ 280.00	R	\$ 280.00 X
13 Number plate holder	1	\$ 157.00	Bu	\$ 157.00 X
14 Front Reinforcement bar	1	\$ 662.50	R	\$ 662.50 X
15 Condenser	1	\$ 625.00	Bu	\$ 625.00 X
16 Radiator	1	\$ 675.00	Bu	\$ 675.00 X
17 Front bumper Sensor	4	\$ 280.00	Bu	\$ 1,120.00 X

Sub-Total: 12,162.50

Less: 10% discount - 1,216.25

Total Parts after 20% discount: 10,946.25

Special Nett Items

1	Anti-rust coating	3	80.00	nn	240.00	X
2	Front Number plate with casing	1	100.00	nn	100.00	X
3	Coolent	1	100.00	nn	100.00	X
					440.00	

Total Parts: 11,386.25

Labour Charges For Front Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	2,000.00	2201
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	2,000.00	2501
3	Provide skill labour to disconnect and check electrical wiring	150.00	201
4	Reset engine mangement system with diagnostic fault	nn	400.00
5	Remove and replace of aircon condenser,pipe and radiator	nn	150.00
6	vaccum air-con system and refill gas	150.00	X
	Remove and replace bumper sensor	150.00	501

Total Labour:

4,850.00

Total Parts & Labour: 16,236.25

GST 7% 1,136.54

Grand Total: 17,372.79

Estimate Repair Duration

15 days

2-3 days

ACCIDENT VEHICLE OF : SME2343S

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: NINJA LO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: