

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

*Not Authorised
Runny B4pain*

Allianz Insurance Co of S'pore Pte Ltd
3 Temasek Ave
#09-01 Centennial Tower
Singapore 039190
ATTN: MOTOR CLAIM DEPARTMENT

DEAR SIR / MADAM :

Date: 21/12/2022

Page : 1 of 2

ACCIDENT REPAIR ON: SME2343S

MODEL : GTI GOLD 2.0

POLICY NO :

CHASSIS NO : WVWZZZAUZJW286465

YEAR OF MANUFACTURE : 2018

DATE / TIME OF ACCIDENT: 27/11/2022 Time: 1520Hrs AT Nex Mall 1A Carpark

THIRD PARTY VEHICLE NO: SNC9832A

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price S\$	Condition	Amount S\$
S/N					
1	Heaadlamp LH	1	\$ 2,625.00		\$ 2,625.00 7
2	Front Grille	1	\$ 512.50		\$ 512.50 X
3	Head Light Retainers LH	1	\$ 35.00		\$ 35.00 X
4	Front Bumper	1	\$ 1,300.00		\$ 1,300.00 ✓
5	Front Bumper Retainers	1	\$ 18.00		\$ 18.00 X
6	Front Fender LH	1	\$ 675.00		\$ 675.00 X
7	VW EMBLEM	1	\$ 140.00		\$ 140.00 X
8	Fog Light LH	1	\$ 1,250.00		\$ 1,250.00 X
9	Front Bumper Bottom Lid RH	1	\$ 262.50		\$ 262.50 X
10	Front Lower Grille	1	\$ 200.00		\$ 200.00 7
11	Bonnet	1	\$ 1,625.00		\$ 1,625.00 X
12	Bonnet Lock	1	\$ 280.00		\$ 280.00 X
13	Number plate holder	1	\$ 157.00		\$ 157.00 X
14	Front Reinforcement bar	1	\$ 662.50		\$ 662.50 7
15	Condenser	1	\$ 625.00		\$ 625.00 X
16	Radiator	1	\$ 675.00		\$ 675.00 X
17	Front bumper Sensor	4	\$ 280.00		\$ 1,120.00 X

Sub-Total: 12,162.50

Less: 10% discount - 1,216.25

Total Parts after 20% discount: 10,946.25

Special Nett Items

1	Anti-rust coating	3	80.00	nn 240.00 X
2	Front Number plate with casing	1	100.00	nn 100.00 X
3	Coolent	1	100.00	nn 100.00 X
				440.00

Total Parts: 11,386.25

Labour Charges For Front Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	2,000.00	2201
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	2,000.00	259
3	Provide skill labour to disconnect and check electrical wiring	150.00	29
4	Reset engine mangement system with diagnostic fault	400.00	?
5	Remove and replace of aircon condenser,pipe and radiator vaccum air-con system and refill gas	nn 150.00	X
6	Remove and replace bumper sensor	150.00	501

Total Labour:

4,850.00

Total Parts & Labour: 16,236.25

GST 7% 1,136.54

Grand Total:

17,372.79

Estimate Repair Duration

15 days

2-3 days

ACCIDENT VEHICLE OF : SME2343S

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: NINJA LO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/11/2022 17:19 (SGT)
Reported by	Both
Date of Accident	27/11/2022 15:20 (SGT)
Exact Location of Accident	23 Serangoon Central, Singapore 556083
Additional Location Information	NEX MALL 1A CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME2343S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WANG SHAO-ING
NRIC No	SXXXX828F
Email Address	SHAOING@GMAIL.COM
Mobile Phone No	(Phone) +65-96629244
Alternative Phone No	-

VEHICLE PARTICULARS


Manufacturer	Volkswagen
Model	Golf
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1999

INSURANCE COMPANY

Name of Insurance Company	Etiqua Insurance Pte Ltd
Policy Number / Cover Note Number	MA022395

DRIVER

Name of Driver	HUAN SZE LYNN, KRYSTLE
NRIC No	SXXXX193B
Date Of Birth	18/12/1990
Occupation	Indoor



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1. This accident happened at Level 1A at NEX mall carpark.
2. As I entered my car to leave, I saw the white car (BMW, SNC 9832A) waiting on the left side of my parking lot.
3. I started the car engine, and waited for 2 cars to pass before leaving my lot.
4. As I drove out of the lot, I saw the white car (SNC 9832A) reverse. I stopped the car and sounded the horn. The white car continued to reverse into my car, and collided into my car.

DECLARATION

We declare the foregoing particulars are true to every respect

Injured Person's Signature
Date & Time

Driver's Signature
If driver is not the principal driver
Date & Time

Reporting Centre Person's Signature
Date
Time