



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22012796/Kvy3m4 Date: 16/01/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4777E	Veh. Inspected	SMK 8120Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/12/22/2048	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	22/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY (A)	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	AXVH701020255	Colour	METALLIC BLACK	
Odometer	80311 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40ZR18	FALKEN	8 mm	
L/H Front Tyre	235/40ZR18	FALKEN	8 mm	
R/H Rear Tyre	235/40ZR18	FALKEN	8 mm	
L/H Rear Tyre	235/40ZR18	FALKEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/12/2022	Inspection Date	22/12/2022	
Survey held at	CAR TIMES AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29/30 BARTLEY BIZ CENTRE SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	