

AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ONG POH PWAY LINA
22 SPRINGLEAF WALK
SPRINGLEAF GARDEN
SINGAPORE 787874

Estimate No: MCS1900789
Date: 15 Dec 2022
Policy No: MT/01060483
Veh Reg No: SJG8766R
Make/Model: HONDA STREAM 1.8L

ATTN:

Your Ref No: SJG8766R
Claim Type: Third Party
Accident Date: 14/12/2022
TP Veh Reg No: SNG6157P


NOT Authorised
11 Pay @
Recovery After Paim
3 days

Estimate Repair Cost to Vehicle No :SJG8766R

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 HEADLAMP LH	1 PC	928.50	✓
2 FRONT BUMPER	1 PC	760.80	✓
3 FRONT BUMPER SIDE RETAINER LH	1 PC	14.90	✓
4 FRONT BUMPER CLIPS	10 PC	35.00	✓
		1,739.20	
	Less 20%	347.84	1,391.36
Special Nett			
5 FRONT ALLOY RIM LH	1 PC	300.00	250.00
		300.00	300.00
LABOUR			
6 TO CHECK WIRING AND REFOCUS HEADLAMP	1 PC	20.00	✓
7 TO WHEEL ALIGNMENT	1 PC	80.00	60.00
8 TO DISMANTLE AND REPLACE DAMAGE PARTS, TO KNOCK, ALIGN AND REPAIR FRONT LH AFFECTED AREA	1 PC	550.00	300.00
9 TO SPRAY FRONT BUMPER AND FRONT FENDER LH	1 PC	550.00	400.00
		1,200.00	1,200.00
Total			S\$ 2,891.36
Add GST @ 7%			202.40
Total Amount Payable			S\$ 3,093.76

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINETY THREE AND CENTS SEVENTY SIX ONLY

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: