



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE		Ref: CC4/ASM22012802/Kpa3q2 Date: 23/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 1282K	Veh. Inspected	SLU 4659X
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04GVY	Excess (\$)	0.00
Assign From		Assign Date	21/12/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA HRV (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRU1830GX203441	Colour	METALLIC GREY
Odometer	110607 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	2 mm
L/H Front Tyre	215/60 R16	DUNLOP	2 mm
R/H Rear Tyre	215/60 R16	DUNLOP	2 mm
L/H Rear Tyre	215/60 R16	DUNLOP	2 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/12/2022	Inspection Date	28/12/2022
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	