

ASS. REC. BY:

REF:

ASM / 22012802/KP

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLU 4859X Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HRV c.c. 1496

Colour:

M. Gray A/C: Insured / Std / NI / NA

Sp. Reading

110607 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRU1830GX 203441

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

2

mm

Rear

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

20/12/22

D.O.I.

28/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/12 813278-07 Calh

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

26/12 - 6pm

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Reg = 1/12/2017

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT22003787	Page	1
	8 SHENTON WAY	Date	: 21. Dec 2022		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: ANIKKA LAI SWEE KAM		
Registration No	: SLU4659X	Engine No	: L15B4533442		
Chassis No	: JHMRU1830GX203441	Date Time	: 21. Dec 2022 1:35:40 PM		
Model	: HRV LX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: ZHANG BINGQI	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 20/12/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: ZHABG BINGQI						
	OWNER INSURER: SOMPO						
	ACC DATE: 20/12/2022						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA						
	TP VEH: SHC1282K						
68100-T7A-J20ZZ	TAIL GATE COMP	1	915.90	25	686.92	48.08	735.00
68210-T5A-J03ZZ	HINGE COMPTAILGATE	2	32.90	25	49.35	3.45	52.80
74440-T7A-003	WEATHERSTRIPTAILGATE	1	105.60	25	79.20	5.54	84.74
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY	1	174.70	25	131.02	9.17	140.19
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	145.60	25	109.20	7.64	116.84
75722-T7W-A01	EMBLEMRR.	1	15.40	25	11.55	0.81	12.36
75725-T8N-T00	EMBLEM, RR. I-VTEC	1	16.70	25	12.52	0.88	13.40
74890-T7A-J12ZC	GARNISH ASSYRR.LICENSE	1	207.20	25	155.40	10.88	166.28
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUT, PUSH 3MM	2	2.10	25	3.15	0.22	3.37
34150-T7A-J01	LIGHT ASSY, R.LID	1	288.90	25	216.67	15.17	231.84
34155-T7A-J01	LIGHT ASSYL.LID	1	288.90	25	216.67	15.17	231.84
33502-T7A-J01	LAMP UNITR.	1	509.60	25	382.20	26.75	408.95
33552-T7A-J01	LAMP UNITL.	1	509.60	25	382.20	26.75	408.95
74940-TZ5-A01	BUZZER ASSYSMART	1	64.70	25	48.52	3.40	51.92
38387-TZ5-A01	ANTENNA ASSYL.F.	1	63.50	25	47.62	3.33	50.95
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
04715-T7A-900ZZ	FACE, RR.BUMPER	1	484.70	25	363.52	25.45	388.97
04717-T7A-000ZZ	FACER, RR.BUMPER CORNER	1	103.80	25	77.85	5.45	83.30

Printed on 21/12/2022 2:01:19 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU4659X
Chassis No : JHMRU1830GX203441
Model : HRV LX-SIN CVT YM 2016
Owner's Name : ZHANG BINGQI
Ins Policy No. :
Date of Accident : 20/12/2022

Document No. : SQT22003787 **Page** 2
Date : 21. Dec 2022
Customer No. : WZA006
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B4533442
Date | Time : 21. Dec 2022 1:35:40 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST	
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	103.80	25	77.85	5.45	83.30	X
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	18.10	25	13.57	0.95	14.52	X
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	18.10	25	13.57	0.95	14.52	X
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46	✓
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	47.00	25	35.25	2.47	37.72	X
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR	1	203.10	25	152.32	10.66	162.98	X
84550-T7A-J00	BOX ASSY,CARGO FLOOR	1	142.70	25	107.02	7.49	114.51	✓
66100-T7A-300ZZ	PANEL COMPRR.	1	399.40	25	299.55	20.97	320.52	✓
63320-T7A-300ZZ	GUTTER COMPR.RR.	1	82.20	25	61.65	4.32	65.97	X
63720-T7A-300ZZ	GUTTER COMPL.RR.	1	82.20	25	61.65	4.32	65.97	X
65513-T7A-300ZZ	STIFFENERRR.JACK UP	1	65.70	25	49.27	3.45	52.72	X
04655-T7A-310ZZ	PANEL SET,RR.FLOOR	1	723.00	25	542.25	37.96	580.21	✓
18307-T7A-901	SILENCER COMPEXHUAST	1	507.30	25	380.47	26.63	407.10	✓
18215-TF0-003	RUBBEREX MOUNTING	1	8.00	25	6.00	0.42	6.42	✓
18215-TF0-911	RUBBEREX MOUNTING	1	6.00	25	4.50	0.32	4.82	✓
74605-T7A-000	PLATESILENCER BAFFLE	1	29.30	25	21.97	1.54	23.51	✓
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48	✓
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.48	7.30	✓
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48	✓
76711-T6A-003	CAPPIVOT	1	5.20	25	3.90	0.27	4.17	✓
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01	✓
91502-S70-003	FASTENER B	2	5.40	25	8.10	0.57	8.67	✓
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10	✓
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40	✓
Sum Item					5335.08	373.46	5,708.54	
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50	✓
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00	30.00

Printed on 21/12/2022 2:01:19 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

For 24-hours Roadside Assistance, Call 98203838

Website: www.honda.com.sg

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLU4659X
Chassis No : JHMRU1830GX203441
Model : HRV LX-SIN CVT YM 2016
Owner's Name : ZHANG BINGQI
Ins Policy No. :
Date of Accident : 20/12/2022

Document No. : SQT22003787 **Page** 3
Date : 21. Dec 2022
Customer No. : WZA006
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B4533442
Date | Time : 21. Dec 2022 1:35:40 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	150/	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	150/	180.00	12.60	192.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	325/	650.00	45.50	695.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	325/	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	325/	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00	325/	450.00	31.50	481.50
BMU30R	REMOVE & REPLACE EXHAUST SYSTEM.(N)	1	650.00	325/	650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00	80/	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00	80/	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	100.00	80/	100.00	7.00	107.00
BKRP02B	CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG	1	5000.00	3900/	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00	3120/	4000.00	280.00	4280.00
Sum Labor					13060.00	914.20	13,974.20

Survey By Kennerly
Date & Time 28/12/22
Excess _____
Status _____
Signature _____

Total Amount 18,395.08 1,287.66 19,682.74

Total (Inclusive of GST) 19,682.74

Not Authorised
Recovery B4 paint
9 days

Printed on 21/12/2022 2:01:19 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No: M200050223
Company Ref. No: S60FC1380G

Customer: CU0069601 / AXA INSURANCE
Chassis No: JHMRU1830GX203441
License No: SLU4659X
Mileage: 110607
Engine No: L15B4533442

Document No: SVO22057700
Printed By: ANIKKALAI
Order Date: 28. December 2022
Order Time: 2:36:03 PM
Service Advisor: ANIKKA LAI SWEE KAM

Supp

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ZHABG BINGQI OWNER INSURER: SOMPO ACC DATE: 20/12/2022 SURVEYED BY: KENNETH / LKK DATE: 28/12/2022 REF NO: CC4/ASM22012802/pa3 TP INSURER: AXA TP VEH: SHC1282K SUPPLEMENTARY PART							
65770-T7J-H00ZZ	CROSSMEMBER COMPRR.FLOOR RR. BT.	1	158.00	25	118.50	8.30	126.80	
91513-T6A-003	CLIPTAILGATE SPOILER Nec	9	2.60	25	17.55	1.23	18.78	
74646-T7A-010	COVERR R.FLOOR UN Dd.	1	129.20	25	96.90	6.78	103.68	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: